




Consultancy Services for
Tender Preparation and Construction Supervision Consultant for
Shelters
Lebanon Emergency Assistance Project (LEAP)

**ASSESSMENT REPORT
BATCH 2 - LOT 2**

July 2026



BATCH 2 - LOT 2
TRIPOLI & NORTH LEBANON SCHOOLS
GENERAL INDEX

No.	SCHOOL NAME	
1	356	AL Fadila girls (الفضيلة الرسمية للبنات)
2	376	AL Zahrieh Boys (الزاهرية الرسمية للبنين)
3	393	Al Nahda Mina (النهضة الرسمية للصبيان)
4	395	Boutros Dawrah (بطرس دوره للبنين)
5	400	Abi Samra first 4 girls (أبي سمراء الأولى للبنات)
6	407	AL Tadrib (التدريب التربوي الرسمية للبنات)
7	408	Ibn Khaldoun (ابن خلدون الرسمي المختلطة)
8	409	Souad Al Masri girls (المربية سعاد المصري للبنات الرسمية طرابلس)
9	429	Al Farabi boys (الفارابي الرسمية للصبيان)
10	448	Georges Sarraf (ثانوية جورج صراف الرسمية)
11	697	Dahr El Ein mixed (ضهر العين الرسمية المختلطة)
12	704	Gibran Makari Anfeh (جبران مكاري الرسمية)
13	725	Kfar Aaqqa mixed (مدرسة كفر عاقا الأولى المختلطة الرسمية)
14	730	Kfar Hata (ثانوية كفر حاتا الرسمية)
15	748	Chekka (مدرسة شكا المتوسطة الرسمية)
16	752	AL Heri (الهرية المختلطة الرسمية)
17	755	Al Batroun for girls (البترون الرسمية للبنات)
18	756	Estephan Attieh (مدرسة اسطفان عطية المتوسطة الرسمية المختلطة)
19	763	Aabrine mixed (عبرين الرسمية المختلطة)
20	764	Aabrine high school (ثانوية عبرين الرسمية)
21	1377	AL Qobbeh second (ثانوية طرابلس القبة المختلطة الثانية الرسمية)
22	1403	Wadi AL Nahleh mixed (وادي النحلة الرسمية المختلطة)
23	1521	Al Beddaoui girls (متوسطة البداوي الثانية الرسمية للبنات)
24	1606	Ibn Khaldoun girls (مدرسة ابن خلدون الرسمية للبنات)
25	1636	Al Beddaoui high school (ثانوية البداوي الرسمية للبنات)

ASSESSMENT REPORT

STAGE A1


AL Fadila Public School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	AL Fadila Public School				Date of visit :		08/07/2026	
school Location	Village	Tripoli	Caza	Denniyeh	coordinations	34.4233491 35.8343349		
School Principale name :	Fidaa Tabikh			Phone No :	03 508137			
General Information :								
No of Class Room :	16	No Of Other Rooms:	10	No of Female Toilets	2			
				No of Male Toilets	16			
No of Blocks(Buildings)	1							
No of Floors	five floors (basment + GF + first + second + third floor)							
Estimate Total Built Area m2	1880 m2							
No of Students :	626							
Location of shelter within the building :			second and third floor					
Handicap Facilities								
handicap ramp :	available		location		not available	x	space availability	yes
Handicap toilet :	available		location		not available	x	space availability	yes
visual structural condition								
Façade cracks	no				Location :			
Façade water leak	no				Location :			
wall Cracks	no				Location :			
Columns cracks	no				Location :			
Beams cracks	no				Location :			
Roof slab cracks	no				Location :			
Ground slab					Location :			
Repair assessment	Category 1	x	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					
Note:								

Environment

Quality of water	Good
toilets capacity and quality	nb of toilets is acceptable
drinking capacity	enough for students
pollution	yes
play ground	available
kids play ground	available
humidity	present in the school from windows and roof floor
ventilation	good
Gender separation in sanitation	no
mobility to disabled	yes
Env.health condition within school	some wc are leaking to the floors below
waste disposal	

Damages from shelters

The shelters have minor damage to the paint, the wooden doors, and the bathrooms.

Safety

stairs size	140
windows at G.F with defence	yes.
protection of electrical works	yes.
Handrails	yes.
fire extinguishers / Alarms/ smoke detectors	yes.
Directional signs	yes.

Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:



General view to school



General view to school




pic showing the leakage from
the upper windows



Pic showing the bad condition of handles



pic showing the bad condition of the locks



Pic showing the bad condition of wall painting

ASSESSMENT REPORT

STAGE A1

AL Zahriyeh public school for boys

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	AL Zahriyeh public school for boys					Date of visit :		16/7/2026	
school Location	Village	Al Zahriyeh	Caza	Tripoli	coordinations	34.442853 35.843646			
School Principale name :	Marya Zakariya			Phone No :	71 625373				
General Information :									
No of Class Room :	24	No Of Other Rooms:	5	No of Female Toilets	0				
				No of Male Toilets	12				
No of Blocks(Buildings)	1								
No of Floors	5 floors (2 basements +ground floor+1st floor +2nd floor)								
Estimate Total Built Area m2	900 m2								
No of Students :	266								
Location of shelter within the building :	1st and 2nd								
Handicap Facilities									
handicap ramp :	available		location		not available	x	space availability	Yes	
Handicap toilet :	available		location		not available	x	space availability	Yes	
visual structural condition									
Façade cracks	yes				Location :	3rd			
Façade water leak	yes				Location :	all			
wall Cracks	yes				Location :	1st - 2nd			
Columns cracks	yes				Location :				
Beams cracks	no				Location :				
Roof slab cracks	yes				Location :				
Ground slab					Location :				
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs						
	Category 2		need comprehensive rehabilitation including structural						

Enviroment

Quality of water	drinkable
toilets capacity and quality	nb of toilets is enough fro students and it's newly rehabilitated
drinking capacity	enough for students
polution	there's pollution
play ground	available
kids play ground	not available
humidity	present in some areas at the ground floor
ventilation	good
Gender separation in sanitation	
mobility to disabled	no
Env.health condition within school	Good
waste disposal	available thru Municipalty

Damages from shelters

paint
 wood Doors
 doors accessories
 Door paint
 Elec sockets
 lighting fixtures
 Broken solar panel
 water closets
 floor Tiles

Safety

stairs size	120
windows at G.F with defence	no
protection of electrical works	no
Handrails	yes
fire extinguishers / Alarms/ smoke detectors	fire extinguishers are present at different locations
Directional signs	available

Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

SITE PHOTOS:



outside overview



Playground view




Electrical lamp to be changed



Façade cracks



corrosion of the entrance door



Electrical problem to maintain



wooden door damages



WC need to be rehabilitated



Humidity



pic showing cracks in walls



pic showing the glass to be
changed



damage in the parapette

ASSESSMENT REPORT

STAGE A1

393- Al Nahda Public School for Boys

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	393-Al Nahda Mixed Public School				Date of visit :		07/07/2026	
school Location	Village	Mina	Caza	Tripoli	coordinations	34.448540 35.812497		
School Principale name :	Sahar Mostafa			Phone No :	3541922			
General Information :								
No of Class Room :	33	No Of Other Rooms:		20	No of Female Toilets		9	
					No of Male Toilets		12	
No of Blocks(Buildings)	1							
No of Floors	07 floors (2 basements+ground+ first + second+ third+ fourth floors)							
Estimate Total Built Area m2	6200 m2							
No of Students :	721							
Location of shelter within the building :			all the school except the administration offices and service rooms					
Handicap Facilities								
handicap ramp :	available	X	location	GF	not available		space availability	
Handicap toilet :	available	X	location	GF	not available		space availability	
visual structural condition								
Façade cracks	no				Location :			
Façade water leak	yes				Location :	around windows		
wall Cracks	no				Location :			
Columns cracks	no				Location :			
Beams cracks	no				Location :			
Roof slab cracks	no				Location :			
Ground slab	no				Location :			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					

Environment			
Quality of water	Good and drinkable		
toilets capacity and quality	nb of toilets is acceptable		
drinking capacity	enough for students		
pollution	yes because of the waste containers located in front of main entrance school		
play ground	available		
kids play ground	available		
humidity	present in the school from windows and roof floor		
ventilation	good		
Gender separation in sanitation	yes		
mobility to disabled	yes		
Env.health condition within school	some wc are leaking to the floors below		
waste disposal	available thru Municipality		
Damages from shelters			
paint wood Doors doors accessories Door paint Elec sockets lighting fixtures water closets floor Tiles			
Safety			
stairs size	Safe		
windows at G.F with defence	yes.		
protection of electrical works	yes.		
Handrails	yes.		
fire extinguishers / Alarms/ smoke detectors	fire extinguishers are present at different locations		
Directional signs	No		
Expected risks in repair works			
Access to school	Accessible		
permits			
schedule by contractor & Resources			
Labor working conditions	good		
repair with occupants inside			

Site Photos:



General View to school



General View to school



Drinking Basin inside playground



Pic showing the water leak inside the corridor



pic showing the Broken
Aluminum window



Broken wooden door need to be
repaired



Wc doors partition




Waste containers in front of
school's main entrance




Humidity under drinking basin



Humidity and water leak from the
roof and elevations shown inside
the building



Electrical socket to be repaired



Drainage leak pipes from floor to
floor at WC area

ASSESSMENT REPORT

STAGE A1

395-Boutros Dawrah Public School for Boys

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	395-Boutros Dawrah Public School for Boys				Date of visit :		07/07/2026	
school Location	Village	Mina	Caza	Tripoli	coordinations	34.447811 35.814977		
School Principale name :	Samer Moubayed			Phone No :	81748224			
General Information :								
No of Class Room :	21	No Of Other Rooms:	7	No of Female Toilets	0			
				No of Male Toilets	15			
No of Blocks(Buildings)	1							
No of Floors	02 floors (ground+ first floors)							
Estimate Total Built Area m2	1700 m2							
No of Students :	280							
Location of shelter within the building :	all the school except the administration offices							
Handicap Facilities								
handicap ramp :	available		location		not available	X	space availability	No
Handicap toilet :	available		location		not available	X	space availability	No
visual structural condition								
Façade cracks	no				Location :			
Façade water leak	minor around some windows				Location :			
wall Cracks	yes				Location :	external fence		
Columns cracks	no				Location :			
Beams cracks	no				Location :			
Roof slab cracks	no				Location :			
Ground slab	no				Location :			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					

Environment



Quality of water	Good and drinkable
toilets capacity and quality	nb of toilets is enough fro students and it's newly rehabilitated
drinking capacity	enough for students
pollution	yes because of the wate containers located in front of main entrance school
play ground	available
kids play ground	available
humidity	present in some areas at first floor between rooms
ventilation	good
Gender separation in sanitation	yes
mobility to disabled	no
Env.health condition within school	Good
waste disposal	available thru Municipalty

Damages from shelters

paint
wood Doors
doors accessories
Door paint
Elec sockets
lighting fixtures
Broken solar panel
water closets
floor Tiles

Safety

stairs size	
windows at G.F with defence	yes.
protection of electrical works	yes.
Handrails	yes.
fire extinguishers / Alarms/ smoke detectors	fire extinguishers are present at different locations
Directional signs	yes.

Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	


SITE PHOTOS:



Pic showing the broken tiles at entrance and which need to be replaces



View from inside the school



Lever handle and lock to door to be replaced and door to be painted



Fence needs to be rehabilitated



pic showing the humidity inside
the wall



Broken solar panel



Fence needs to be rehabilitated
(pic from inside the room)



Storm water pipes causing leak
inside the building


ASSESSMENT REPORT

STAGE A1

400- Abi Samra First School for Girls

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	400- Abi Samra First School for Girls				Date of visit :		07/11/2026	
school Location	Village	Abi Samra	Caza	tripoli	coordinations	34.4158881, 35.8355204		
School Principale name :	Asma Mlek Darwish			Phone No :	71499845			
General Information :								
No of Class Room :	7	No Of Other Rooms:	2	No of Female Toilets	17	Staff	1	
				No of Male Toilets	0 kindergarden			0
No of Blocks(Buildings)	1							
No of Floors	4floor (ground+second) first and third are different schools and facilities							
Estimate Total Built Area m2	1320 m2 only the used area							
No of Students :	357							
Location of shelter within the building :			all the school except the administration offices and service rooms					
Handicap Facilities								
handicap ramp :	available		location	GF	not available	x	space availability	no
Handicap toilet :	available		location	GF	not available	x	space availability	no
visual structural condition								
Façade cracks	no				Location :			
Façade water leak	yes				Location :	around windows		
wall Cracks	yes				Location :	corridor		
Columns cracks	no				Location :			
Beams cracks	no				Location :			
Roof slab cracks	no				Location :			
Ground slab	no				Location :			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					

Environment			
Quality of water	Good and drinkable		
toilets capacity and quality	nb of toilets is acceptable but not working		
drinking capacity	enough for students		
pollution	no		
play ground	available		
kids play ground	available		
humidity	present in the school from windows and roof floor		
ventilation	good		
Gender separation in sanitation	yes		
mobility to disabled	yes		
Env.health condition within school	some wc are leaking to the floors below		
waste disposal	available thru Municipality		
Damages from shelters			
paint wood Doors doors accessories Door paint Elec sockets lighting fixtures water closets floor Tiles electricity problem			
Safety			
stairs size		yes.	
windows at G.F with defence		yes.	
protection of electrical works		not safe	
Handrails		yes.	
fire extinguishers / Alarms/ smoke detectors		no	
Directional signs		No	
Expected risks in repair works			
Access to school		Accessible	
permits			
schedule by contractor & Resources			
Labor working conditions		good	
repair with occupants inside			

Site Photos:



General View to school



General View to school



Drinking Basin inside playground



Electrical socket to be repaired



Broken wooden door need to be repaired



Broken wooden door need to be repaired



status of the washing basin



tiles need repair and its slippery



w.c status



Humidity and water leak from
elevations shown inside the
building



crackst to be repaired



roof status


ASSESSMENT REPORT

STAGE A1

407 - Al Tadrib public school for girls

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	407 - Al Tadrib public school for girls					Date of visit :	16/7/2026		
school Location	Village	Abi Samra	Caza	Tripoli	coordinations	34.4261305 35.8460588			
School Principale name :	Sohaila kayal			Phone No :	3365705				
General Information :									
No of Class Room :	28	No Of Other Rooms:	4	No of Female Toilets	16				
				No of Male Toilets	3				
No of Blocks(Buildings)	1								
No of Floors	ground floor+1st floor +2nd floor								
Estimate Total Built Area m2	1700 m2								
No of Students :	664								
Location of shelter within the building :	all the school except the administration offices								
Handicap Facilities									
handicap ramp :	available	NO	location		not available		space availability	yes	
Handicap toilet :	available	NO	location		not available		space availability	No	
visual structural condition									
Façade cracks	no				Location :				
Façade water leak	yes				Location :	first floor			
wall Cracks	yes				Location :	ground floor			
Columns cracks	yes				Location :	first floor			
Beams cracks	no				Location :				
Roof slab cracks	no				Location :				
Ground slab	yes				Location :	ground+1st floor			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs						
	Category 2		need comprehensive rehabilitation including structural						

Environment

Quality of water	drinkable
toilets capacity and quality	nb of toilets is enough fro students and it's newly rehabilitated
drinking capacity	enough for students
polution	there's pollution
play ground	available
kids play ground	not available
humidity	present in some areas at the ground floor
ventilation	good
Gender separation in sanitation	
mobility to disabled	no
Env.health condition within school	Good
waste disposal	available through Municipalty

Damages from sheters

paint
 wood Doors
 doors accessories
 Door paint
 Elec sockets
 lighting fixtures
 Broken solar panel
 water closets
 floor Tiles

Safety

stairs size	130
windows at G.F with defence	no
protection of electrical works	no
Handrails	yes
fire extinguishers / Alarms/ smoke detectors	fire extinguishers are present at different locations
Directional signs	available


Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants43 inside	


SITE PHOTOS:



Pic showing crack in the column



View from inside the school



Lever handle and lock to door to be replaced and door to be painted



damage in doors needs t be fixed




pic showing the humidity in the ceiling



exposed electrical works



pic showing crack in the ground



damage in the ceiling



damage in the playground floor



floor settlement



roof need to be waterproofed



window's handle need to be fixed

ASSESSMENT REPORT

STAGE A1

408 -Ibn khaldoun public school for boys

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	1606 -Ibn khaldoun public school for girls				Date of visit :		16/7/2026	
school Location	Village	Abi samra	Caza	Tripoli	coordinations	34.4137493 35.8494941		
School Principale name :	Ahlam helwani			Phone No :	70492978			
General Information :								
No of Class Room :	18	No Of Other Rooms:	7	No of Female Toilets	10			
				No of Male Toilets	11			
No of Blocks(Buildings)	1							
No of Floors	5 floors (2 basements +ground floor+1st floor +2nd floor)							
Estimate Total Built Area m2	650m2							
No of Students :	900							
Location of shelter within the building :	all the school except the administration offices							
Handicap Facilities								
handicap ramp :	available	no	location		not available		space availability	yes
Handicap toilet :	available	yes	location	GF	not available		space availability	yes
visual structural condition								
Façade cracks	no				Location :			
Façade water leak	np				Location :			
wall Cracks	yes				Location :	ground floor		
Columns cracks	no				Location :			
Beams cracks	no				Location :			
Roof slab cracks	no				Location :			
Ground slab	no				Location :			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					

Environment		 KHATIB & ALAMI CONSOLIDATED ENGINEERING COMPANY S.A.L.	
Quality of water	drinkable		
toilets capacity and quality	nb of toilets is enough fro students and it's newly rehabilitated		
drinking capacity	enough for students		
polution	there's pollution		
play ground	available		
kids play ground	not available		
humidity	present in some areas at the ground floor		
ventilation	good		
Gender separation in sanitation			
mobility to disabled	no		
Env.health condition within school	Good		
waste disposal	available thru Municipalty		
Damages from shelters			
paint wood Doors doors accessories Door paint Elec sockets lighting fixtures Broken solar panel water closets floor Tiles			
Safety			
stairs size	120		
windows at G.F with defence	no		
protection of electrical works	no		
Handrails	yes		
fire extinguishers / Alarms/ smoke detectors	fire extinguishers are present at different locations		
Directional signs	available		
Expected risks in repair works			
Access to school	Accessible		
permits			
schedule by contractor & Resources			
Labor working conditions	good		
repair with occupants inside			

SITE PHOTOS:



Pic showing crack in the walls



View from inside the school



Lever handle and lock to door to
be replaced and door to be
painted



damage in doors needs t be fixed



pic showing the humidity in the walls



pic showing damage in walls



pic showing damage in the toilet



handicap ramp for the toilet



ASSESSMENT REPORT

STAGE A1

409- Al-Murabbiya Souad Al-Masri Official School for Girls

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	409- Al-Murabbiya Souad Al-Masri Official School for Girls				Date of visit :		07/11/2026	
school Location	Village	Abi Samra	Caza	tripoli	coordinations	34.42395208, 35.84673128		
School Principale name :	Safaa abedl Ruzak Al zaayla			Phone No :	70426942			
General Information :								
No of Class Room :	30	No Of Other Rooms:	15	No of Female Toilets	27	Staff	8	
				No of Male Toilets	0 kindergarden	0		
No of Blocks(Buildings)	1							
No of Floors	5floor (bassment+ground+first+second+third)							
Estimate Total Built Area m2	3100 m2 only the used are							
No of Students :	800							
Location of shelter within the building :	all the school except the administration offices and service rooms							
Handicap Facilities								
handicap ramp :	available		location	GF	not available	x	space availability	no
Handicap toilet :	available		location	GF	not available	x	space availability	no
visual structural condition								
Façade cracks	no				Location :			
Façade water leak	yes				Location :	around windows		
wall Cracks	yes				Location :	corridor		
Columns cracks	no				Location :			
Beams cracks	no				Location :			
Roof slab cracks	no				Location :			
Ground slab	no				Location :			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					

Environment			
Quality of water	Good and drinkable		
toilets capacity and quality	nb of toilets is acceptable but not all working		
drinking capacity	enough for students		
pollution	no		
play ground	available		
kids play ground	available		
humidity	present in the school from windows and roof floor		
ventilation	good		
Gender separation in sanitation	yes		
mobility to disabled	yes		
Env.health condition within school	some wc are leaking		
waste disposal	available thru Municipality		
Damages from shelters			
paint wood Doors doors accessories Door paint Elec sockets lighting fixtures water closets floor Tiles electricity problem			
Safety			
stairs size	yes.		
windows at G.F with defence	yes.		
protection of electrical works	safe		
Handrails	yes.		
fire extinguishers / Alarms/ smoke detectors	no		
Directional signs	No		
Expected risks in repair works			
Access to school	Accessible		
permits			
schedule by contractor & Resources			
Labor working conditions	good		
repair with occupants inside			

Site Photos:



General View to school




General View to school



Drinking Basin inside playground



Electrical socket to be repaired



Broken wooden door need to be repaired



Broken wooden door need to be repaired



status of the washing basin



wall need repair



cracks between joints of coulmn



Humidity and water leak from
elevations shown inside the
building



crackst to be repaired



bassment pump status




ASSESSMENT REPORT

STAGE A1

429- Al-Farabi Official School for Boys

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	429- Al-Farabi Official School for Boys					Date of visit :		07/11/2026	
school Location	Village	Al Qobbeh	Caza	tripoli	coordinations	34.43288833, 35.84793141			
School Principale name :	Mona Youssef Saad			Phone No :	70328019				
General Information :									
No of Class Room :	9	No Of Other Rooms:	1	No of Female Toilets	6	Staff	2		
				No of Male Toilets	kindergarden			0	
No of Blocks(Buildings)	1								
No of Floors	ground floor but its part of residential building of 4 floors								
Estimate Total Built Area m2	400								
No of Students :	188								
Location of shelter within the building :	all the school except the administration offices and service rooms								
Handicap Facilities									
handicap ramp :	available		location	GF	not available	x	space availability	no	
Handicap toilet :	available		location	GF	not available	x	space availability	no	
visual structural condition									
Façade cracks	no				Location :				
Façade water leak	yes				Location :	around windows			
wall Cracks	yes				Location :	corridor			
Columns cracks	no				Location :				
Beams cracks	no				Location :				
Roof slab cracks	no				Location :				
Ground slab	no				Location :				
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs						
	Category 2		need comprehensive rehabilitation including structural						

Environment

Quality of water	Good and drinkable
toilets capacity and quality	nb of toilets is acceptable but not working
drinking capacity	enough for students
pollution	no
play ground	available
kids play ground	available
humidity	present in the school from windows and roof floor
ventilation	good
Gender separation in sanitation	yes
mobility to disabled	yes
Env.health condition within school	the building surrounding of the school have risk of fall on the school
waste disposal	available through Municipality

Damages from shelters

paint
 wood Doors
 doors accessories
 Door paint
 Elec sockets
 lighting fixtures
 water closets
 floor Tiles
 electricity problem

Safety

stairs size	yes.
windows at G.F with defence	yes.
protection of electrical works	yes.
Handrails	yes.
fire extinguishers / Alarms/ smoke detectors	yes.
Directional signs	No


Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:



General View to school



General View to school



Drinking Basin inside playground



Broken metal door need to be repaired



Broken wooden door need to be repaired



Broken metal door need to be repaired



Broken concret need to be repaired



tiles need repair and its slippery

ASSESSMENT REPORT

STAGE A1

448 -Georges Sarraf public school

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1


School Name:	448 -Georges Sarraf public school				Date of visit : 16/7/2026	
school Location	Village	Abi Samra	Caza	Tripoli	coordinations	34.4162173 35.8392034
School Principale name :	Sherine Sfarjalani			Phone No :	3199653	
General Information :						
No of Class Room :	14	No Of Other Rooms:	6	No of Female Toilets	10	
				No of Male Toilets	10	
No of Blocks(Buildings)	1					
No of Floors	4 floors(ground floor+1st floor +2nd floor+3rd floor)					
Estimate Total Built Area m2	1700 m2					
No of Students :	370					
Location of shelter within the building :			all the school except the administration offices			
Handicap Facilities						
handicap ramp :	available	NO	location		not available	space availability yes
Handicap toilet :	available	NO	location		not available	space availability yes
visual structural condition						
Façade cracks	yes			Location :	first floor	
Façade water leak	no			Location :		
wall Cracks	yes			Location :	third floor	
Columns cracks	no			Location :		
Beams cracks	no			Location :		
Roof slab cracks	no			Location :		
Ground slab	no			Location :		
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs			
	Category 2		need comprehensive rehabilitation including structural			

Environment			
Quality of water	drinkable		
toilets capacity and quality	nb of toilets is enough fro students and it's newly rehabilitated		
drinking capacity	not enough for students		
polution	there's pollution		
play ground	available		
kids play ground	not available		
humidity	present in some areas at the ground floor		
ventilation	good		
Gender separation in sanitation			
mobility to disabled	no		
Env.health condition within school	Good		
waste disposal	available thru Municipalty		
Damages from shelters			
paint wood Doors doors accessories Door paint Elec sockets lighting fixtures Broken solar panel water clotets floor Tiles			
Safety			
stairs size	170		
windows at G.F with defence	no		
protection of electrical works	yes		
Handrails	yes		
fire extinguishers / Alarms/ smoke detectors	fire extinguishers are present at different locations		
Directional signs	available		
Expected risks in repair works			
Access to school	Accessible		
permits			
schedule by contractor & Resources			
Labor working conditions	good		
repair with occupants inside			


SITE PHOTOS:



Pic showing crack in the walls



View from inside the school



Lever handle and lock to door to be replaced and door to be painted



damage in doors needs t be fixed



pic showing the humidity in the ceiling




damage in the outdoor toilet




pic showing crack in the walls



damage in the playground walls



damage in the toilet



damage of exhost



maintenance of aluminium door



damage in the windows

ASSESSMENT REPORT

STAGE A1

697- Dahr El Ein Mixed Public School

JULY 2026



Assessment Report stage A1

School Name:	697-Dahr El Ein Mixed Public School				Date of visit :		07/08/2026	
school Location	Village	Dahr El Ein	Caza	Koura	coordinations	34.390513, 35.847675		
School Principale name :	Samira Moussa			Phone No :	71 563873			
General Information :								
No of Class Room :	16	No Of Other Rooms:	9	No of Female Toilets	9			
				No of Male Toilets	9			
No of Blocks(Buildings)	1							
No of Floors	03 floors (ground+ first + second floor)							
Estimate Total Built Area m2	2550							
No of Students :	441							
Location of shelter within the building :	all the school except the administration offices and service rooms							
Handicap Facilities								
handicap ramp :	available		location		not available	X	space availability	X
Handicap toilet :	available		location		not available	X	space availability	X
visual structural condition								
Façade cracks	yes				Location :	different locations		
Façade water leak	yes				Location :	different locations		
wall Cracks	yes				Location :	different locations		
Columns cracks	yes				Location :	different locations		
Beams cracks	yes				Location :	different locations		
Roof slab cracks	yes				Location :	different locations		
Ground slab	no				Location :			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					

Environment			
Quality of water	Good and drinkable		
toilets capacity and quality	nb of toilets is acceptable		
drinking capacity	needs to be increased		
pollution	no		
play ground	available		
kids play ground	available		
humidity	present in the school at different locations		
ventilation	good		
Gender separation in sanitation	yes		
mobility to disabled	no		
Env.health condition within school	poor because of humidity and water leak.		
waste disposal	available thru Municipality		
...			
paint wood Doors metal Doors doors accessories Door paint Damages from shelters Elec sockets lighting fixtures water closets mixers toilet finishing Floor drain lavatories counter top floor Tiles aluminum glazing aluminum Accessories roof water proofing			
Safety			
stairs size	160 cm		
windows at G.F with defence	yes.		
protection of electrical works	no		
Handrails	yes.		
fire extinguishers / Alarms/ smoke detectors	fire extinguishers are present at different locations		
Directional signs	No		
Expected risks in repair works			
Access to school	Accessible		
permits			
schedule by contractor & Resources			
Labor working conditions	good		
repair with occupants inside			

Site Photos:



General View to school



General View to school



General View to school



Pic showing the water leak inside
the building



crack and rusted steel which
required special method to rehab



Water leak thru ceiling and walls



Water leak thru ceiling




The majority of steel windows are
not working properly



Pic showic the bad situation of woden doors



Wash basin inside wc at ground floor



pic showing a wc not working and required to be replaced



pic showing a malfunctioning electrical socket and switch


ASSESSMENT REPORT

STAGE A1

704- Gibran Makari Public School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	704- Gibran Makari Public School					Date of visit : 16/7/2026	
school Location	Village	Anfeh	Caza	Koura	coordinations	34.360025, 35.731094	
School Principale name :	Rania Daaboul			Phone No :	03 167766		
General Information :							
No of Class Room :	16	No Of Other Rooms:	9	No of Female Toilets	9		
				No of Male Toilets	9		
No of Blocks(Buildings)	4						
No of Floors	03 floors (ground+ first + second floor)						
Estimate Total Built Area m2	4980						
No of Students :	135						
Location of shelter within the building :	all the school except the administration offices and service rooms						
Handicap Facilities							
handicap ramp :	available	X	location	X	not available	space availability	
Handicap toilet :	available	X	location	X	not available	space availability	
visual structural condition							
Façade cracks	yes				Location :	different locations	
Façade water leak	yes				Location :	different locations	
wall Cracks	yes				Location :	different locations	
Columns cracks	yes				Location :	different locations	
Beams cracks	yes				Location :	different locations	
Roof slab cracks	yes				Location :	different locations	
Ground slab	no				Location :		
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs				
	Category 2		need comprehensive rehabilitation including structural				

Environment

Quality of water	Good and drinkable
toilets capacity and quality	nb of toilets is acceptable
drinking capacity	needs to be increased
pollution	no
play ground	available
kids play ground	available
humidity	present in the school at different locations
ventilation	good
Gender separation in sanitation	yes
mobility to disabled	yes
Env.health condition within school	poor because of humidity and water leak.
waste disposal	available thru Municipality

Damages from shelters

paint
 wood Doors
 metal Doors
 doors accessories
 Door paint
 Elec sockets
 lighting fixtures
 aluminum
 glaZing
 aluminum Accessories
 roof water proofing

Safety

stairs size	200 cm
windows at G.F with defence	yes.
protection of electrical works	no
Handrails	yes.
fire extinguishers / Alarms/ smoke detectors	Fire hose cabinets are installed in the school
Directional signs	No

Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:



General View to school



General View to school



General View to school



General view inside the school



crack and rusted steel which
required special method to rehab



Water leak thru ceiling and walls



Pic showing the water leak inside
the building



Pic showic the bad situation of woden doors



Picture showing the water leak thru wall and windows



Picture showing the water proofing membrane



crack and rusted steel which required special method to rehab


ASSESSMENT REPORT

STAGE A1

725-Kfar Aaqqa Mixed Public School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	758-Kfar Aaqqa Mixed Public School					Date of visit :		07/10/2026	
school Location	Village	Kfar Aaqqa	Caza	Koura	coordinations	34.305153, 35.835983			
School Principale name :	Miriam Farah			Phone No :	76 054 125				
General Information :									
No of Class Room :	9	No Of Other Rooms:	7	No of Female Toilets	4				
				No of Male Toilets	4				
No of Blocks(Buildings)	1								
No of Floors	02 floors (ground+ first floor)								
Estimate Total Built Area m2	1280								
No of Students :	145 day shift+ 246 night shift								
Location of shelter within the building :	all the school except the administration offices and service rooms								
Handicap Facilities									
handicap ramp :	available	X	location	GF	not available		space availability		
Handicap toilet :	available	X	location	GF	not available		space availability		
visual structural condition									
Façade cracks	yes				Location :	different locations			
Façade water leak	yes				Location :	different locations			
wall Cracks	yes				Location :	different locations			
Columns cracks	yes				Location :	different locations			
Beams cracks	yes				Location :	Ground Floor			
Roof slab cracks	yes				Location :	different locations			
Ground slab	no				Location :				
Repair assessment	Category1	X	can be rehabilitated with minor Fixes and repairs						
	Category 2		need comprehensive rehabilitation including structural						

Environment

Quality of water	Good and drinkable
toilets capacity and quality	nb of toilets needs to be increased
drinking capacity	needs to be increased (only 06 drinking taps)
pollution	no
play ground	available
kids play ground	available
humidity	present in the school at different locations
ventilation	good
Gender separation in sanitation	yes
mobility to disabled	yes at ground floor only
Env.health condition within school	poor because of humidity and water leak.
waste disposal	available thru Municipality

Damages from shelters

paint
 wood Doors
 metal Doors
 doors accessories
 Door paint and rehab
 Elec sockets
 lighting fixtures
 mixers
 toilet finishing
 aluminum
 glazing
 aluminum Accessories
 roof water proofing

Safety

stairs size	≤ 150 cm
windows at G.F with defence	yes.
protection of electrical works	no
Handrails	yes.
fire extinguishers / Alarms/ smoke detectors	fire extinguishers and smoke detectors are present at different locations
Directional signs	yes.

Expected risks in repair works

Access to school	The access is dangerous because it is directly on the high way with no defense.
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:



General View to school



General View to school



General View to school



General View to school



Existing Water proofing
membrane which required to be
changed



Wooden partition installed by
shelters inside the room



Water leak thru ceiling and
elevation



the bad condition of the structure
of the slab due to humidity and
water leak, and which required
maintenance




Pic showic the bad situation of woden doors



pic showing a malfunctioning electrical socket and switch



this pic shows the broken tiles inside the wc and which need to be repaired



this pic reflect the bad condition of the existing woden doors

ASSESSMENT REPORT

STAGE A1

730- Kfar Hata Mixed Public High School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	730-Kfar Hata Mixed Public High School					Date of visit :		07/10/2026	
school Location	Village	Kfar Hata	Caza	Koura	coordinations	34.281846, 35.750694			
School Principale name :	Maya Fidawi			Phone No :	71 822 584				
General Information :									
No of Class Room :	8		No Of Other Rooms:		8		No of Female Toilets		3
							No of Male Toilets		5
No of Blocks(Buildings)	1								
No of Floors	03 floors (basement+ground+ first floor)								
Estimate Total Built Area m2	1280								
No of Students :	122								
Location of shelter within the building :			all the school except the administration offices and service rooms						
Handicap Facilities									
handicap ramp :	available		location		not available	X	space availability	X	
Handicap toilet :	available		location		not available	X	space availability	X	
visual structural condition									
Façade cracks	yes				Location :	different locations			
Façade water leak	yes				Location :	different locations			
wall Cracks	yes				Location :	different locations			
Columns cracks	yes				Location :	different locations			
Beams cracks	yes				Location :	Ground Floor			
Roof slab cracks	yes				Location :	different locations			
Ground slab	no				Location :	s			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs						
	Category 2		need comprehensive rehabilitation including structural						

Environment

Quality of water	Good and drinkable
toilets capacity and quality	nb of toilets needs to be increased
drinking capacity	needs to be increased (only 06 drinking taps)
pollution	no
play ground	available
kids play ground	available
humidity	present in the school at different locations
ventilation	good
Gender separation in sanitation	yes
mobility to disabled	yes at ground floor only
Env.health condition within school	poor because of humidity and water leak.
waste disposal	available thru Municipality

...

Damages from shelters

paint
 wood Doors
 metal Doors
 doors accessories
 Door paint
 Elec sockets
 lighting fixtures
 Broken solar panel
 wash basin
 water closets
 mixers
 Kitchen
 toilet finishing
 Floor drain
 lavatories counter top
 floor Tiles
 aluminum
 glazing
 aluminum Accessories
 roof water proofing

Safety

stairs size	≤ 150 cm
windows at G.F with defence	yes.
protection of electrical works	no
Handrails	yes.
fire extinguishers / Alarms/ smoke detectors	fire extinguishers and smoke detectors are present at different locations
Directional signs	yes.

Expected risks in repair works

Access to school	The access is dangerous because it is directly on the highway with no defense.
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:



General View to school



General View to school



General View to school



Existing Water proofing
membrane which required to be
changed




Water leak thru ceiling and
existing old lighting.



Water leak thru elevation



Water leak thru elevation



Water leak thru elevation



Water leak thru ceiling



Door and ceramic grout
rehabilitation is required



Drinking basin and drinking taps


ASSESSMENT REPORT

STAGE A1

748-Chekka Intermediate Public School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	748-Chekka Mixed Public School					Date of visit :	07/11/2026		
school Location	Village	Chekka	Caza	Batroun	coordinations	34.324352, 35.728733			
School Principale name :	Joseph Sassine			Phone No :	03 870 282				
General Information :									
No of Class Room :	24	No Of Other Rooms:	6	No of Female Toilets	4				
				No of Male Toilets	4				
No of Blocks(Buildings)	1								
No of Floors	3 floors (first+ second+ third floor)								
Estimate Total Built Area m2	3480								
No of Students :	187								
Location of shelter within the building :	all the school except the administration offices and service rooms								
Handicap Facilities									
handicap ramp :	available		location		not available	X	space availability	X	
Handicap toilet :	available		location		not available	X	space availability	X	
visual structural condition									
Façade cracks	yes				Location :	different locations			
Façade water leak	yes				Location :	different locations			
wall Cracks	yes				Location :	different locations			
Columns cracks	yes				Location :	different locations			
Beams cracks	yes				Location :	different locations			
Roof slab cracks	yes				Location :	different locations			
Ground slab	no				Location :				
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs						
	Category 2		need comprehensive rehabilitation including structural						

Environment

Quality of water	Good and drinkable
toilets capacity and quality	nb of toilets needs to be increased
drinking capacity	needs to be increased (only 06 drinking taps)
pollution	no
play ground	available
kids play ground	available
humidity	present in the school at different locations
ventilation	good
Gender separation in sanitation	yes
mobility to disabled	yes at ground floor only
Env.health condition within school	poor because of humidity and water leak.
waste disposal	available thru Municipality

...

Damages from shelters

paint
 wood Doors
 metal Doors
 doors accessories
 Door paint
 Elec sockets
 lighting fixtures
 wash basin
 water closets
 mixers
 toilet finishing
 Floor drain
 floor Tiles
 aluminum
 glazing
 aluminum Accessories
 roof water proofing

Safety

stairs size	≤ 150 cm
windows at G.F with defence	no
protection of electrical works	no
Handrails	yes.
fire extinguishers / Alarms/ smoke detectors	only 02 fire extinguishers are available
Directional signs	no

Expected risks in repair works

Access to school	good
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:



General View to school



General View to school



General View to school



Existing Water proofing
membrane which required to be
changed



picture showing the bad condition of the wooden door, wall cracks can be also notified



Water leak thru ceiling and elevation



Water leak thru ceiling and elevation




the bad condition of the structure of the slab due to humidity and water leak, and which required maintenance



the majority of the existing steel windows are in very bad condition and need to be replaced



Pic showing the ironmongery of the wooden door



Broken tiles and broken door inside the WC



this pic reflect the bad condition of the existing building structure


ASSESSMENT REPORT

STAGE A1

752-Al Heri Mixed Public School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	752-Al Heri Mixed Public School					Date of visit :		07/10/2026	
school Location	Village	Al Heri	Caza	Batroun	coordinations	34.308510, 35.716425			
School Principale name :	Mariam Samrout			Phone No :	70 462 584				
General Information :									
No of Class Room :	13	No Of Other Rooms:	8	No of Female Toilets	4				
				No of Male Toilets	4				
No of Blocks(Buildings)	1								
No of Floors	3 floors (ground+ first+ second floor)								
Estimate Total Built Area m2	1095								
No of Students :	122								
Location of shelter within the building :	all the school except the administration offices and service rooms								
Handicap Facilities									
handicap ramp :	available	X	location	GF	not available		space availability		
Handicap toilet :	available	X	location	GF	not available		space availability		
visual structural condition									
Façade cracks	yes				Location :	at first floor			
Façade water leak	yes				Location :	at first floor			
wall Cracks	yes				Location :	at first floor			
Columns cracks	no				Location :				
Beams cracks	no				Location :				
Roof slab cracks	no				Location :				
Ground slab	no				Location :				
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs						
	Category 2		need comprehensive rehabilitation including structural						

Environment

Quality of water	Good and drinkable
toilets capacity and quality	acceptable
drinking capacity	acceptable
pollution	no
play ground	available
kids play ground	available
humidity	present in the school mainly at second floor and stair case
ventilation	good
Gender separation in sanitation	yes
mobility to disabled	yes at ground floor only
Env.health condition within school	good
waste disposal	available thru Municipality

Damages from shelters

paint
 wood Doors
 metal Doors
 doors accessories
 Door paint
 Elec sockets
 lighting fixtures
 roof water proofing

Safety

stairs size	100 cm
windows at G.F with defence	yes.
protection of electrical works	no
Handrails	yes.
fire extinguishers / Alarms/ smoke detectors	fire extinguishers are present at different locations
Directional signs	yes.

Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:



General View to school



General View to school



General View to roof with solar panels



Picture showing the stair's school



Water leak thru ceiling and elevation



Water leak thru elevation




Water leak thru elevation



Pic showic the bad situation of electric socket



the wall near the wooden frame need to be rehabilitated



Picture showing the drainage leak from the wc located above this room



picture showing the wooden doors paint condition


ASSESSMENT REPORT

STAGE A1

755- Batroun Official School for Girls

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	755- Batroun Official School for Girls					Date of visit :		07/11/2026	
school Location	Village	Batroun	Caza	batroun	coordinations	34.25439026, 35.66221628			
School Principale name :	Rima Youssef Hwayek			Phone No :	3653905				
General Information :									
No of Class Room :	15	No Of Other Rooms:	4	No of Female Toilets	4	Staff	1		
				No of Male Toilets	3	kindergarden		0	
No of Blocks(Buildings)	1								
No of Floors	3 floor (+ground+first +second)								
Estimate Total Built Area m2	1400 m2								
No of Students :	75								
Location of shelter within the building :	all the school except the administration offices and service rooms								
Handicap Facilities									
handicap ramp :	available		location	GF	not available	x	space availability	no	
Handicap toilet :	available		location	GF	not available	x	space availability	no	
visual structural condition									
Façade cracks	yes				Location :				
Façade water leak	yes				Location :		around windows		
wall Cracks	yes				Location :				
Columns cracks	yes				Location :				
Beams cracks	no				Location :				
Roof slab cracks	no				Location :				
Ground slab	no				Location :				
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs						
	Category 2		need comprehensive rehabilitation including structural						

Environment			
Quality of water	not Good and drinkable		
toilets capacity and quality	nb of toilets is acceptable but not working		
drinking capacity	enough for students		
pollution	no		
play ground	available		
kids play ground	available		
humidity	present in the school from windows and roof floor		
ventilation	good		
Gender separation in sanitation	yes		
mobility to disabled	yes		
Env.health condition within school	some wc are leaking to the floors below		
waste disposal	available thru Municipality		
Damages from shelters			
paint wood Doors doors accessories Door paint Elec sockets lighting fixtures water closets floor Tiles electricity problem			
Safety			
stairs size	yes.		
windows at G.F with defence	yes.		
protection of electrical works	yes.		
Handrails	yes.		
fire extinguishers / Alarms/ smoke detectors	no		
Directional signs	No		
Expected risks in repair works			
Access to school	Accessible		
permits			
schedule by contractor & Resources			
Labor working conditions	good		
repair with occupants inside			


Site Photos:



General View to school



General View to school



Drinking Basin inside playground



Electrical word to be repaired



cracks in column need to be repaired



cracks in column need to be repaired




status of the washing basin



w.c need to be repaired



cracks in slab need to be repaired



Humidity and water leak from the
roof and elevations shown inside
the building



Humidity and water leak



stairs need to be repaired

ASSESSMENT REPORT

STAGE A1

756 -Estephan Attieh Intermediate Mixed Public School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	756 -Estephan Attieh Intermediate Mixed Public School				Date of visit :		07/11/2026	
school Location	Village	Batroun	Caza	Batroun	coordinations	34.25423871,35.66314155		
School Principale name :	Nouhad Mouzaya			Phone No :	3916357			
General Information :								
No of Class Room :	23	No Of Other Rooms:	10	No of Female Toilets	11	Staff	5	
				No of Male Toilets	12	kindergarden		4
No of Blocks(Buildings)	2							
No of Floors	3 floor (+ground+first +second)							
Estimate Total Built Area m2	4900 m2							
No of Students :	200							
Location of shelter within the building :			all the school except the administration offices and service rooms					
Handicap Facilities								
handicap ramp :	available		location	GF	not available	x	space availability	no
Handicap toilet :	available	X	location	GF	not available		space availability	
visual structural condition								
Façade cracks	NO				Location :			
Façade water leak	yes				Location :	around windows		
wall Cracks	yes				Location :	Fence and corridor		
Columns cracks	yes				Location :	Fence and corridor		
Beams cracks	yes				Location :	corridor second floor		
Roof slab cracks	no				Location :			
Ground slab	no				Location :			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					

Environment

Quality of water	Good and drinkable
toilets capacity and quality	nb of toilets is acceptable but not all working
drinking capacity	enough for students
pollution	no
play ground	available
kids play ground	available
humidity	present in the school from windows and roof floor
ventilation	good
Gender separation in sanitation	yes
mobility to disabled	yes
Env.health condition within school	
waste disposal	available through Municipality

Damages from shelters

paint
 wood Doors
 doors accessories
 Door paint
 Elec sockets
 lighting fixtures
 water closets
 floor Tiles
 electricity problem

Safety

stairs size	yes.
windows at G.F with defence	yes.
protection of electrical works	yes.
Handrails	yes.
fire extinguishers / Alarms/ smoke detectors	no
Directional signs	No

Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:



General View to school



General View to school




Drinking Basin inside playground



Electrical socket status



cracks wall &column need to be
repaired in play ground



cracks wall &column need to be
repaired



status of the washing basin




moisture on the wall need to be
repaired



cracks in beams to be repaired



status of the steel locks



Humidity and water leak from
roof



Humidity and water leak at WC
area and leaking


ASSESSMENT REPORT

STAGE A1


763-Abrine Mixed Public School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	763-Abrine Mixed Public School					Date of visit : 15/7/2026	
school Location	Village	Abrine	Caza	Batroun	coordinations	34.252483 35.705242	
School Principale name :	Ayda Chahine			Phone No :	03 349091		
General Information :							
No of Class Room :	10		No Of Other Rooms:	7		No of Female Toilets	3
						No of Male Toilets	4
No of Blocks(Buildings)	1						
No of Floors	02 floors (ground+ first floor)						
Estimate Total Built Area m2	950 m2						
No of Students :	130						
Location of shelter within the building :			all the school except the administration offices				
Handicap Facilities							
handicap ramp :	available		location		not available	X	space availability No
Handicap toilet :	available		location		not available	X	space availability No
visual structural condition							
Façade cracks	yes				Location :	all school	
Façade water leak	yes				Location :	all school	
wall Cracks	yes				Location :	all school	
Columns cracks	yes				Location :	all school	
Beams cracks	yes				Location :	all school	
Roof slab cracks	yes				Location :	all school	
Ground slab					Location :		
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs				
	Category 2		need comprehensive rehabilitation including structural				

Environment

Quality of water	drinkable with filters
toilets capacity and quality	acceptable
drinking capacity	acceptable
pollution	no
play ground	yes
kids play ground	yes
humidity	yes because of water leak
ventilation	good
Gender separation in sanitation	no
mobility to disabled	no
Env.health condition within school	good
waste disposal	thru Municipality

Damages from shelters

paint
 wood Doors
 metal Doors
 doors accessories
 Door paint
 Elec sockets
 lighting fixtures
 aluminum
 glazing
 aluminum Accessories
 roof water proofing

Safety

stairs size	
windows at G.F with defence	yes.
protection of electrical works	yes.
Handrails	yes.
fire extinguishers / Alarms/ smoke detectors	fire extinguishers quantities are not enough to cover the school
Directional signs	No

Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:



General view to school



General view to school



Pic showing the bed condition of
water proofing membrane



Pic showing the water leak



water leak thru elevation walls



water leak thru elevation walls



water leak thru elevation walls



Pic showing the humidity and the
water leak thru slab

ASSESSMENT REPORT

STAGE A1

764- Abrine High School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	764- Abrine High School					Date of visit : 15/7/2026	
school Location	Village	Abrine	Caza	Koura	coordinations	34.252061, 35.704356	
School Principale name :	Samira Moussa			Phone No :	71 563873		
General Information :							
No of Class Room :	7	No Of Other Rooms:	4	No of Female Toilets	3		
				No of Male Toilets	2		
No of Blocks(Buildings)	1						
No of Floors	04 floors (ground+ first + second + third floor)						
Estimate Total Built Area m2	260						
No of Students :	104						
Location of shelter within the building :	all the school except the administration offices						
Handicap Facilities							
handicap ramp :	available		location		not available	X	space availability no
Handicap toilet :	available		location		not available	X	space availability no
visual structural condition							
Façade cracks	no				Location :	no	
Façade water leak	yes				Location :	different locations	
wall Cracks	no				Location :		
Columns cracks	no				Location :		
Beams cracks	no				Location :		
Roof slab cracks	no				Location :		
Ground slab	no				Location :		
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs				
	Category 2		need comprehensive rehabilitation including structural				

Environment		
Quality of water	Good and drinkable	
toilets capacity and quality	nb of toilets is acceptable	
drinking capacity	needs to be increased	
pollution	no	
play ground	available	
kids play ground	available	
humidity	present in the school mainly around windows	
ventilation	good	
Gender separation in sanitation	no	
mobility to disabled	no	
Env.health condition within school	poor because the drinking basin is located inside the WC	
waste disposal	available thru Municipality	
Damages from shelters		
paint		
wood Doors		
metal Doors		
doors accessories		
Door paint		
aluminum		
glazing		
aluminum Accessories		
TOT shed which required to be replaced with sandwich panel.		
Safety		
stairs size	<160 cm	
windows at G.F with defence	yes.	
protection of electrical works	yes.	
Handrails	yes.	
fire extinguishers / Alarms/ smoke detectors	fire extinguishers are present at different locations	
Directional signs	No	
Expected risks in repair works		
Access to school	Accessible	
permits		
schedule by contractor & Resources		
Labor working conditions	good	
repair with occupants inside		

Site Photos:



General View to school




General View to school



General View to school



Pic showing the damaged steel door



picture inside the school stair
case



Water leak from aluminum
window



Water leak thru TOT



Water leak thru TOT




ASSESSMENT REPORT

STAGE A1

1377- Tripoli Al Qobbeh Second Official Mixed High School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	1377- Tripoli Al-Qobbeh Second Official Mixed High School					Date of visit : 07/11/2026	
school Location	Village	Al Qobbeh	Caza	kesrwan	coordinations	34.44034445, 35.85239122,	
School Principale name :	Ali Mohamad issa			Phone No :	71176546		
General Information :							
No of Class Room :	23	No Of Other Rooms:	9	No of Female Toilets	7	Staff	3
				No of Male Toilets	10 kindergarden		0
No of Blocks(Buildings)	1						
No of Floors	3(ground+first +second)						
Estimate Total Built Area m2	2300 m2						
No of Students :	474						
Location of shelter within the building :		all the school except the administration offices and service rooms					
Handicap Facilities							
handicap ramp :	available		location	GF	not available	x	space availability no
Handicap toilet :	available		location	GF	not available	x	space availability no
visual structural condition							
Façade cracks	no				Location :		
Façade water leak	no				Location :		
wall Cracks	no				Location :		
Columns cracks	no				Location :		
Beams cracks	no				Location :		
Roof slab cracks	no				Location :		
Ground slab	no				Location :		
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs				
	Category 2		need comprehensive rehabilitation including structural				

Environment			
Quality of water	Good and drinkable		
toilets capacity and quality	nb of toilets is acceptable		
drinking capacity	enough for students		
pollution	no		
play ground	available		
kids play ground	available		
humidity	no		
ventilation	good		
Gender separation in sanitation	yes		
mobility to disabled	yes		
Env.health condition within school	yes		
waste disposal	yes		
Damages from shelters			
paint wood Doors doors accessories Door paint Elec sockets lighting fixtures water closets floor Tiles electricity problem			
Safety			
stairs size	yes.		
windows at G.F with defence	yes.		
protection of electrical works	yes.		
Handrails	yes.		
fire extinguishers / Alarms/ smoke detectors	no		
Directional signs	No		
Expected risks in repair works			
Access to school	Accessible		
permits			
schedule by contractor & Resources			
Labor working conditions	good		
repair with occupants inside			

Site Photos:



General View to school



General View to school



windows status



Electrical socket to be repaired


ASSESSMENT REPORT

STAGE A1

1403 - Wadi el Nahleh public mixed school

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	1403 - Wadi el Nahleh public mixed school				Date of visit : 14/7/2026	
school Location	Village	Wadi el Nahleh	Caza	Denniyeh	coordinations	34.26599 35.51598
School Principale name :	Hanan Awik			Phone No :	70 568961	
General Information :						
No of Class Room :	16	No Of Other Rooms:	4	No of Female Toilets	6	
				No of Male Toilets	4	
No of Blocks(Buildings)	1					
No of Floors	2 floors (GF - 1st)					
Estimate Total Built Area m2	750					
No of Students :	311					
Location of shelter within the building :			GF only			
Handicap Facilities						
handicap ramp :	available		location		not available	X
						space availability
						No
Handicap toilet :	available		location		not available	X
						space availability
						No
visual structural condition						
Façade cracks	yes				Location :	1st
Façade water leak	yes				Location :	all
wall Cracks	yes				Location :	all
Columns cracks	yes				Location :	1st
Beams cracks	yes				Location :	1st
Roof slab cracks	yes				Location :	1st
Ground slab	no				Location :	
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs			
	Category 2		need comprehensive rehabilitation including structural			

Environment

Quality of water	not drinkable
toilets capacity and quality	nb of toilets is not enough for students and to be rehabilitated
drinking capacity	not enough for students
pollution	pollution
play ground	available
kids play ground	not available
humidity	present in some areas at first floor between rooms
ventilation	not good
Gender separation in sanitation	yes
mobility to disabled	no
Env.health condition within school	Good
waste disposal	available thru Municipalty

Damages from shelters

paint
 wood Doors -
 doors accessories 2
 Door paint -
 Elec sockets -
 lighting fixtures 2
 Broken solar panel -
 water closets 2
 floor Tiles 2

Safety

stairs size	110
windows at G.F with defence	yes.
protection of electrical works	no
Handrails	yes.
fire extinguishers / Alarms/ smoke detectors	no
Directional signs	no

Expected risks in repair works

Access to school	Accessible
permits	yes
schedule by contractor & Resources	
Labor working conditions	very bad
repair with occupants inside	

SITE PHOTOS:



Pic showing damage in the ceiling



View from outside the school



Lever handle and lock to door to be replaced and door to be rehabilitated



Pic showing the humidity



pic showing the cracks of wall inid
the school



Pic showing the bad conditions if
the paint



Crack in column



Pics showing the bad conditions
of Wc in the school


ASSESSMENT REPORT

STAGE A1

1521 - Al Beddaoui Intermediate school for girls

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	1521 - Al Beddaoui Intermediate school for girls				Date of visit :	07/07/2026
school Location	Village	Al Beddaoui	Caza	Tripoli	coordinations	34.451626 35.863750
School Principale name :	Jihan Korhani			Phone No :	70 024278	

General Information :									
No of Class Room :		19	No Of Other Rooms:		5	No of Female Toilets		6	
						No of Male Toilets		8	
No of Blocks(Buildings)		2							
No of Floors		first block 1 floor and second block GF + mezanine + 1st + 2nd floor							
Estimate Total Built Area m2		1077 m2							
No of Students :		435							
Location of shelter within the building :				GF and 1st floor					
Handicap Facilities									
handicap ramp :		available	yes	location	GF	not available		space availability	
Handicap toilet :		available	yes	location	GF	not available		space availability	

visual structural condition					
Façade cracks	no			Location :	
Façade water leak	no			Location :	
wall Cracks	no			Location :	
Columns cracks	no			Location :	
Beams cracks	no			Location :	
Roof slab cracks	no			Location :	
Ground slab				Location :	
Repair assessment	Category 1	x	can be rehabilitated with minor Fixes and repairs		
	Category 2		need comprehensive rehabilitation including structural		

Note:

Environment		 KHAYIB & ALAMI CONSOLIDATED ENGINEERING COMPANY S.A.S.	
Quality of water	Good		
toilets capacity and quality	nb of toilets is acceptable		
drinking capacity	enough for students		
pollution	no		
play ground	available		
kids play ground	available		
humidity	present in the school from windows and roof floor		
ventilation	good		
Gender separation in sanitation	no		
mobility to disabled	yes		
Env.health condition within school	some wc are leaking to the floors below		
waste disposal	available thru Municipality		
Damages from shelters			
Safety			
stairs size	130		
windows at G.F with defence	yes.		
protection of electrical works	yes.		
Handrails	yes.		
fire extinguishers / Alarms/ smoke detectors	yes.		
Directional signs	yes.		
Expected risks in repair works			
Access to school	Accessible		
permits			
schedule by contractor & Resources			
Labor working conditions	good		
repair with occupants inside			

Site Photos:



General view to school



HPL door need to be maintain



Pic showing the humidity from
the window



Pic showing the sanitary need to be maintain



pic showing the vinyl



Pic showing the aluminum need to be maitain

ASSESSMENT REPORT

STAGE A1

1606 -Ibn khaldoun public school for girls

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	1606 -Ibn khaldoun public school for girls				Date of visit :		16/7/2026	
school Location	Village	Abi Samra	Caza	Tripoli	coordinations	34.4137493 35.8494941		
School Principale name :	Hala jajatieh			Phone No :	03 589098			
General Information :								
No of Class Room :	16		No Of Other Rooms:	7		No of Female Toilets	18	
						No of Male Toilets	3	
No of Blocks(Buildings)	1							
No of Floors	5 floors (2 basements +ground floor+1st floor +2nd floor)							
Estimate Total Built Area m2	700m2							
No of Students :	415							
Location of shelter within the building :			all the school except the administration offices					
Handicap Facilities								
handicap ramp :	available	yes	location	GF	not available		space availability	
Handicap toilet :	available	yes	location	GF	not available		space availability	
visual structural condition								
Façade cracks	no				Location :			
Façade water leak	np				Location :			
wall Cracks	yes				Location :	ground floor		
Columns cracks	no				Location :			
Beams cracks	no				Location :			
Roof slab cracks	no				Location :			
Ground slab	no				Location :			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					

Environment

Quality of water	drinkable
toilets capacity and quality	nb of toilets is enough fro students and it's newly rehabilitated
drinking capacity	enough for students
pollution	there's pollution
play ground	available
kids play ground	not available
humidity	present in some areas at the ground floor
ventilation	good
Gender separation in sanitation	
mobility to disabled	no
Env.health condition within school	Good
waste disposal	available through Municipalty

Damages from shelters

paint
 wood Doors
 doors accessories
 Door paint
 Elec sockets
 lighting fixtures
 Broken solar panel
 water closets
 floor Tiles

Safety

stairs size	120
windows at G.F with defence	no
protection of electrical works	no
Handrails	yes
fire extinguishers / Alarms/ smoke detectors	fire extinguishers are present at different locations
Directional signs	available

Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	


SITE PHOTOS:



Pic showing crack in the walls



View from inside the school



Lever handle and lock to door to be replaced and door to be painted



damage in doors needs t be fixed



pic showing the humidity in the walls



pic showing damage in walls



pic showing damage in the solar panel



damage in the ceiling


ASSESSMENT REPORT

STAGE A1

1636 - Al Beddaoui secondary school

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	1636 - Al Beddaoui secondary school				Date of visit :	06/07/2026
school Location	Village	Al Beddaoui	Caza	Tripoli	coordinations	34.451626 35.863750
School Principale name :	Hala Mousa			Phone No :	03 124397	

General Information :								
No of Class Room :	6	No Of Other Rooms:	1	No of Female Toilets	2	No of Male Toilets	1	
No of Blocks(Buildings)	1							
No of Floors	1 floor							
Estimate Total Built Area m2	570 m2							
No of Students :	100							
Location of shelter within the building :	all							
Handicap Facilities								
handicap ramp :	available		location		not available	x	space availability	x
Handicap toilet :	available		location		not available	x	space availability	x

visual structural condition					
Façade cracks	no		Location :		
Façade water leak	no		Location :		
wall Cracks	no		Location :		
Columns cracks	no		Location :		
Beams cracks	no		Location :		
Roof slab cracks	no		Location :		
Ground slab			Location :		
Repair assessment	Category 1	x	can be rehabilitated with minor Fixes and repairs		
	Category 2		need comprehensive rehabilitation including structural		

Note:

Environment			
Quality of water	quantity of water is not enough		
toilets capacity and quality	not enough		
drinking capacity	no drinking basin		
pollution	no		
play ground	available		
kids play ground			
humidity	no		
ventilation	good		
Gender separation in sanitation	no		
mobility to disabled	yes		
Env.health condition within school	some wc are leaking to the floors below		
waste disposal	available thru Municipality		
Damages from shelters			
Safety			
stairs size	130		
windows at G.F with defence	yes.		
protection of electrical works	yes.		
Handrails	yes.		
fire extinguishers / Alarms/ smoke detectors	yes.		
Directional signs	yes.		
Expected risks in repair works			
Access to school	Accessible		
permits			
schedule by contractor & Resources			
Labor working conditions	good		
repair with occupants inside			

Site Photos:



Damage of stairs



Sanitary ware in a bad condition



Tiles damage to be replaced



Pic showing the damage of the wooden doors



pic showing the vinyle



wooden board to be maintain



www.khatibalami.com