




Consultancy Services for
Tender Preparation and Construction Supervision Consultant for
Shelters
Lebanon Emergency Assistance Project (LEAP)

**ASSESSMENT REPORT
BATCH 2- LOT 1**

July 2026



BATCH 2 - LOT 1
MINYEH SCHOOLS
GENERAL INDEX

No.	SCHOOL NAME	
1	439	Al Minieh Blat mixed (المنية بلاط الرسمية المختلطة)
2	440	Al Minieh Blat Girls (المنية بلاط الرسمية للبنات)
3	449	Nabi Youchaa (النبي يوشع الرسمية المختلطة)
4	452	Nabi Kzayber (النبي كزبير الرسمية المختلطة)
5	453	Bhanin School (بحنين الرسمية المختلطة)
6	463	Harf Al Siyad (حرف السيد الرسمية المختلطة)
7	468	Mrah Al Sraj (مراح السراج المتوسطة الرسمية المختلطة)
8	477	Beit Al Faqs high school (ثانوية بيت الفقس الرسمية)
9	480	Korsayta mixed (قرصيتا الرسمية المختلطة)
10	481	Nemrine mixed (نمرين الرسمية المختلطة)
11	491	Syr mixed (تكميلية سير الرسمية المختلطة)
12	492	Morched Derbass (المربي مرشد درباس الرسمية المختلطة)
13	495	Bkarsouna second (بقرصونا الثانية الرسمية المختلطة)
14	496	Bkarsouna first (بقرصونا الأولى الرسمية المختلطة)
15	500	El Qattine mixed (القطين الرسمية المختلطة)
16	502	Btormaz mixed (بطرماز الرسمية المختلطة)
17	1336	Al Minieh mixed (المنية الرسمية المختلطة)
18	1384	Korsayta intermediate (متوسطة قرصيتا الرسمية الثانية)
19	1385	Rihaniyeh Minieh (الريحانية الرسمية المختلطة – المنية)
20	1546	Markabta (ثانوية مركبتا الرسمية)
21	1548	Taran (ثانوية طاران الرسمية)
22	1579	Baazkoun (بعزقون الرسمية المختلطة)
23	1586	Wissam Eid (ثانوية الشهيد الرائد وسام عيد الرسمية)

ASSESSMENT REPORT

STAGE A1

439-AI Minieh Blat Public mixed School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	439-Al Minieh Blat Public mixed School				Date of visit :		07/07/2026	
school Location	Village	Al Minieh	Caza	Denniyeh	coordinations	34.28098 35.56133		
School Principale name :	Siham zrayka			Phone No :	03 216895			
General Information :								
No of Class Room :	19	No Of Other Rooms:	5	No of Female Toilets	6			
				No of Male Toilets	8			
No of Blocks(Buildings)	2							
No of Floors	first block 1 floor and second block GF + mezanine + 1st + 2nd floor							
Estimate Total Built Area m2	1077 m2							
No of Students :	435							
Location of shelter within the building :			GF and 1st floor					
Handicap Facilities								
handicap ramp :	available	yes	location	GF	not available		space availability	
Handicap toilet :	available	yes	location	GF	not available		space availability	
visual structural condition								
Façade cracks	no				Location :			
Façade water leak	no				Location :			
wall Cracks	no				Location :			
Columns cracks	no				Location :			
Beams cracks	no				Location :			
Roof slab cracks	no				Location :			
Ground slab					Location :			
Repair assessment	Category 1	x	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					
Note:								

Environment			
Quality of water	Good		
toilets capacity and quality	nb of toilets is acceptable		
drinking capacity	enough for students		
pollution	no		
play ground	available		
kids play ground	available		
humidity	present in the school from windows and roof floor		
ventilation	good		
Gender separation in sanitation	no		
mobility to disabled	yes		
Env.health condition within school	some wc are leaking to the floors below		
waste disposal	available thru Municipality		
Damages from shelters			
Safety			
stairs size	130		
windows at G.F with defence	yes.		
protection of electrical works	yes.		
Handrails	yes.		
fire extinguishers / Alarms/ smoke detectors	yes.		
Directional signs	yes.		
Expected risks in repair works			
Access to school	Accessible		
permits			
schedule by contractor & Resources			
Labor working conditions	good		
repair with occupants inside			

Site Photos:



General view to school



General view to school



General view to school



Pic showing the bad condition of
WCs



pic showing the WC doors



Pic showing the bad condition of
steel door

ASSESSMENT REPORT

STAGE A1

440-Al Minieh Blat Public school for girls

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	440-Al Minieh Blat Public school for girls				Date of visit :		07/07/2026	
school Location	Village	El Minieh	Caza	Denniyeh	coordinations	34.28037 35.56274		
School Principale name :	Rania Hamdash			Phone No :	71 093000			
General Information :								
No of Class Room :	17	No Of Other Rooms:	5	No of Female Toilets	24			
				No of Male Toilets	0			
No of Blocks(Buildings)	1							
No of Floors	03 floors (ground+ first floors+ second floor)							
Estimate Total Built Area m2	1910 m2							
No of Students :	377							
Location of shelter within the building :	all the school except the administration offices							
Handicap Facilities								
handicap ramp :	available	yes	location	GF	not available		space availability	
Handicap toilet :	available	yes	location	GF	not available		space availability	
visual structural condition								
Façade cracks	no				Location :			
Façade water leak	minor around some windows				Location :			
wall Cracks	yes				Location :	external fence		
Columns cracks	no				Location :			
Beams cracks	yes				Location :	second floor		
Roof slab cracks	no				Location :			
Ground slab	no				Location :			
Repair assessment	Category 1	x	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					

Environment			
Quality of water	the water is polluted and undrinkable		
toilets capacity and quality	nb of toilets is enough for students		
drinking capacity	enough for students		
pollution	yes because of the waste containers located in front of main entrance school		
play ground	available		
kids play ground	available		
humidity	present in some areas at first floor between rooms and at the ground floor		
ventilation	good		
Gender separation in sanitation	yes		
mobility to disabled	no		
Env.health condition within school	Good		
waste disposal	available through Municipality		
Damages from shelters			
paint wood Doors doors accessories Door paint Elec sockets lighting fixtures Broken solar panel water closets floor Tiles			
Safety			
stairs size	1.5 m		
windows at G.F with defence	yes.		
protection of electrical works	yes.		
Handrails	yes.		
fire extinguishers / Alarms/ smoke detectors	no		
Directional signs	yes.		
Expected risks in repair works			
Access to school	Accessible		
permits			
schedule by contractor & Resources			
Labor working conditions	good		
repair with occupants inside			

SITE PHOTOS:



Pic showing beam crack at the second floor



Pic showing the leakage from the aluminum window



Lever handle and lock to door to be replaced and door to be rehabilitated



Pic showing the broken glass to be replaced



pic showing the humidity inside
the wall



pic showing the handle and lock
to be changed

ASSESSMENT REPORT

STAGE A1

449- AL Nabi Youshaa Public mixed School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	449- AL Nabi Youshaa Public mixed School				Date of visit :		07/07/2026	
school Location	Village	El Minieh	Caza	Denniyeh	coordinations	34.27471 35.56227		
School Principale name :	Ghazi Hallak			Phone No :	70 118798			
General Information :								
No of Class Room :	16	No Of Other Rooms:	5	No of Female Toilets	7			
				No of Male Toilets	6			
No of Blocks(Buildings)	1							
No of Floors	2 floor (ground+ first floor)							
Estimate Total Built Area m2	1800 m2							
No of Students :	323							
Location of shelter within the building :			ground and first floor					
Handicap Facilities								
handicap ramp :	available	X	location	GF	not available		space availability	
Handicap toilet :	available	X	location	GF	not available		space availability	
visual structural condition								
Façade cracks	no				Location :			
Façade water leak	no				Location :			
wall Cracks	no				Location :			
Columns cracks	no				Location :			
Beams cracks	no				Location :			
Roof slab cracks	no				Location :			
Ground slab	no				Location :			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					

Environment

Quality of water	Good and drinkable
toilets capacity and quality	nb of toilets is acceptable
drinking capacity	enough for students
pollution	yes because of the waste containers located in front of main entrance school
play ground	available
kids play ground	available
humidity	no humidity
ventilation	good
Gender separation in sanitation	yes
mobility to disabled	yes
Env.health condition within school	good
waste disposal	available thru Municipality

Damages from shelters

paint
 wood Doors
 doors accessories
 Door paint
 Elec sockets
 lighting fixtures
 water closets
 floor Tiles

Safety

stairs size	Safe
windows at G.F with defence	yes.
protection of electrical works	yes.
Handrails	yes.
fire extinguishers / Alarms/ smoke detectors	no
Directional signs	No

Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:



General View to school



Pic showing the over view of the
school



Solar panel in a good condition

ASSESSMENT REPORT

STAGE A1

452 - NabiKzayber public mixed school

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	452 - NabiKzayber public mixed school					Date of visit :		13/7/2026	
school Location	Village	El Minieh	Caza	Denniyeh		coordinations	34.4956246 35.9472056		
School Principale name :	Kawthar hussein			Phone No :	70 530170				
General Information :									
No of Class Room :	50	No Of Other Rooms:	26	No of Female Toilets		16			
				No of Male Toilets		26			
No of Blocks(Buildings)	2								
No of Floors	2 floors (GF + 1st)								
Estimate Total Built Area m2	1850 m2								
No of Students :	1164								
Location of shelter within the building :	all the school except the KG area								
Handicap Facilities									
handicap ramp :	available	yes	location	GF	not available		space availability		
Handicap toilet :	available	yes	location	GF	not available		space availability		
visual structural condition									
Façade cracks	yes				Location :	GF - 1st			
Façade water leak	yes				Location :	1st			
wall Cracks	yes				Location :	ground floor			
Columns cracks	no				Location :				
Beams cracks	yes				Location :	1st			
Roof slab cracks	no				Location :				
Ground slab	no				Location :				
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs						
	Category 2		need comprehensive rehabilitation including structural						

Environment

Quality of water	not drinkable
toilets capacity and quality	nb of toilets is enough fro students and it's newly rehabilitated
drinking capacity	enough for students
pollution	no pollution
play ground	available
kids play ground	not available
humidity	present in some areas at first floor between rooms
ventilation	good
Gender separation in sanitation	no
mobility to disabled	no
Env.health condition within school	Good
waste disposal	available thru Municipalty

Damages from shelters

paint
 wood Doors -
 doors accessories 2
 Door paint -
 Elec sockets -
 lighting fixtures 2
 Broken solar panel -
 water closets 2
 floor Tiles 2

Safety

stairs size	103
windows at G.F with defence	yes.
protection of electrical works	no
Handrails	yes.
fire extinguishers / Alarms/ smoke detectors	no
Directional signs	no

Expected risks in repair works

Access to school	Accessible
permits	yes
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

SITE PHOTOS:




Pic showing crackin the walls



View from inside the school



Lever handle and lock to door to be replaced and door to be painted



damage needs t be rehabilitated



pic showing the humidity inside the wall



crack showing from outside



Door damage



pic showing walls need to be painted


ASSESSMENT REPORT

STAGE A1

453 - Bhanin public mixed school

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE




Assessment Report stage A1

School Name:	453 - Bhanin public mixed school					Date of visit :		14/7/2026	
school Location	Village	Bhanin	Caza	Denniyeh	coordinations	34.4956246 35.9472056			
School Principale name :	Lina El Achrafi			Phone No :	76 858967				
General Information :									
No of Class Room :	12	No Of Other Rooms:	5	No of Female Toilets	5				
				No of Male Toilets	5				
No of Blocks(Buildings)	1								
No of Floors	2 floors (GF - 1st)								
Estimate Total Built Area m2	750								
No of Students :	225								
Location of shelter within the building :	all the school except the administration offices								
Handicap Facilities									
handicap ramp :	available		location		not available	X	space availability	No	
Handicap toilet :	available		location		not available	X	space availability	No	
visual structural condition									
Façade cracks	no				Location :				
Façade water leak	yes				Location :	GF - 1st			
wall Cracks	yes				Location :	GF			
Columns cracks	yes				Location :	GF - 1st			
Beams cracks	yes				Location :	1st			
Roof slab cracks					Location :				
Ground slab	no				Location :				
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs						
	Category 2		need comprehensive rehabilitation including structural						

Environment			
Quality of water	not drinkable		
toilets capacity and quality	nb of toilets is not enough for students and to be rehabilitated		
drinking capacity	not enough for students		
pollution	pollution		
play ground	available		
kids play ground	not available		
humidity	present in some areas at first floor between rooms		
ventilation	not good		
Gender separation in sanitation	yes		
mobility to disabled	no		
Env.health condition within school	Good		
waste disposal	available thru Municipality		
Damages from shelters			
paint wood Doors - doors accessories 2 Door paint - Elec sockets - lighting fixtures 2 Broken solar panel - water closets 2 floor Tiles 2			
Safety			
stairs size	110		
windows at G.F with defence	yes.		
protection of electrical works	no		
Handrails	yes.		
fire extinguishers / Alarms/ smoke detectors	no		
Directional signs	no		
Expected risks in repair works			
Access to school	Accessible		
permits	yes		
schedule by contractor & Resources			
Labor working conditions	very bad		
repair with occupants inside			

SITE PHOTOS:



Pic showing damage in the walls



View from outside the school



Lever handle and lock to door to be replaced and door to be painted



damage needs to be rehabilitated



pic showing the humidity inside the wall



crack in the walls



Door damage



Drinking basin damages



ASSESSMENT REPORT

STAGE A1

463- Harf Al Siyad public school

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE





**Assessment Report
stage A1**

School Name:	463- Harf Al Siyad public school					Date of visit :		16/07/2026	
school Location	Village	Harf Al Siyad	Caza	Denniyeh	coordinations	34.420325 36.021373			
School Principale name :	Dalal al Chami			Phone No :	70412949				
General Information :									
No of Class Room :	5	No Of Other Rooms:	5	No of Female Toilets	2				
				No of Male Toilets	2				
No of Blocks(Buildings)	1								
No of Floors	02 floors (ground+ first floors)								
Estimate Total Built Area m2	450 m2								
No of Students :	50								
Location of shelter within the building :	all the school except the administration offices								
Handicap Facilities									
handicap ramp :	available		location		not available	X	space availability	No	
Handicap toilet :	available		location		not available	X	space availability	No	
visual structural condition									
Façade cracks	yes				Location :	all			
Façade water leak	yes				Location :	all			
wall Cracks	yes				Location :	external fence			
Columns cracks	no				Location :				
Beams cracks	yes				Location :	first floor			
Roof slab cracks	no				Location :				
Ground slab	no				Location :				
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs						
	Category 2		need comprehensive rehabilitation including structural						

Environment			
Quality of water	not drinkable		
toilets capacity and quality	nb of toilets is enough for students and it's newly rehabilitated		
drinking capacity	enough for students		
pollution	yes because of the waste containers located in front of main entrance school		
play ground	available		
kids play ground	not available		
humidity	present in some areas at first floor between rooms		
ventilation	good		
Gender separation in sanitation	yes		
mobility to disabled	no		
Env.health condition within school	Good		
waste disposal	available thru Municipality		
Damages from shelters			
paint wood Doors doors accessories Door paint Elec sockets lighting fixtures Broken solar panel water closets floor Tiles			
Safety			
stairs size			
windows at G.F with defence	yes.		
protection of electrical works	yes.		
Handrails	yes.		
fire extinguishers / Alarms/ smoke detectors	fire extinguishers are present at different locations		
Directional signs	yes.		
Expected risks in repair works			
Access to school	Accessible		
permits			
schedule by contractor & Resources			
Labor working conditions	good		
repair with occupants inside			

SITE PHOTOS:



outside view of school



Humidity in wall



Lever handle and lock to door to
be replaced and door to be
painted



Electrical lighting to be changed



ceiling to be repaired



Humidity in ceiling



outdoor wall cracks



Stair to be rehabilitated


ASSESSMENT REPORT

STAGE A1

468-Marah El Sraj Public School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	468-Mrah El Sraj Public School					Date of visit :	07/07/2026		
school Location	Village	Mrah El Sraj	Caza	Al Minieh-Dennyeh	coordinations				
School Principale name :	Layla Mofdi			Phone No :	3819410				
General Information :									
No of Class Room :	25	No Of Other Rooms:	10	No of Female Toilets	6				
				No of Male Toilets	6				
No of Blocks(Buildings)	1								
No of Floors	03 floors (ground+ first+second)								
Estimate Total Built Area m2	1050								
No of Students :	690								
Location of shelter within the building :	all the school except the administration offices and service rooms								
Handicap Facilities									
handicap ramp :	available	yes	location	GF	not available		space availability		
Handicap toilet :	available	yes	location	GF	not available		space availability		
visual structural condition									
Façade cracks	YES				Location :	2ND			
Façade water leak	NO				Location :				
wall Cracks	YES				Location :	2ND			
Columns cracks	NO				Location :				
Beams cracks	YES				Location :	1ST			
Roof slab cracks	NO				Location :				
Ground slab	NO				Location :				
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs						
	Category 2		need comprehensive rehabilitation including structural						

Environment			
Quality of water	Good and drinkable		
toilets capacity and quality	nb of toilets isn't enough		
drinking capacity	enough for students		
pollution	no		
play ground	available		
kids play ground	available		
humidity	yes		
ventilation	good		
Gender separation in sanitation	yes		
mobility to disabled	gf		
Env.health condition within school	yes		
waste disposal	available		
Damages from shelters			
paint doors accessories door paint wash basin water closets mixers kitchen toilet finishing floor drain roof water proofing			
Safety			
stairs size	Safe		
windows at G.F with defence	yes		
protection of electrical works	no		
Handrails	safe		
fire extinguishers / Alarms/ smoke detectors	no		
Directional signs	no		
Expected risks in repair works			
Access to school	Accessible		
permits			
schedule by contractor & Resources			
Labor working conditions	good		
repair with occupants inside			

Site Photos:



broken glass



drinking basin situation



humidity in slab



cracks in wall



doors in wcs



cracks in wall



humidity in walls



inclined cracks in walls



water leakage in walls



wooden doors accessories



cracks in beams



elevation of school


ASSESSMENT REPORT

STAGE A1

477-Beit El-Faqs Secondary Public School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	477-Beit El-Faqs Secondary Public School				Date of visit :		16/07/2026	
school Location	Village	Beit El-Faqs	Caza	Al Minieh-Dennyeh	coordinations	34.3922222 36.0527778		
School Principale name :	عبدالفتاح عبدالقادر			Phone No :	3492807			
General Information :								
No of Class Room :	14	No Of Other Rooms:	8	No of Female Toilets	12			
				No of Male Toilets	12			
No of Blocks(Buildings)	1							
No of Floors	05 floors (bas+ground+ first+second+third)							
Estimate Total Built Area m2	1100							
No of Students :	275							
Location of shelter within the building :			all the school except the administration offices and service rooms					
Handicap Facilities								
handicap ramp :	available	no	location		not available	yes	space availability	gf
Handicap toilet :	available	no	location		not available	yes	space availability	gf
visual structural condition								
Façade cracks	NO				Location :			
Façade water leak	NO				Location :			
wall Cracks	YES				Location :	ALL		
Columns cracks	NO				Location :			
Beams cracks	NO				Location :			
Roof slab cracks	NO				Location :			
Ground slab	NO				Location :			
Repair assessment	Category1	X	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					

Environment		 KHATIB & ALAMI CONSOLIDATED ENGINEERING COMPANY S.A.L.	
Quality of water	good		
toilets capacity and quality	nb of toilets is enough		
drinking capacity	enough for students		
pollution	no		
play ground	available		
kids play ground	no		
humidity	present in the school from facade and roof floor		
ventilation	good		
Gender separation in sanitation	yes		
mobility to disabled	no		
Env.health condition within school	good		
waste disposal	available		
Damages from shelters			
paint wood doors metal doors doors accessories door paint elec sockets lighting fixtures wash basin water closets mixers kitchen toilet finishing floor drain lavatories countertop glazing roof water proofing			
Safety			
stairs size		Safe	
windows at G.F with defence		yes	
protection of electrical works		no	
Handrails		yes	
fire extinguishers / Alarms/ smoke detectors		no	
Directional signs		no	
Expected risks in repair works			
Access to school		Accessible	
permits			
schedule by contractor & Resources			
Labor working conditions		good	
repair with occupants inside			

Site Photos:



rear elevation of the school



playground needs repair in some place



bad connection of wastewater



concrete of ramp needs rehabilitation



most of curtains need
replacement



waterproofing membrane needs
repair in some place on the roof




hair cracks and humidity on the
façade



wc situation



humidity inside the school



some broken parts in stairs



water leakage in some rooms



inclined cracks in the walls




ASSESSMENT REPORT

STAGE A1

480-Qorsaita Public School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	480-Korsayta Public School				Date of visit :		07/07/2026	
school Location	Village	Korsayta	Caza	Al Minieh-Dennyeh	coordinations	34.3872042 36.0588559		
School Principale name :	Mohamad Issa			Phone No :	71031401			
General Information :								
No of Class Room :	13	No Of Other Rooms:	14	No of Female Toilets	4			
				No of Male Toilets	4			
No of Blocks(Buildings)	1							
No of Floors	04 floors (basement+ground+ first+second)							
Estimate Total Built Area m2	850							
No of Students :	168							
Location of shelter within the building :			all the school except the administration offices and service rooms					
Handicap Facilities								
handicap ramp :	available	No	location		not available	yes	space availability	GF
Handicap toilet :	available	No	location		not available	yes	space availability	GF
visual structural condition								
Façade cracks	NO				Location :			
Façade water leak	NO				Location :			
wall Cracks	YES				Location :	ALL		
Columns cracks	NO				Location :			
Beams cracks	NO				Location :			
Roof slab cracks	NO				Location :			
Ground slab	NO				Location :			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					

Environment

Quality of water	Good and drinkable
toilets capacity and quality	nb of toilets isn't enough
drinking capacity	not enough for students
pollution	no
play ground	available
kids play ground	no
humidity	present in the school from windows and roof floor
ventilation	good
Gender separation in sanitation	no
mobility to disabled	no
Env.health condition within school	some wc are leaking to the floors below
waste disposal	available

Damages from shelters

paint
 wood doors
 metal doors
 doors accessories
 door paint
 wash basin
 water closets
 mixers
 kitchen
 toilet finishing
 floor drain
 lavatories countertop
 glazing
 roof water proofing

Safety

stairs size	Safe
windows at G.F with defence	no
protection of electrical works	no
Handrails	no
fire extinguishers / Alarms/ smoke detectors	no
Directional signs	No


Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:



main elevation of the school



wc condition



wc wooden doors conditions



wc finishing conditions



drinking water conditions



cracks around windows



broken tiles in wc



humidity in classes



the playground needs safe steel
fence



the playground needs retaining
wall



bad installation of sanitation
pipes at wc



roof needs waterproofing system


ASSESSMENT REPORT

STAGE A1

481-Nemrin Public School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	481-Nemrin Public School				Date of visit :		07/07/2026	
school Location	Village	Nemrin	Caza	Al Minieh-Dennyeh	coordinations	34.3845278 36.0506389		
School Principale name :	Ahmad Hamoud			Phone No :	70495459			
General Information :								
No of Class Room :	11	No Of Other Rooms:	7	No of Female Toilets	6			
				No of Male Toilets	6			
No of Blocks(Buildings)	1							
No of Floors	03 floors (ground+ first+second)							
Estimate Total Built Area m2	600							
No of Students :	143							
Location of shelter within the building :	all the school except the administration offices and service rooms							
Handicap Facilities								
handicap ramp :	available	No	location		not available	yes	space availability	GF
Handicap toilet :	available	No	location		not available	yes	space availability	GF
visual structural condition								
Façade cracks	NO				Location :			
Façade water leak	YES				Location :	ALL		
wall Cracks	YES				Location :	ALL		
Columns cracks	NO				Location :			
Beams cracks	NO				Location :			
Roof slab cracks	NO				Location :			
Ground slab	NO				Location :			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					

Environment		 KHATIB & ALAMI CONSOLIDATED ENGINEERING COMPANY S.A.L.	
Quality of water	Good and drinkable		
toilets capacity and quality	nb of toilets is enough		
drinking capacity	enough for students		
pollution	no		
play ground	available		
kids play ground	no		
humidity	present in the school from windows and roof floor		
ventilation	good		
Gender separation in sanitation	yes		
mobility to disabled	no		
Env.health condition within school	good		
waste disposal	available		
Damages from shelters			
paint wood doors metal doors doors accessories door paint wash basin water closets mixers kitchen toilet finishing floor drain lavatories countertop glazing roof water proofing			
Safety			
stairs size		Safe	
windows at G.F with defence		yes	
protection of electrical works		no	
Handrails		yes	
fire extinguishers / Alarms/ smoke detectors		no	
Directional signs		no	
Expected risks in repair works			
Access to school		Accessible	
permits			
schedule by contractor & Resources			
Labor working conditions		good	
repair with occupants inside			

Site Photos:



main elevation of school



main elevation of school from
other side



stair and handrail situation



needs new lavatories or
countertop with all accessories



humidity at walls and especially
from west side



most of doors needs new
accessories



esbestos top roof suffers from
water leakage



broken glass for a main steel door
of first floor



driniking water situation



humidity at wcs and aluminum
windows



wcs without water sprayer



broken wooden door


ASSESSMENT REPORT

STAGE A1

491-Takmiliet Syr Mixed

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	491-Takmiliet Syr Mixed				Date of visit :		07/07/2026	
school Location	Village	Syr	Caza	Al Minieh-Dennyeh	coordinations	34.3864542 36.0330476		
School Principale name :	Rana Diab			Phone No :	71335044			
General Information :								
No of Class Room :	12	No Of Other Rooms:	5	No of Female Toilets	3			
				No of Male Toilets	3			
No of Blocks(Buildings)	1							
No of Floors	04 floors (BF+ground+ first+second)							
Estimate Total Built Area m2	750							
No of Students :	172							
Location of shelter within the building :	all the school except the administration offices and service rooms							
Handicap Facilities								
handicap ramp :	available	no	location		not available	yes	space availability	no
Handicap toilet :	available	no	location		not available	yes	space availability	no
visual structural condition								
Façade cracks	YES				Location :	ALL		
Façade water leak	YES				Location :	ALL		
wall Cracks	YES				Location :	ALL		
Columns cracks	NO				Location :			
Beams cracks	NO				Location :			
Roof slab cracks	NO				Location :			
Ground slab	NO				Location :			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					

Environment

Quality of water	Good and drinkable
toilets capacity and quality	nb of toilets isn't enough
drinking capacity	enough for students
pollution	no
play ground	available
kids play ground	no
humidity	present in the school from facade and roof floor
ventilation	good
Gender separation in sanitation	yes
mobility to disabled	no
Env.health condition within school	good
waste disposal	available

Damages from shelters

paint
 wood doors
 metal doors
 doors accessories
 door paint
 elec sockets
 lighting fixtures
 wash basin
 water closets
 mixers
 kitchen
 toilet finishing
 floor drain
 lavatories countertop
 glazing
 roof water proofing

Safety

stairs size	Safe
windows at G.F with defence	yes
protection of electrical works	no
Handrails	yes
fire extinguishers / Alarms/ smoke detectors	no
Directional signs	no

Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:




corroded steel at slab



humidity at wc slab



humidity at classes



kitchen mixer need replacement



wooden door need repair



wooden door needs accessories



leakage arround lighting fixtures



humidity and leakage in most of
walls



humidity at facades



facades need painting with
waterproofing



broken drinking water tap



broken door accessories at wc


ASSESSMENT REPORT

STAGE A1

492-Morched Derbass Public School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	492-Morched Derbass Public School					Date of visit :		07/07/2026	
school Location	Village	Syr	Caza	Al Minieh-Dennyeh	coordinations	34.3861944 36.0279722			
School Principale name :	Mountaser Hawshar			Phone No :	70951545				
General Information :									
No of Class Room :	14	No Of Other Rooms:	4	No of Female Toilets	3				
				No of Male Toilets	3				
No of Blocks(Buildings)	1								
No of Floors	03 floors (ground+ first+second)								
Estimate Total Built Area m2	1200								
No of Students :	500								
Location of shelter within the building :			all the school except the administration offices and service rooms						
Handicap Facilities									
handicap ramp :	available	yes	location	gf	not available		space availability		
Handicap toilet :	available	yes	location	gf	not available		space availability		
visual structural condition									
Façade cracks	YES				Location :	2nd			
Façade water leak	NO				Location :				
wall Cracks	YES				Location :	2nd			
Columns cracks	NO				Location :				
Beams cracks	NO				Location :				
Roof slab cracks	NO				Location :				
Ground slab	NO				Location :				
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs						
	Category 2		need comprehensive rehabilitation including structural						

Note: there is retaining wall for the playground of the school need consolidation works



Environment

Quality of water	Good and drinkable
toilets capacity and quality	nb of toilets isn't enough
drinking capacity	not enough for students
pollution	no
play ground	available
kids play ground	no
humidity	present in the school from facade and roof floor
ventilation	good
Gender separation in sanitation	yes
mobility to disabled	no
Env.health condition within school	good
waste disposal	available

Damages from shelters

paint
 wood doors
 metal doors
 doors accessories
 door paint
 elec sockets
 lighting fixtures
 wash basin
 water closets
 mixers
 kitchen
 toilet finishing
 floor drain
 lavatories countertop
 glazing
 roof water proofing

Safety

stairs size	Safe
windows at G.F with defence	no
protection of electrical works	no
Handrails	yes
fire extinguishers / Alarms/ smoke detectors	no
Directional signs	no

Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:



wooden door accessories



cracks in walls



humidity in rooms



inclined crack in wall



classes need painting



bad condition of electrical sockets



bad condition of electrical
installations



humidity in classes



water leakage in walls



bad conditions of painting



broken retaining wall



wooden door accessories


ASSESSMENT REPORT

STAGE A1

495-Bkarsouna Second Public School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	495-Bkarsouna Second Public School					Date of visit :	16/07/2026		
school Location	Village	Bkarsouna	Caza	Al Minieh-Dennyeh	coordinations	34.376828, 36.038577			
School Principale name :	Fatima Bakkour			Phone No :	70 567 623				
General Information :									
No of Class Room :	18	No Of Other Rooms:	4	No of Female Toilets	18				
				No of Male Toilets	18				
No of Blocks(Buildings)	1								
No of Floors	03 floors (ground+ first+second)								
Estimate Total Built Area m2	1500								
No of Students :	142								
Location of shelter within the building :	all the school except the administration offices and service rooms								
Handicap Facilities									
handicap ramp :	available	yes	location	GF	not available		space availability		
Handicap toilet :	available	yes	location	GF	not available		space availability		
visual structural condition									
Façade cracks	NO					Location :			
Façade water leak	NO					Location :			
wall Cracks	YES					Location :	ALL		
Columns cracks	NO					Location :			
Beams cracks	NO					Location :			
Roof slab cracks	NO					Location :			
Ground slab	NO					Location :			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs						
	Category 2		need comprehensive rehabilitation including structural						

Environment

Quality of water	good
toilets capacity and quality	nb of toilets is enough
drinking capacity	enough for students
pollution	no
play ground	available
kids play ground	available
humidity	present in the school from facade
ventilation	good
Gender separation in sanitation	yes
mobility to disabled	no
Env.health condition within school	good
waste disposal	available

Damages from shelters

paint
 wood doors
 metal doors
 doors accessories
 door paint
 elec sockets
 lighting fixtures
 water closets
 mixers
 glazing

Safety

stairs size	Safe
windows at G.F with defence	yes
protection of electrical works	no
Handrails	yes
fire extinguishers / Alarms/ smoke detectors	no
Directional signs	no

Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:




rear elevation of the school



Doors need repair




Humidity in the inside of the school




Stairs in good conditions




Steel protection for openings



waterproofing membrane needs repair in some place on the roof



Sink of the toilets



wc situation



Windows situation need some repair



Lighting Fixtures



Playground Situation



Steel gate Situation


ASSESSMENT REPORT

STAGE A1

496-Bkarsouna First Public School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	496-Bkarsouna First Public School				Date of visit :		18/07/2026	
school Location	Village	Bakarsouna	Caza	Al Minieh-Dennyeh	coordinations	34.3758056 36.0398611		
School Principale name :	Rouba Rifai			Phone No :	70179957			
General Information :								
No of Class Room :	19	No Of Other Rooms:	5	No of Female Toilets	6			
				No of Male Toilets	6			
No of Blocks(Buildings)	1							
No of Floors	03 floors (ground+ first+second)							
Estimate Total Built Area m2	1450							
No of Students :	341							
Location of shelter within the building :			all the school except the administration offices and service rooms					
Handicap Facilities								
handicap ramp :	available	no	location		not available	yes	space availability	gf
Handicap toilet :	available	no	location		not available	yes	space availability	gf
visual structural condition								
Façade cracks	YES				Location :	ALL		
Façade water leak	NO				Location :			
wall Cracks	YES				Location :	ALL		
Columns cracks	NO				Location :			
Beams cracks	NO				Location :			
Roof slab cracks	NO				Location :			
Ground slab	NO				Location :			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					

Environment

Quality of water	good
toilets capacity and quality	nb of toilets is enough
drinking capacity	enough for students
pollution	no
play ground	available
kids play ground	no
humidity	present in the school from facade and roof floor
ventilation	good
Gender separation in sanitation	yes
mobility to disabled	no
Env.health condition within school	good
waste disposal	available

Damages from shelters

paint
 wood doors
 metal doors
 doors accessories
 door paint
 elec sockets
 lighting fixtures
 wash basin
 water closets
 mixers
 kitchen
 toilet finishing
 floor drain
 lavatories countertop
 glazing
 roof water proofing

Safety

stairs size	GOOD
windows at G.F with defence	yes
protection of electrical works	no
Handrails	yes
fire extinguishers / Alarms/ smoke detectors	no
Directional signs	no

Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:



the fence needs rehabilitation



stair needs some repair for safety issues



steel corroded in slabs



cracks in fence



fence needs plastering



exposed steel in slabs



cracks in walls



cracks in façade



inclined cracks in walls



humidity on façade



humidity at walls



rear elevation of school

ASSESSMENT REPORT

STAGE A1

500-El Qattine Public School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	500-El Qattine Public School					Date of visit :	15/07/2026		
school Location	Village	El Qattine	Caza	Al Minieh-Dennyeh	coordinations	34.3976389 36.0238056			
School Principale name :	Ola Mariam			Phone No :	3105507				
General Information :									
No of Class Room :	16		No Of Other Rooms:	8		No of Female Toilets	9		
						No of Male Toilets	9		
No of Blocks(Buildings)	1								
No of Floors	03 floors (ground+ first+second)								
Estimate Total Built Area m2	1770								
No of Students :	300								
Location of shelter within the building :			all the school except the administration offices and service rooms						
Handicap Facilities									
handicap ramp :	available	no	location		not available		space availability	gf	
Handicap toilet :	available	no	location		not available		space availability	gf	
visual structural condition									
Façade cracks	NO					Location :			
Façade water leak	NO					Location :			
wall Cracks	YES					Location :	ALL		
Columns cracks	NO					Location :			
Beams cracks	NO					Location :			
Roof slab cracks	NO					Location :			
Ground slab	NO					Location :			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs						
	Category 2		need comprehensive rehabilitation including structural						

Environment

Quality of water	not good
toilets capacity and quality	nb of toilets is enough
drinking capacity	not enough for students
pollution	no
play ground	available
kids play ground	no
humidity	present in the school from facade and roof floor
ventilation	good
Gender separation in sanitation	yes
mobility to disabled	no
Env.health condition within school	good
waste disposal	available

Damages from shelters

paint
 wood doors
 metal doors
 doors accessories
 door paint
 elec sockets
 lighting fixtures
 wash basin
 water closets
 mixers
 kitchen
 toilet finishing
 floor drain
 lavatories countertop
 glazing
 roof water proofing

Safety

stairs size	Safe
windows at G.F with defence	yes
protection of electrical works	no
Handrails	yes
fire extinguishers / Alarms/ smoke detectors	no
Directional signs	no

Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:



turkish wc



lavatories in wc



inclined cracks



humidity in slab



needs paint



cracks between walls



needs paint



class without lighting fixtures



humidity from façade



rear elevation



main elevation



playground situation


ASSESSMENT REPORT

STAGE A1

502-Btermaz Public School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	502-Btermaz Public School					Date of visit : 16/07/2026	
school Location	Village	Btermaz	Caza	Al Minieh-Dennyeh	coordinations	34.4211944 36.0358611	
School Principale name :	Joumana Dannaoui			Phone No :	78954087		
General Information :							
No of Class Room :	16	No Of Other Rooms:	4	No of Female Toilets	5		
				No of Male Toilets	5		
No of Blocks(Buildings)	1						
No of Floors	03 floors (ground+ first+second)						
Estimate Total Built Area m2	650						
No of Students :	304						
Location of shelter within the building :	all the school except the administration offices and service rooms						
Handicap Facilities							
handicap ramp :	available	yes	location	GF	not available	space availability	
Handicap toilet :	available	yes	location	GF	not available	space availability	
visual structural condition							
Façade cracks	NO				Location :		
Façade water leak	NO				Location :		
wall Cracks	NO				Location :		
Columns cracks	NO				Location :		
Beams cracks	NO				Location :		
Roof slab cracks	NO				Location :		
Ground slab	NO				Location :		
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs				
	Category 2		need comprehensive rehabilitation including structural				

Environment

Quality of water	good
toilets capacity and quality	nb of toilets is enough
drinking capacity	enough for students
pollution	no
play ground	available
kids play ground	available
humidity	No
ventilation	good
Gender separation in sanitation	yes
mobility to disabled	no
Env.health condition within school	good
waste disposal	available

Damages from shelters

paint
 wood doors
 metal doors
 doors accessories
 door paint
 water closets
 mixers

Safety

stairs size	Safe
windows at G.F with defence	yes
protection of electrical works	no
Handrails	no
fire extinguishers / Alarms/ smoke detectors	no
Directional signs	no

Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:



rear elevation of the school



Humidity in the school



Lighting Fixtures



WC Situation




Kitchen Situation



Drinking Basin



Vinyl Situation



Protection for openings



Handicap WC Situation



Playground Situation



Ramp For Handicap



Stair Situation


ASSESSMENT REPORT

STAGE A1

1336- El Minieh Public mixed School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	1336- El Minieh Public mixed School				Date of visit :		15/07/2026	
school Location	Village	El Minieh	Caza	Denniyeh	coordinations	34.4719186 35.9399499		
School Principale name :	Layla Eid			Phone No :	03 490807			
General Information :								
No of Class Room :	27	No Of Other Rooms:	5	No of Female Toilets	4			
				No of Male Toilets	4			
No of Blocks(Buildings)	2							
No of Floors	block 1 - 2 floor (ground+ first floor) / block 1 - 2 floor (ground+ first floor)							
Estimate Total Built Area m2	940 m2							
No of Students :	741							
Location of shelter within the building :	block 1 (1st) / block 2 (Gf +1st)							
Handicap Facilities								
handicap ramp :	available		location		not available	x	space availability	yes
Handicap toilet :	available		location		not available	x	space availability	yes
visual structural condition								
Façade cracks	yes				Location :	block 2 1st		
Façade water leak	yes				Location :	block 2 1st		
wall Cracks	yes				Location :	block 2 1st		
Columns cracks					Location :			
Beams cracks					Location :			
Roof slab cracks					Location :			
Ground slab					Location :			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					

Environment			
Quality of water	not good		
toilets capacity and quality	nb of toilets is not enough		
drinking capacity	not enough for students		
pollution	yes		
play ground	available		
kids play ground	available		
humidity	no humidity		
ventilation	good		
Gender separation in sanitation	yes		
mobility to disabled	yes		
Env.health condition within school	good		
waste disposal	available thru Municipality		
Damages from shelters			
paint wood Doors doors accessories Door paint Elec sockets lighting fixtures water closets floor Tiles			
Safety			
stairs size	100		
windows at G.F with defence	yes.		
protection of electrical works	no		
Handrails	yes.		
fire extinguishers / Alarms/ smoke detectors	no		
Directional signs	No		
Expected risks in repair works			
Access to school	Accessible		
permits			
schedule by contractor & Resources			
Labor working conditions	good		
repair with occupants inside			

Site Photos:



General View to school



Pic showing the over view of the school



bad condition of wooden doors
to be rehabilitated



Pic showing the electrical DB in a very bad condition and not safe at all



Pic showing the lighting in the school



WC in a bad condition



General View to school



Pic showing the humidity inside the school



Wooden doors of WC in bad condition


ASSESSMENT REPORT

STAGE A1

1384-Korsayta Second Public School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	1384-Korsayta Second Public School				Date of visit :		16/07/2026	
school Location	Village	Korsayta	Caza	Al Minieh-Dennyeh	coordinations	34.3908056 36.0614444		
School Principale name :	Bassam Issa			Phone No :	76400586			
General Information :								
No of Class Room :	15	No Of Other Rooms:	9	No of Female Toilets	5			
				No of Male Toilets	5			
No of Blocks(Buildings)	1							
No of Floors	04 floors (ground+ first+second+third)							
Estimate Total Built Area m2	1050							
No of Students :	275							
Location of shelter within the building :	all the school except the administration offices and service rooms							
Handicap Facilities								
handicap ramp :	available	no	location		not available	yes	space availability	GF
Handicap toilet :	available	no	location		not available	yes	space availability	GF
visual structural condition								
Façade cracks	NO				Location :			
Façade water leak	NO				Location :			
wall Cracks	YES				Location :	ALL		
Columns cracks	NO				Location :			
Beams cracks	NO				Location :			
Roof slab cracks	NO				Location :			
Ground slab	NO				Location :			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					

Environment

Quality of water	good
toilets capacity and quality	nb of toilets isn't enough
drinking capacity	isn't enough for students
pollution	no
play ground	available
kids play ground	no
humidity	present in the school from facade
ventilation	good
Gender separation in sanitation	yes
mobility to disabled	no
Env.health condition within school	good
waste disposal	available

Damages from shelters

paint
 wood doors
 metal doors
 doors accessories
 door paint
 elec sockets
 lighting fixtures
 wash basin
 water closets
 mixers
 kitchen
 toilet finishing
 floor drain
 lavatories countertop
 aluminum
 glazing
 aluminum accessories
 roof waterproofing

Safety

stairs size	Safe
windows at G.F with defence	yes
protection of electrical works	no
Handrails	yes
fire extinguishers / Alarms/ smoke detectors	no
Directional signs	no

Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:



drinking basin needs replacement



wc wooden doors need
replacement



wc area needs covering by
sandwich panels slab



wc needs lavatories or wash
basins



wc need seats and replacement
of finishings



main elevation of school



availability for handicapped ramp



handrails needs some fixing
support



wooden doors need repainting



windows without glass



kitchen situation



humidity inside school


ASSESSMENT REPORT

STAGE A1

1385 -Al Rihaniyeh public school

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	1385 -Al -Rihaniyeh public school					Date of visit :		16/7/2026	
school Location	Village	Al Rihaniyeh	Caza	Al Minieh	coordinations	34.4907854 35.9714618			
School Principale name :	Samar hallak			Phone No :	70409302				
General Information :									
No of Class Room :	8	No Of Other Rooms:	4	No of Female Toilets	5				
				No of Male Toilets	6				
No of Blocks(Buildings)	1								
No of Floors	2 floors(ground floor+1st floor)								
Estimate Total Built Area m2	206 m2								
No of Students :	120								
Location of shelter within the building :	all the school except the administration offices								
Handicap Facilities									
handicap ramp :	available	NO	location		not available		space availability	yes	
Handicap toilet :	available	NO	location		not available		space availability	yes	
visual structural condition									
Façade cracks	no				Location :				
Façade water leak	no				Location :				
wall Cracks	yes				Location :	second floor			
Columns cracks	no				Location :				
Beams cracks	no				Location :				
Roof slab cracks	no				Location :				
Ground slab	no				Location :				
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs						
	Category 2		need comprehensive rehabilitation including structural						

Environment			
Quality of water	drinkable		
toilets capacity and quality	nb of toilets is enough fro students and it's newly rehabilitated		
drinking capacity	not enough for students		
polution	there's pollution		
play ground	available		
kids play ground	not available		
humidity	present in some areas at the ground floor		
ventilation	good		
Gender separation in sanitation	yes		
mobility to disabled	no		
Env.health condition within school	Good		
waste disposal	available thru Municipalty		
Damages from shelters			
paint wood Doors doors accessories Door paint Elec sockets lighting fixtures Broken solar panel water closets floor Tiles			
Safety			
stairs size	130		
windows at G.F with defence	no		
protection of electrical works	no		
Handrails	yes		
fire extinguishers / Alarms/ smoke detectors	fire extinguishers are present at different locations		
Directional signs	available		
Expected risks in repair works			
Access to school	Accessible		
permits			
schedule by contractor & Resources			
Labor working conditions	good		
repair with occupants inside			

SITE PHOTOS:



Pic showing crack in the walls



View from inside the school



Lever handle and lock to door to
be replaced and door to be
painted



damage in doors needs t be fixed



pic showing the humidity in the ceiling



pic showing the outdoor toilet




pic showing crack in the playground floor



crack in the playground walls



pic showing exposed electrical work



humidity in the classes



damage in the lamps



outdoor toilet


ASSESSMENT REPORT

STAGE A1

1546- Markabta public school

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	1546- Markabta public school					Date of visit : 18/7/2026	
school Location	Village	Markabta	Caza	Al Miniyeh	coordinations	34.4528425 35.9627376	
School Principale name :	George fajloun			Phone No :	3427496		
General Information :							
No of Class Room :	8	No Of Other Rooms:	3	No of Female Toilets	6		
				No of Male Toilets	5		
No of Blocks(Buildings)	1						
No of Floors	1 floor						
Estimate Total Built Area m2	650 m2						
No of Students :	103						
Location of shelter within the building :			all the school except the administration offices				
Handicap Facilities							
handicap ramp :	available	NO	location		not available		space availability
Handicap toilet :	available	NO	location		not available		space availability
							no
							no
visual structural condition							
Façade cracks	no				Location :		
Façade water leak	no				Location :		
wall Cracks	yes				Location :	first floor	
Columns cracks	no				Location :		
Beams cracks	no				Location :		
Roof slab cracks	no				Location :		
Ground slab	no				Location :		
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs				
	Category 2		need comprehensive rehabilitation including structural				

Environment			
Quality of water	drinkable		
toilets capacity and quality	nb of toilets is enough fro students and it's newly rehabilitated		
drinking capacity	not enough for students		
polution	there's pollution		
play ground	available		
kids play ground	not available		
humidity	present in some areas at the ground floor		
ventilation	good		
Gender separation in sanitation	yes		
mobility to disabled	no		
Env.health condition within school	Good		
waste disposal	available thru Municipalty		
Damages from shelters			
paint wood Doors doors accessories Door paint Elec sockets lighting fixtures Broken solar panel water closets floor Tiles			
Safety			
stairs size	120		
windows at G.F with defence	no		
protection of electrical works	yes		
Handrails	80 cm		
fire extinguishers / Alarms/ smoke detectors	fire extinguishers are present at different locations		
Directional signs	available		
Expected risks in repair works			
Access to school	Accessible		
permits			
schedule by contractor & Resources			
Labor working conditions	good		
repair with occupants inside			


SITE PHOTOS:



Pic showing crack in the walls



View from inside the school



Lever handle and lock to door to be replaced and door to be painted



damage in doors needs t be fixed



pic showing the humidity in the ceiling



crack in the tiles



exposed electrical work



damage in the walls


ASSESSMENT REPORT

STAGE A1

1548-Taran Secondary Public School

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	1548-Taran Secondary Public School				Date of visit : 16/07/2026	
school Location	Village	Taran	Caza	Al Minieh-Dennyeh	coordinations	34.4016731 36.0276400
School Principale name :	Hadya Trad		Phone No :	70165313		
General Information :						
No of Class Room :	9	No Of Other Rooms:	5	No of Female Toilets	6	
				No of Male Toilets	5	
No of Blocks(Buildings)	1					
No of Floors	04 floors (bas+ground+ first+second)					
Estimate Total Built Area m2	800					
No of Students :	115					
Location of shelter within the building :	all the school except the administration offices and service rooms					
Handicap Facilities						
handicap ramp :	available	no	location		not available	space availability
Handicap toilet :	available	no	location		not available	space availability
visual structural condition						
Façade cracks	NO				Location :	
Façade water leak	NO				Location :	
wall Cracks	NO				Location :	
Columns cracks	NO				Location :	
Beams cracks	NO				Location :	
Roof slab cracks	NO				Location :	
Ground slab	NO				Location :	
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs			
	Category 2		need comprehensive rehabilitation including structural			

Environment

Quality of water	good
toilets capacity and quality	nb of toilets is enough
drinking capacity	enough for students
pollution	no
play ground	available
kids play ground	No
humidity	YES
ventilation	good
Gender separation in sanitation	yes
mobility to disabled	no
Env.health condition within school	good
waste disposal	available

Damages from shelters

paint
 wood doors
 metal doors
 doors accessories
 door paint
 elec sockets
 lighting fixtures
 wash basin
 water closets
 mixers
 kitchen
 toilet finishing
 floor drain
 roof water proofing

Safety

stairs size	Safe
windows at G.F with defence	yes
protection of electrical works	no
Handrails	no
fire extinguishers / Alarms/ smoke detectors	no
Directional signs	no

Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

Site Photos:



rear elevation of the school



WC Situation




Internal Walls Situation



Missing Lighting Fixtures



Aluminum Partition need some repair



Kitchen Situation




Electrical Socket




Doors Situation




Drinking Basin



Playground Situation



Lighting Fixtures in the room



Steel Doors

ASSESSMENT REPORT

STAGE A1

1579 -Baazqoun public school

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	1579 -Baazqoun public school					Date of visit : 16/7/2026	
school Location	Village	Baazqoun	Caza	Al mniyeh	coordinations	34.381184, 35.951038	
School Principale name :	Ayman kaddour			Phone No :	3952782		
General Information :							
No of Class Room :	20		No Of Other Rooms:	5		No of Female Toilets	4
						No of Male Toilets	6
No of Blocks(Buildings)	1						
No of Floors	3 floors(basement+ground floor+1st floor)						
Estimate Total Built Area m2	800 m2						
No of Students :	452						
Location of shelter within the building :			all the school except the administration offices				
Handicap Facilities							
handicap ramp :	available	NO	location		not available		space availability yes
Handicap toilet :	available	NO	location		not available		space availability yes
visual structural condition							
Façade cracks	no				Location :		
Façade water leak	no				Location :		
wall Cracks	no				Location :		
Columns cracks	no				Location :		
Beams cracks	no				Location :		
Roof slab cracks	no				Location :		
Ground slab	no				Location :		
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs				
	Category 2		need comprehensive rehabilitation including structural				

Environment

Quality of water	drinkable
toilets capacity and quality	nb of toilets is enough fro students and it's newly rehabilitated
drinking capacity	not enough for students
pollution	there's pollution
play ground	available
kids play ground	not available
humidity	present in some areas at the ground floor
ventilation	good
Gender separation in sanitation	yes
mobility to disabled	no
Env.health condition within school	Good
waste disposal	available thru Municipalty

Damages from shelters

paint
 wood Doors
 doors accessories
 Door paint
 Elec sockets
 lighting fixtures
 Broken solar panel
 water closets
 floor Tiles

Safety

stairs size	130
windows at G.F with defence	no
protection of electrical works	no
Handrails	yes
fire extinguishers / Alarms/ smoke detectors	fire extinguishers are present at different locations
Directional signs	available

Expected risks in repair works

Access to school	Accessible
permits	
schedule by contractor & Resources	
Labor working conditions	good
repair with occupants inside	

SITE PHOTOS:



humidity in the classes



View from inside the school



pic showing the toilet



damage in doors needs t be fixed



pic showing exposed electrical work



pic showing inside the class



pic showing damage in the ceiling



roof need to be rehabilitated



Lever handle and lock to door to
be replaced and door to be
painted



pic showing the elevation



pic showing toilet situation



toilet need to be rehabilitated

ASSESSMENT REPORT

STAGE A1

1586 - Wissam Eid public secondary school

JULY 2026

SCHOOL LOCATION



SCHOOL ENTRANCE



Assessment Report stage A1

School Name:	1586 - Wissam Eid public secondary school				Date of visit :		13/7/2026	
school Location	Village	Al Minieh	Caza	Al Matn	coordinations	34.4956246 35.9472056		
School Principale name :	Saad katrib			Phone No :	71 772733			
General Information :								
No of Class Room :	12	No Of Other Rooms:	7	No of Female Toilets	5			
				No of Male Toilets	8			
No of Blocks(Buildings)	1							
No of Floors	3 floors (Basment (not accessible) + GF + 1st)							
Estimate Total Built Area m2	1200 m2							
No of Students :	276							
Location of shelter within the building :	all the school except the administration offices							
Handicap Facilities								
handicap ramp :	available	NO	location		not available	X	space availability	yes
Handicap toilet :	available	NO	location		not available	X	space availability	yes
visual structural condition								
Façade cracks	no				Location :			
Façade water leak	no				Location :			
wall Cracks	yes				Location :	ground floor - 1 st		
Columns cracks	yes				Location :	1st		
Beams cracks	no				Location :			
Roof slab cracks	no				Location :			
Ground slab	no				Location :			
Repair assessment	Category 1	X	can be rehabilitated with minor Fixes and repairs					
	Category 2		need comprehensive rehabilitation including structural					

Environment		 K.S.A.E. K.S.A.E. K.S.A.E. CONSOLIDATED ENGINEERING COMPANY S.A.L.	
Quality of water	not drinkable		
toilets capacity and quality	nb of toilets is enough fro students and it's newly rehabilitated		
drinking capacity	enough for students		
polution	no pollution		
play ground	available		
kids play ground	not available		
humidity	present in some areas at the ground floor		
ventilation	good		
Gender separation in sanitation	yes		
mobility to disabled	no		
Env.health condition within school	Good		
waste disposal	available thru Municipalty		
Damages from shelters			
paint wood Doors - doors accessories 2 Door paint - Elec sockets - lighting fixtures 2 Broken solar panel - water clostets 2 floor Tiles 2			
Safety			
stairs size	150		
windows at G.F with defence	yes.		
protection of electrical works	Electricity not enough for this school need solar panels		
Handrails	yes.		
fire extinguishers / Alarms/ smoke detectors	no		
Directional signs	no		
Expected risks in repair works			
Access to school	Accessible		
permits	yes		
schedule by contractor & Resources			
Labor working conditions	good		
repair with occupants inside			

SITE PHOTOS:



Pic showing crackin the walls



View from inside the school



Lever handle and lock to door to be replaced and door to be painted



damage needs to be rehabilitated



pic showing the humidity inside the wall



more cracks



Door damage



pic showing damage in the toilet