



**GRAND SERAIL**  
**(Government Palace)-Beirut**



**Annex III**  
**False Ceiling Schedule**  
**May 2022**








**ABDULWAHED CHEHAB**  
CONSULTING ENGINEERING OFFICE





### **Annex III:**


- 1. False Ceiling Types**
- 2. False Ceiling Schedule**

## **Annex III:**

- 1. False Ceiling Types**
- 2. False Ceiling Schedule**

Type	Description	Image	Room
Type 1a	PVC Panel 60x60 cm		2178
Type 1b	Perforated Metal 150 x 50 cm		B008 B009
Type 1c	Replacement of aluminum strips by aluminum Panel		
Type 2	Arabic Gypsum	 	1043
Type 3	Gypsum Board		2019a

Type 4	Arabic Gypsum with Wood		0034 0035
Type 5a	Strips Ceiling ( To be replaced by aluminum panel 60 x 60 cm)		
Type 5b	PVC Strips 25 cm		B128
Type 6a	Decorative Wood		2028

Type 6b	Decorative Wood Ceiling		1002
Type 6c	Decorative Wood Ceiling		0094A
Type 6d	Decorative Wood Ceiling		1003

### **Annex III:**

1. False Ceiling Types
2. False Ceiling Schedule

Room Nr.	Type	Damage (%)	Status	Windows Jamb's (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
Second Floor																
2001	Type 2		G									X				
2002	Type 2		G							X		X				
2003	Type 6		G			X										
2006	Type 2		G		X							X				
2007	Type 2		G		X							X				
2008	Type 2		G									X				
2010	Type 2		G		X							X	1	R		
2011	Type 2		G									X				
2016	Type 2		G		X							X				
2017	Type 4		G		X							X				
2018	Type 4		G		X							X				
2020	Type 1c		N													



Room Nr.	Type	Damage (%)	Status	Windows Jambes (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
2021	Type 1a	20%	R													
2022	Type 1c		N													
2023	Type 2		G		X							X				
2024	Type 2		G		X							X				
2027	Type 2		G									X				
2028	Type 6a	10%	R		X								1	N		
2030	Type 2		G									X				
2034	Type 2		G									X	1	R		
2035	Type 4		G						X			X				X
2036	Type 2		G									X				
2037	Type 2		G									X				
2038	Type 2		G									X				
2039	Type 2		G									X				
2046	Type 1c		N													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
2048	Type 6		G													
2049	Type 2		G									X				
2050	Type 6		G													
2052	Type 6		G						X			X				X
2054	Type 2		M									X				
2056	Type 2		G									X				
2057	Type 4		G					X				X				X
2058	Type 2		G									X				
2060	Type 2		G									X				
2061	Type 2		G									X				
2062	Type 2		G									X				
2063	Type 6		G			X										
2064	Type 2		G		X	X						X				
2065	Type 2		G		X							X				

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
2066	Type 1c		N													
2067	Type 1c		N													
2071	Type 2		G													
2073	Type 2	10%	R			X						X	1	R		
2074	Type 2		G									X				
2075	Type 2		G			X						X				
2002a	Type 2		G									X				
2047	Type 2		G									X				
2004 Hall	Type 2		G									X	1	R		
2005 Lobby	Type 2		G									X				
2009 WC	Type 2		G									X				
2012 WC	Type 2		G									X				
2013 Lobby	Type 2		G									X				
2014 Dressing	Type 2		G									X				

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
2015	Type 2		G									X				
2019	Type 3	5%	M	X								X				
2019a	Type 3	100%	N									X				
2025 Corrdior	Type 2	10%	R									X				
2026 Lobby	Type 2		G									X	1	R		
2029 Dressing	Type 2		G									X				
2031 Electrical Room			No F.C													
2032 & 2032a	Type 2		G									X	2	R		
2033 Lobby	Type 2		G									X				
2040 Dressing	Type 2		G									X				
2041 Wc	Type 2		G									X				
2042 Hall	Type 4		G									X				
2043 Lobby	Type 2		G									X				
2045	No F.C		No F.C													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
2047a	Type 2		G									X				
2051/a	Type 6		G													
2055 Wc	Type 2		G									X				
2056a	Type 2		G									X				
2059 WC	Type 2		G									X				
2068 Lobby	Type 2		G									X				
2069 & a Wc	Type 2		G									X				
2070 Corridor	Type 2		G									X				
2071a	Type 2		G									X				
2072 & 2072aWc	Type 2		G									X				

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
First Floor																
1001	Type 2		G									X				
1002	Type 6b		M													
1003	Type 6d	15%	R		X								1	R		
1005	Type 2		G		X							X				
1006	Type 2		G		X							X				
1007	Type 2		G									X				
1008	Type 2	50%	R									X				
1009	Type 2		G		X							X	1	R		
1010	Type 2		G									X				
1010a	Type 2		M									X	1	R		
1012	Type 6		G													
1013	Type 2		G		X				X			X				

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
1014	Type 4		G									X				
1017	Type 2		G									X	1	R		
1018	Type 2		G									X				
1019	Type 2		G									X	1	R		
1020	Type 2	20%	R									X				
1026	Type 2		G		X							X				
1027	Type 1c		N				10.80									
1028	Type 1c		N													
1029	Type 4		G		X							X	1	R		
1030	Type 2		G		X							X				
1004	Type 2		G									X				
1006a	Type 2		G									X				
1007a	Type 2		G		X							X				
1011& 1011a	Type 2		M									X	1	N		

Room Nr.	Type	Damage (%)	Status	Windows Jamb's (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
1012a	Type 2	40%	R									X	1	N		
1015 Lobby	Type 1c		N													
1018a	Type 2	20%	R									X	1	R		
1019a	Type 2		G									X				
1021	Type 2		G									X				
1022 Lobby	Type 2	50%	R									X				
1022a	Type 2	50%	R									X				
1024	Type 2	20%	R									X	1	N		
1025	Type 2	20%	R									X				
1026a	Type 6		G													
1016	Type 1c		N													



Room Nr.	Type	Damage (%)	Status	Windows Jamb's (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
Ground Floor																
0001	Type 4		G									X				
0002	Type 2	40%	R				8.16					X	1	R		
0003&0003a	Type 1c		N													
0005 Corridor	Type 4		G									X				
0006 (D9000)	Type 4		G		X							X				
0007	Type 2		G		X							X				
0007a	Type 2	20%	R		X							X				
0008 Lobby	Type 2	20%	R									X				
0009	Type 2	10%	R									X				
0009a	Type 2	100%	N									X				
0010	Type 2		G		X				X			X				
0011	Type 2		G									X				

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
0013	Type 2		G									X				
0014	Type 2		G									X	1	R		
0015	Type 2		G									X				
0016	Type 2		G									X	1	R		
0017 Hall	Type 2	20%	R								47.85	X				
0018	Type 2	20%	R									X	1	N		
0019	Type 4		G									X				
0020	Type 2	20%	R				4.08					X	1	N		
0022	Type 1c		N				16.32									
0022a	Type 1c		N													
0023	Type 1c		N													
0023a	Type 1c		N													
0024	Type 2	30%	R									X				
0025	Type 2	40%	R									X				

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
0026	Type 2	20%	R									X				
0027	Type 4		G		X							X				
0028			No F.C				4.32									
0029			No F.C													
0030	Type 1c		N				8.64									
0031	Type 2		G									X	1	R		
0032	Type 1c		N													
0033 Corridor	Type 2		G									X				
0034	Type 4	20%	R		X				X							X
0035	Type 4	20%	R		X				X							
0036 Lobby	Type 2		G									X				
0037	Type 2		G									X				
0037a	Type 2		G									X				
0037b	Type 2		G									X				

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
0038	Type 2		G									X				
0038a	Type 2	40%	R		X							X				
0038b	Type 2		G		X							X				
0039	Type 2	25%	R									X				
0039a	Type 2	20%	N	X								X				
0040	Type 2	15%	R				8.16					X	1	R		
0041&0041a	Type 1c		N													
0042	Type 2		G									X				

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
Basement																
B003			No F.C													
B004	Type 1c		N													
B005	Type 1c		N													
B006			No F.C													
B008 parking	Type 1b	20%	N													
B008 parking	Type 1b		R													
B009 Parking	Type 1b	10%	N													
B009A Lobby			G													
B010	Type 1a		G													
B011	Type 1c		N													
B012	Type 1a	30%	R													
B013	Type 1a		M													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
B014	Type 1c		N													
B015	Type 1a	40%	R													
B019 Hall	Type 2		G									X				
B019a			No F.C													
B019B	Type 1a	10%	R													
B020 Hall	Type 2		G									X				
B021	Type 1a	20%	R													
B022 Lobby	Type 2		G									X				
B023 Lobby	Type 2		G									X				
B024 WC	Type 2		M									X				
B025	Type 2		G									X				
B026	Type 2		G									X				
B027 Entrance	Type 2		M									X	1	R		
B028 gym	Type 2		G									X				

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
B029	Type 2		G									X	1	R		
B030	Type 2		G									X	1	R		
B031	Type 2		G									X				
B032 Dressing	Type 2		G									X				
B033	Type 1c		N													
B034	Type 2	60%	R									X				
B035	Type 2		G									X				
B036	Type 1c		N													
B037	Type 2	5%	M									X				
B038	Type 2		G									X				
B039	Type 2	15%	R									X				
B040	Type 2	80%	N									X				
B041	Type 1c		N													
B042	Type 2	30%	R									X				

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
B043	Type 2	30%	R									X				
B044	Type 1c		N										1	R		
B045	Type 2		G									X				
B046	Type 2		G									X				
B047	Type 2		G									X				
B048 gym	Type 2		G									X				
B049 gym	Type 1a		G													
B050	Type 1a	10%	R													
B051	Type 1a		G													
B052 wc	Type 1a		G													
B053 Bathroom	Type 1a		G													
B054 dressing	Type 1a		G													
B055	Type 1c		N													
B056	Type 1c		N													



Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
B057 Lobby service	Type 1c		N													
B059	Type 1c		N													
B060	Type 1c		N													
B060a	Type 1c		N													
B064	Type 1c		N													
B067	Type 1a	100%	N													
B068	Type 1a		N													
B069	Type 1a	20%	M													
B070	Type 1c		N													
B071	Type 1a	50%	R													
B072	Type 1c		N													
B073	No F.C		No F.C													
B074	No F.C		No F.C													
B075			Closed													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
B076	Type 1c		N													
B079	Type 1c		N													
B080	Type 1a	30%	R													
B081	Type 1c		N													
B082	Type 1a	100%	N													
B083	Type 1a		M													
B084	Type 1c		N													
B085	Type 1c		N													
B088	Type 1c		N													
B089	Type 1c		N													
B090 & B091	Type 1c		N													
B092	Type 1c		N													
B093	Type 1c		N													
B094	Type 1c		N													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
B096	Type 1c		N													
B097 Lobby	Type 1a		G													
B097	Type 1c		N													
B098	Type 1a	100%	N													
B098 ( Lobby)	Type 1c		N													
B077	No F.C		No F.C													
B100 Corr. Near B099	Type 1a	20%	R													
B099 room	Type 1a	10%	R													
B100 corridor Near room B109	Type 1a	25%	M													
B101	Type 1a		G													
B102	Type 1a	10%	R													
B103	Type 1a	5%	R													
B104	Type 1a		G													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
B105	Type 1c		N													
B106	Type 1c		N													
B107	Type 1a		G													
B108	Type 1a		G													
B109	Type 1a		G													
B110		25%	R													

(x) = Requires Works  
G= False Ceiling in Good Condition  
M= Maintenance  
R= Rehabilitation  
N = New False Ceiling  
N.FC= No False Ceiling Existing

Room Nr.	Type	Damage (%)	Status	Windows Jambes (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) (Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
Second Floor																
2077	Type 2		G									X				
2078	Type 2		G	X								X				
2079	Type 2		G									X				
2080	Type 2		G	X								X				
2081	Type 2		G									X				
2082	Type 2		G	X								X				
2083	Type 1c		N													
2084	Type 2	10%	R	X								X			X	
2085	Type 2	30%	R									X	X	N		
2086	Type 2		M	X								X				
2088	Type 2		G								X	X				
2089	Type 1c		N													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) (Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
2090			No F.C													
2171	Type 2		G									X				
2172	Type 1c		N													
2174	Type 1a		M						X							
2175	Type 1a	75%	R						X							
2176	Type 2		G						X			X				
2173A	Type 1a	100%	N	X												
2177	Type 1a		M						X							
2178	Type 1a	100%	N						X							
2179	Type 1c		N													
2180	Type 1c		N													
2182	Type 1c		N													
2183	Type 1c		N													
2184	Type 1a		N													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) (Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
2184b	Type 1a		N													
2187	Type 1a		M													
2188	Type 1a	100%	N						X							
2189	Type 1a		G													
2190	Type 1a		G	X												
2191	Type 1a	100%	N	X												
2192	Type 1a		G	X												
2193	Type 1a	100%	N						X							
2194	Type 1a	40%	R						X							
2195 WC	Type 1c		N													
2196	Type 1a	100%	N													
2197	Type 1a	50%	R													
2198	Type 1a		M													
2087 Wc	Type 2		G									X				

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) (Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
2181 Corridor	Type 2		M									X				
2181a	Type 2		G									X				
Stairs Private Lift	Type 2	50%	R				X		X			X				
ST11	Type 1a	100%	N													



Room Nr.	Type	Damage (%)	Status	Windows Jamb (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) (Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
First Floor																
1032	Type 1c		N													
1034	Type 2		G									X	X			
1035	Type 1a		M													
1036	Type 1a	100%	N													
1037	Type 2		G						X			X				
1038	Type 2		G									X				
1039	Type 2		G									X				
1040	Type 2	25%	R	X								X				
1041	Type 2	20%	R	X								X				
1042	Type 2		G									X				
1043	Type 2		N	X								X				
1044	Type 1a		M													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) (Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
1046	Type 2		G									X				
1047	Type 1a	60%	R													
1048	Type 1a	30%	R	X												
1051	Type 2	30%	R									X				
1147	Type 1a		G						X							
1148	Type 1a		G													
1157	Type 1c		N													
1158			No F.C													
1159	Type 1a	100%	N													
1160	Type 1a	25%	R						X							
1162	Type 1a		G						X							
1163	Type 1a	100%	N						X							
1164	Type 1c		N													
1165	Type 1c		N													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) (Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
1167	Type 1c		N													
1168	Type 1c		N													
1169	Type 1a	20%	N													
1170			No F.C													
1171			No F.C													
1169b	Type 1a	20%	N													
1172	Type 1a		G													
1173	Type 1a		M						X							
1174	Type 1a	100%	N													
1175	Type 1a		G													
1176	Type 1a	50%	R						X							
1177	Type 1a		G													
1178	Type 1a	20%	R						X							
1179	Type 1a	20%	R													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) (Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
1180	Type 1c		N													
1181	Type 1a		G													
1182	Type 1a	10%	R													
1183	Type 1a		G													
1031	Type 2		G								X	X	X	R		
1033	Type 2		G									X				
1161	Type 2	10%	R					X				X				
1166 Corridor	Type 2		G									X				
ST11			No F.C													
lobby 1156	Type 2		G									X				
1053	Type 2		G									X				
ST4			No F.C		X											

Room Nr.	Type	Damage (%)	Status	Windows Jambes (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) (Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
Ground Floor																
0043	Type 2		G								X	X	X	R		
0044	Type 2		G									X				
0045	Type 2		G									X	X	R		
0046	Type 2		G									X	X	R		
0047	Type 2		G									X				
0048	Type 4		G		X							X				
0049	Type 2		G									X				
0051	Type 1a	20%	R	X								X				
0052	Type 1c		N									X				
0054	Type 1a		G	X												
0057	Type 2		M									X	X	N		
0065	Type 2		G									X				

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) (Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
0133	Type 2	40%	R									X				
0137	Type 1a	100%	N													
0138	Type 1a	100%	N													
0140	Type 2		G									X				
0141	Type 2		G					X				X				X
0142	Type 1a		G					X				X				
0143	Type 1a	5%	R													
0144	Type 1c		N													
0145	Type 1c		N													
0146	Type 2		G									X				
0147	Type 1c		N													
0148	Type 1c		N													
0149	Type 1a		N													
0149a	Type 1a		N													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) (Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
0150			No F.C													
0151			No F.C	X												
0152	Type 1a	10%	R						X							
0153	Type 1a		M													
0154	Type 1a		G						X							
0155	Type 1a		G													
0156	Type 1a		G						X							
0157	Type 1a		G						X							
0158	Type 1a		G						X							
0159	Type 1c		N													
0160	Type 1a		G													
0161	Type 1a		G													
0162	Type 1a		G													
0163	Type 1a		G													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) (Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
ST 11			No F.C													
ST4 0049			No F.C		X											



Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) (Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
Basement																
B113 Delivery Bay	Type 1a	10%	R													
B113a	Type 1a	20%	R													
Lobby near B114	Type 1a	5%	R													
B114 security room			Closed													
B116	Type 1c		N													
B116a	Type 1c		N										X	N		
B117			Closed													
B118	Type 1a	100%	N													
B119			No F.C													
B119a			No F.C													
B120			Closed													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) (Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
B121	Type 1c		N													
B122	Type 1c		N													
B123	Type 1c		N													
B124	Type 2	20%	R						X			X				
B124a	Type 1a	100%	N													
B124b	Type 1a	50%	R													
B124 - Entrance Right	Type 2	100%	N						X			X				
B124 -Entrance Left	Type 2	100%	N						X			X				
B125	Type 2	40%	R									X	X	N		
B126	Type 2	10%	R									X	X	N		
B127	Type 2		G									X				
B128	Type 1c		N													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) (Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
B129	Type 2		G									X				
B130	Type 1a		G													
B130 Lobby	Type 1a	100%	N													
B132			No F.C													
B132c			No F.C													
B132d			No F.C													
B146	Type 1a		G													
B154 Corridor	Type 1a	5%	R													
B155			Closed													
B157			Closed													
B164	Type 1a		G													
B165	Type 1a	25%	R													
B167	Type 5b	20%	R													
B168	Type 5b	20%	R													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) (Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
B170			Closed													
B171	Type 1a		G													
B172			Closed													
B173	Type 1a		G													
B174			Closed													
B174a Corridor	Type 1a	40%	R													
B176	Type 1c		N													
B178 & B179	Type 5b	10%	R													
B180	Type 5b		M													

(x) = Requires Works  
G= False Ceiling in Good Condition  
M= Maintenance  
R= Rehabilitation  
N = New False Ceiling  
N.FC= No False Ceiling Existing

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
Second Floor																
2093	Type 2	10%	R									X				
2091	Type 1a	60%	R													
2094	Type 2		G						X			X	X	R		
2096	Type 2	10%	R									X				
2097	Type 2		N	X								X				
2098	Type 2	25%	R	X								X				
2099	Type 2	40%	R									X				
2100	Type 2		M	X								X				
2101	Type 2		G	X	X							X				
2103	Type 4		G			X						X				
2110	Type 1a	100%	N													
2111	Type 2		G									X				
2112	Type 2		G									X	X	R		

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
2113	Type 2		M									X				
2119	Type 2		G									X	X	R		
2117	Type 2		G									X				
2120	Type 2		G									X	X	R		
2121	Type 1a		G													
2122	Type 1a	100%	N						X							
2123	Type 1a		G													
2124	Type 1a		M													
2127	Type 1a		N													
2128	Type 2		G									X				
2129	Type 2		G									X				
2130	Type 2		G									X				
2131	Type 2		M									X	X	R		
2132	Type 2		M									X				

Room Nr.	Type	Damage (%)	Status	Windows Jambes (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
2133	Type 1a		M													
2134	Type 1a	35%	R	X												
2135	Type 1a		N													
2137	Type 1c		N													
2138	Type 1c		N													
2139			No F.C													
2139			No F.C													
2140			No F.C													
2140			No F.C													
2141	Type 1a		N													
2142	Type 1c		N													
2143	Type 1a		N													
2144	Type 1c		N													
2145	Type 1c		N													

Room Nr.	Type	Damage (%)	Status	Windows Jambes (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
2147	Type 1a		N													
2149	Type 1a		M													
2150	Type 1a		M	X												
2151	Type 1a		N													
2152	Type 1a		N													
2153	Type 1a		G	X												
2154	Type 1a		M	X												
2155	Type 1a		N													
2156	Type 1a		N													
2157	Type 1a		M													
2158	Type 1a		M	X												
2159	Type 1a		M													
2160	Type 1a		N													
2161	Type 1a	25%	R	X												



Room Nr.	Type	Damage (%)	Status	Windows Jamb's (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
2162	Type 1a	100%	N						X							
2164	Type 1a		N													
2165	Type 1a	30%	R	X												
2166	Type 1a	65%	R													
2167	Type 1a	45%	R													
2168	Type 1a		G													
2169	Type 1c		N													
2170	Type 1a		M	X												
2092 Corridor	Type 2		M									X				
2095 WC	Type 2	5%	R									X				
2102 Hall	Type 2		G									X				
2104 Hall	Type 2		G									X				
2105 wc	Type 2		G									X				
2106 wc	Type 2		G									X	X	R		

Room Nr.	Type	Damage (%)	Status	Windows Jams (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
2109	Type 2	10%	R									X	X	N		
2118	Type 2		N									X				
2115 & 2116	Type 1a		N						X							
2115A Pantry	Type 1c		N													
2126	Type 2	10%	R						X			X				
2128 Lobby	Type 2		G									X				
2163 Wc	Type 1c		N													
Corridor From 2125 -2146	Type 2	30%	R									X				
2114	Type 2		G									X				

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
First Floor																
1112	Type 1a		G													
1041	Type 2	20%	R	X								X				
1052	Type 2		M									X				
1054	Type 2		M									X				
1055	Type 2	65%	R	X								X				
1056	Type 2	80%	R	X								X	X	N		
1057	Type 1c		N													
1058	Type 2	70%	R	X								X				
1059 (1069 on door)	Type 1a	100%	N													
1061	Type 2	25%	R									X				
1062	Type 2	10%	R									X				
1063	Type 2	10%	R									X				
1064	Type 2	100%	N									X				

Room Nr.	Type	Damage (%)	Status	Windows Jambes (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
1065	Type 1c		N													
1067	Type 2		G									X				
1068	Type 2		G	X					X			X				
1069	Type 2	30%	R	X								X				
1070	Type 2	10%	R									X				
1074	Type 1a	100%	N													
1075	Type 1a	100%	N													
1076	Type 1a	50%	R	X												
1078			No F.C													
1079	Type 1a	100%	N													
1080	Type 1a	50%	R													
1081	Type 1a	30%	R						X							
1082	Type 1a	100%	N													
1083	Type 1a		G													

Room Nr.	Type	Damage (%)	Status	Windows Jambes (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
1084	Type 1a		G	X												
1085	Type 1a		G													
1086	Type 1a		G	X					X							
1088	Type 1c		N													
1091	Type 1a	100%	N													
1092	Type 1a		G													
1093	Type 1a	100%	N													
1094	Type 1c		N													
1095	Type 1a	40%	R													
1096	Type 1a		G													
1097	Type 1a	45%	R						X							
1098	Type 1a		M													
1100	Type 1a		G													
1101	Type 1a	100%	N													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
1102	Type 1a	100%	N													
1104	Type 1a		G													
1105	Type 1a	100%	N													
1106	Type 1a	100%	N													
1107	Type 1a		G						X							
1108	Type 1a		M	X												
1111	Type 1a	100%	N						X							
1112	Type 1a		G													
1113	Type 1a		G													
1114	Type 1a		G													
1115	Type 1a	10%	R	X												
1116	Type 1c		N													
1117	Type 1c		N													
1119	Type 1a	100%	N													

Room Nr.	Type	Damage (%)	Status	Windows Jambes (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
1120	Type 1a	100%	N						X							
1121	Type 1a	100%	N													
1122	Type 1a		G													
1123	Type 1a		G													
1124	Type 1c		N													
1125	Type 1c		N													
1126			No F.C													
1127	Type 1a	40%	R													
1128	Type 1a		G													
1129	Type 1a	20%	R	X												
1130	Type 1a		G	X												
1133	Type 1a	100%	N													
1134	Type 1a	100%	N	X												
1135	Type 1a	100%	N													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
1136	Type 1a	50%	R	X												
1137	Type 1a	100%	N													
1138	Type 1a		G	X												
1139	Type 1a		G	X												
1140	Type 1a		G													
1142	Type 1a	50%	R													
1143	Type 1a	100%	N	X												
1144	Type 1a	100%	N													
1145	Type 1a	25%	R													
1146	Type 1a	30%	R	X												
1149	Type 1a	100%	N													
1150	Type 1a	70%	R													
1151	Type 1a		G													
1152	Type 1a	100%	N													



Room Nr.	Type	Damage (%)	Status	Windows Jamb's (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
1153	Type 1a	100%	N													
1154	Type 1a	50%	R													
1155	Type 1a	70%	R						X							
1066 Lobby	Type 2		M									X				
1073(Corridor)	Type 2		M									X				
1077	Type 1c		N													
1087	Type 1a	15%	R													
1089	Type 2	15%	R									X			X	
1090	Type 2	25%	R						X			X				
1103	Type 1c		N													
1104a	Type 1a	5%	R													
1110	Type 2	80%	R						X			X				
1126a			No F.C									X				
1130a	Type 1a	100%	N	X								X				

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
1131	Type 1c		N													
1132	Type 1c		N													
Corridor 1050	Type 2	15%	R									X				
Corridor 1118	Type 2		M									X			X	
Corridor 1118b	Type 2		M									X			X	
Corridor 1118c	Type 2		M									X			X	
Fm200 (1060)	Type 1a	20%	R									X				
1099	Type 2	30%	R									X				
1094	Type 1a		M													
1141	Type 1a	20%	R						X							
1071	Type 2	100%	N	X								X				
1072	Type 2	50%	R	X				X				X				

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
Ground Floor																
0058	Type 2		M					X				X	X	N		
0058a	Type 2		G									X				
0059	Type 2	50%	R	X								X				
0059a	Type 2		G									X	X	R	X	
0060			No F.C													
0061	Type 1a		M	X												
0062	Type 1c		N													
0063	Type 1a	80%	R	X												
0064	Type 1c		N													
0066	Type 1c		N	X												
0067	Type 1a		N													
0069	Type 1a		N													
0070	Type 1a		N	X												

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
0071	Type 1a		N	X												
0072	Type 1a		G	X												
0073	Type 1c		N													
0074	Type 2		M									X	X	R	X	
0075	Type 1c		N													
0077	Type 1a	15%	R													
0078	Type 1a	25%	R													
0079	Type 1a	25%	R													
0080	Type 1a	100%	N													
0081			No F.C													
0082	Type 1a		G													
0083	Type 1a		M													
0084	Type 1a		G													
0085	Type 1a	30%	R													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
0086	Type 1a	30%	R													
0087	Type 2		M									X	X	N	X	
0088	Type 2		M						X			X	X	N		
0089	Type 1a	100%	N													
0090	Type 1a		M													
0091	Type 1a		M	X												
0092	Type 1a		M													
0093	Type 1a		G													
0094	Type 2		M									X	X	N		
0094a	Type 6c	20%	R													
0095	Type 1a		M	X												
0097	Type 1a		M	X												
0097a	Type 1c		N													
0098	Type 1c		N													

Room Nr.	Type	Damage (%)	Status	Windows Jambes (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
0099	Type 1a		M													
0100	Type 1a		M	X												
0100a	Type 1c		N													
0101	Type 1c		N													
0102	Type 1a		M													
0103 & 0103A	Type 1a	15%	M	X												
0104	Type 2	50%	R									X				
0105	Type 2		M									X			X	
0106	Type 2	45%	R						X			X				
0107	Type 1a	100%	N													
0108	Type 1a	100%	N													
0109	Type 1a		G													
0110	Type 1a	100%	N	X												
0111	Type 1a		G													

Room Nr.	Type	Damage (%)	Status	Windows Jambes (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
0112	Type 1c		N													
0113	Type 1a		M	X												
0114	Type 2		G									X				
0114a	Type 2		G									X				
0115	Type 1a	40%	R					X								
0116	Type 1a		G													
0117	Type 1a	100%	N													
0118	Type 1c		N													
0119	Type 1c		N													
0120			No F.C													
0122	Type 1a	100%	N													
0123			No F.C													
0124	Type 1a	100%	N													
0125	Type 1a	100%	N													

Room Nr.	Type	Damage (%)	Status	Windows Jambbs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
0126	Type 1c		N													
0127	Type 1c		N													
0128	Type 2	70%	R									X	X	N		
0129			No F.C		X											
0131	Type 2	20%	R									X				
0132	Type 2	10%	M									X				
0135	Type 1a	30%	M	X					X							
0136	Type 1a	20%	M													



Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
Basement																
B111	Type 1c		N													
B147	Type 1a	10%	R													
B149	Type 1a	10%	R													
B151 corridor	Type 1a	50%	R													
B152	Type 1a	100%	N													
B152 Lobby	Type 1a	100%	N													
B153	Type 1a	5%	R													
B154B Corrodor	Type 1a	30%	R													
B163	Type 1a	20%	M													
B183 & B184	Type 5b	50%	R													
B185	Type 5b		G													
B186	Type 5b	20%	M													

Room Nr.	Type	Damage (%)	Status	Windows Jambs (m2)				Wall (m2)				Paint (m2)	Access panel (60x60 cm)	Access panel Status	Gypsum Moulding Cornice (Similar to exisitng (LM)	Marble Skirting (lm) ( Similar to Existing)
				Double Glass for - Arabic Gypsum (m2)	Bullet Proof - Arabic Gypsum (m2)	Bullet Proof - Marbel (m2)	New Bullet Proof (m2)	Gypsum Board Wall (m2)	Arabic Gypsum (m2)	Rehab of Mosaic Tiles (m2)	Rehab of Granites					
B188	Type 1a		G													
B131				X												
ST9	No F.C		No F.C													

(x) = Requires Works  
G= False Ceiling in Good Condition  
M= Maintenance  
R= Rehabilitation  
N = New False Ceiling  
N.FC= No False Ceiling Existing