

**REPUBLIC OF LEBANON  
COUNCIL FOR DEVELOPMENT & RECONSTRUCTION**



**Lebanon Emergency Assistance Project  
(LEAP)**

**Rehabilitation of Schools–Shelters  
“LEAP-SH-SW-MEHE- Batch 1 (Lot 2)”**

**Assessment Report - Activity A2  
Schools Findings, Location Maps &  
Photographs**

Prepared By:

Ref. L2026-06  
August, 2026

---

# **Lebanon Emergency Assistance Project (LEAP)**

## **Tender Preparation and Construction Supervision For the Rehabilitation of Schools–Shelters**

---

### **Assessment Report - Activity A2**

---

#### **Schools Findings, Location Maps & Photographs**

---

##### **School Site Assessment Findings and Documentation**

Following the completion of the site assessment of all assigned schools, the findings and observations for each school are presented in the following sections. The purpose of this documentation is to provide a clear and comprehensive overview of the existing physical, structural, functional, and general condition of each school based on the site visits and visual assessments carried out by the assessment team.

For each assessed school, the information is organized systematically to facilitate identification of the school, understanding of its location and general characteristics, and evaluation of its current condition. The documentation for each school includes the school assessment sheet, location map, and photographic documentation.

The location map, obtained through Google Maps, provides a visual reference to the school's geographical position, while the photographs document the existing conditions observed during the site assessment and provide visual evidence supporting the findings recorded in the assessment sheet.

The assessment sheets are arranged according to the school serial number, allowing each school to be easily identified and cross-referenced with its corresponding maps and photographs. The following information is provided for each school:

##### **1. School Identification and Location Information**

The assessment starts with the basic identification details of the school, including:

- School serial number;
- School name;
- CERD number;
- Governorate and district;
- School location and geographical coordinates, including the X and Y coordinates.

The coordinates are provided to accurately identify the school's geographical location and facilitate its reference on the corresponding location map.

---

## **2. General School and Building Information**

General information regarding the school premises and its physical configuration is then provided. This includes the ownership status of the property, indicating whether the school building is owned or rented, as well as the number of building blocks, number of floors, and number of classrooms within the premises.

This information is important for understanding the overall size and configuration of the school and for establishing the context in which the technical condition of the buildings and facilities has been assessed.

## **3. School Administration and Contact Information**

The name of the school director or responsible administrator is recorded together with the available telephone number or other contact details. This information provides a reference for communication and, where necessary, for clarification of specific observations or issues identified during the assessment.

## **4. Technical Assessment of the Existing Condition**

A detailed description of the technical condition of the school is provided based on the visual assessment undertaken during the site visit. The assessment considers the observable condition of the main building components and facilities, as applicable, including the general condition of the buildings, structural elements, roofs, walls, floors, doors and windows, electrical and plumbing installations, sanitary facilities, water supply and drainage systems, and other relevant school infrastructure.

The assessment is primarily based on visual inspection and observations made during the site visit. It is intended to document visible defects, deterioration, deficiencies, damage, maintenance requirements, and other conditions that may affect the functionality, safety, usability, or overall condition of the school facilities. Where relevant, the findings are supported by photographs included in the school documentation.

## **5. Special Remarks and Observations**

At the end of each assessment sheet, special remarks and observations are provided to record specific conditions or issues that require particular attention. These remarks may include unusual site conditions, significant defects, accessibility concerns, urgent maintenance requirements, restrictions encountered during the assessment, or other observations that may not be fully reflected in the standard assessment categories.

## **School List**

The following table presents the list of schools, including the serial number, school name, CERD number, and governorate/district location.

**LEAP-SH-SW-MEHE- Batch 1**  
**Lot 2 – Akkar Governorate (23 Schools)**

| School No. | School Name                                                                       | CERD No. | Governorate / District |
|------------|-----------------------------------------------------------------------------------|----------|------------------------|
| 2          | Al Rihanieh Mixed Public School<br>مدرسة الريحانية الرسمية المختلطة عكار          | 511      | Akkar                  |
| 5          | Al Masoudieh Mixed Public School<br>مدرسة المسعودية الرسمية المختلطة              | 516      | Akkar                  |
| 6          | Tel Maayan Mixed Public School<br>مدرسة تلمعيان الرسمية المختلطة                  | 518      | Akkar                  |
| 7          | Kolayaat Mixed Public School<br>مدرسة القليعات الرسمية المختلطة                   | 519      | Akkar                  |
| 13         | Hekr El Hawshab Mixed Public School<br>مدرسة حكر الحوشب الرسمية المختلطة          | 527      | Akkar                  |
| 14         | Halba Secondary Public School<br>ثانوية حلبا الرسمية                              | 530      | Akkar                  |
| 15         | Khraibit El Jindi Mixed Public School<br>مدرسة خريبة الجندي الرسمية المختلطة      | 536      | Akkar                  |
| 16         | Jdeidat El Jouma Elementary Public School<br>مدرسة جديده الجومة التكميلية الرسمية | 539      | Akkar                  |
| 17         | El Hakour Public School<br>مدرسة الحاكور الرسمية                                  | 546      | Akkar                  |
| 18         | Bkarzela Mixed Public School<br>مدرسة بقرزلا الرسمية المختلطة                     | 547      | Akkar                  |
| 19         | Zouk El Habasela Mixed Public School<br>ذوق الحبالصة الرسمية المختلطة             | 551      | Akkar                  |
| 20         | Majdala Mixed Public School<br>مدرسة مجدلا الرسمية المختلطة                       | 552      | Akkar                  |
| 23         | Burj Al Arab Mixed Public School<br>مدرسة برج العرب الرسمية المختلطة              | 559      | Akkar                  |
| 34         | EL Souweisa Mixed Public School<br>مدرسة السويصة الرسمية المختلطة                 | 593      | Akkar                  |
| 35         | Rahbeh Public School - Girls<br>مدرسة رحبة الرسمية للبنات                         | 595      | Akkar                  |
| 36         | Daher El Laysineh Mixed Public School<br>مدرسة ضهر الليسينه الرسمية المختلطة      | 597      | Akkar                  |
| 37         | Al Ouyoun Secondary Public School<br>ثانوية العيون الرسمية                        | 603      | Akkar                  |
| 38         | Beino Mixed Public School<br>مدرسة بينو الرسمية المختلطة                          | 606      | Akkar                  |
| 39         | Bazbina Mixed Public School<br>مدرسة بزبينا الرسمية المختلطة                      | 608      | Akkar                  |
| 40         | Akkar El Atila Public School<br>ثانوية عكار العتيقة الرسمية                       | 616      | Akkar                  |
| 41         | Mrahat Akkar Mixed Public School<br>مدرسة مراحات عكار الرسمية المختلطة            | 617      | Akkar                  |
| 60         | Ayat Public School<br>متوسطة عيات الرسمية                                         | 1489     | Akkar                  |
| 69         | EL Hseinah Public School<br>مدرسة الحصنية الرسمية                                 | 1623     | Akkar                  |

| School No. | School Name                                                              | CERD No. | Governorate / District |
|------------|--------------------------------------------------------------------------|----------|------------------------|
| 2          | Al Rihanieh Mixed Public School<br>مدرسة الريحانية الرسمية المختلطة عكار | 511      | Akkar                  |

|                  |            |            |
|------------------|------------|------------|
| School Location: | X          | Y          |
|                  | 34.5837046 | 36.1176783 |

|                     |                |        |                    |    |
|---------------------|----------------|--------|--------------------|----|
| School Information: | Owned          | Rented | No. of Blocks:     | 1  |
|                     | ✓ (Gift)       |        |                    |    |
|                     | No. of Floors: | 2      | No. of Classrooms: | 12 |

|                            |                          |             |           |
|----------------------------|--------------------------|-------------|-----------|
| Director Name and Contact: | Suzan Mohamad Al Mohamad | - Landline: | 06-845273 |
|                            |                          | - Mobile:   | 81-647712 |

Building Condition: Category **1**

|                       |     |    |          |           |           |
|-----------------------|-----|----|----------|-----------|-----------|
| Roof Heat Insulation: | Yes | No | Comments | Condition |           |
|                       |     | ✓  |          | Good      | To Repair |

|                     |     |    |          |           |           |
|---------------------|-----|----|----------|-----------|-----------|
| Roof Waterproofing: | Yes | No | Comments | Condition |           |
|                     | ✓   |    |          | Good      | To Repair |

|                                    |     |    |          |           |           |
|------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Parapet at Roof Floor: | Yes | No | Comments | Condition |           |
|                                    | ✓   |    |          | Good      | To Repair |

|                                        |     |    |          |           |           |
|----------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Ramp at GF level: | Yes | No | Comments | Condition |           |
|                                        |     | ✓  |          | Good      | To Repair |

|                              |     |    |          |           |           |
|------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Toilet: | Yes | No | Comments | Condition |           |
|                              |     | ✓  |          | Good      | To Repair |

|             |     |    |          |           |           |
|-------------|-----|----|----------|-----------|-----------|
| Playground: | Yes | No | Comments | Condition |           |
|             | ✓   |    |          | Good      | To Repair |

|                                     |     |    |                                                                                   |           |           |
|-------------------------------------|-----|----|-----------------------------------------------------------------------------------|-----------|-----------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments                                                                          | Condition |           |
|                                     | ✓   |    | Type: Resin                                                                       | Good      | To Repair |
|                                     |     |    |                                                                                   | ✓         |           |
| <b>External Main Gate:</b>          | Yes | No | Comments                                                                          | Condition |           |
|                                     | ✓   |    |                                                                                   | Good      | To Repair |
|                                     |     |    |                                                                                   |           | ✓         |
| <b>Internal Main Gate:</b>          | Yes | No | Comments                                                                          | Condition |           |
|                                     | ✓   |    | Installation of a protective metal gate is required (There is Only a Wooden door) | Good      | To Repair |
|                                     |     |    |                                                                                   |           | ✓         |
| <b>Shed:</b>                        | Yes | No | Comments                                                                          | Condition |           |
|                                     | ✓   |    | Type: Steel                                                                       | Good      | To Repair |
|                                     |     |    |                                                                                   | ✓         |           |
| <b>Rain Water System:</b>           | Yes | No | Comments                                                                          | Condition |           |
|                                     | ✓   |    | Pipe causing problems                                                             | Good      | To Repair |
|                                     |     |    |                                                                                   |           | ✓         |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments                                                                          | Condition |           |
|                                     | ✓   |    | Bad Smell                                                                         | Good      | To Repair |
|                                     |     |    |                                                                                   |           | ✓         |
| <b>Electrical System:</b>           | Yes | No | Comments                                                                          | Condition |           |
|                                     | ✓   |    |                                                                                   | Good      | To Repair |
|                                     |     |    |                                                                                   | ✓         |           |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments                                                                          | Condition |           |
|                                     | ✓   |    |                                                                                   | Good      | To Repair |
|                                     |     |    |                                                                                   | ✓         |           |
| <b>Source of Electricity:</b>       | EDL |    | Generator                                                                         | Condition |           |
|                                     | No  |    | No                                                                                | Good      | To Repair |
|                                     |     |    |                                                                                   |           |           |

**Remarks:**

The school, which is owned by the Lebanese Republic, was renovated by the Swiss Embassy in 2019 and was subsequently used as a shelter for displaced persons.

Based on the current visual assessment, the building requires only light rehabilitation works, with no structural intervention identified. Accordingly, the school is classified as **Category 1** under the current project.

| School No. | School Name                                                              | CERD No. | Governorate / District |
|------------|--------------------------------------------------------------------------|----------|------------------------|
| 2          | Al Rihanieh Mixed Public School<br>مدرسة الريحانية الرسمية المختلطة عكار | 511      | Akkar                  |



| School No. | School Name                                                              | CERD No. | Governorate / District |
|------------|--------------------------------------------------------------------------|----------|------------------------|
| 2          | Al Rihanieh Mixed Public School<br>مدرسة الريحانية الرسمية المختلطة عكار | 511      | Akkar                  |



| School No. | School Name                                                          | CERD No. | Governorate / District |
|------------|----------------------------------------------------------------------|----------|------------------------|
| 5          | Al Masoudieh Mixed Public School<br>مدرسة المسعودية الرسمية المختلطة | 516      | Akkar                  |

|                  |            |            |
|------------------|------------|------------|
| School Location: | X          | Y          |
|                  | 34.6056588 | 36.0511192 |

|                     |                |        |                    |    |
|---------------------|----------------|--------|--------------------|----|
| School Information: | Owned          | Rented | No. of Blocks:     | 1  |
|                     | ✓ (Gift)       |        |                    |    |
|                     | No. of Floors: | 3      | No. of Classrooms: | 18 |

|                            |               |             |           |
|----------------------------|---------------|-------------|-----------|
| Director Name and Contact: | Mohamad Rajab | - Landline: | 06-810161 |
|                            |               | - Mobile:   | 03-698345 |

Building Condition: Category **1**

|                       |     |    |          |           |           |
|-----------------------|-----|----|----------|-----------|-----------|
| Roof Heat Insulation: | Yes | No | Comments | Condition |           |
|                       |     | ✓  |          | Good      | To Repair |

|                     |     |    |          |           |           |
|---------------------|-----|----|----------|-----------|-----------|
| Roof Waterproofing: | Yes | No | Comments | Condition |           |
|                     |     | ✓  |          | Good      | To Repair |

|                                    |     |    |          |           |           |
|------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Parapet at Roof Floor: | Yes | No | Comments | Condition |           |
|                                    | ✓   |    |          | Good      | To Repair |
|                                    |     |    |          | ✓         |           |

|                                        |     |    |          |           |           |
|----------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Ramp at GF level: | Yes | No | Comments | Condition |           |
|                                        |     | ✓  |          | Good      | To Repair |
|                                        |     |    |          |           |           |

|                              |     |    |          |           |           |
|------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Toilet: | Yes | No | Comments | Condition |           |
|                              | ✓   |    |          | Good      | To Repair |
|                              |     |    |          | ✓         |           |

|             |     |    |                |           |           |
|-------------|-----|----|----------------|-----------|-----------|
| Playground: | Yes | No | Comments       | Condition |           |
|             | ✓   |    | Type: Concrete | Good      | To Repair |
|             |     |    |                | ✓         |           |

**Drinking Fountain:**

| Yes | No | Comments    |
|-----|----|-------------|
| ✓   |    | Type: Tiles |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**External Main Gate:**

| Yes | No | Comments    |
|-----|----|-------------|
| ✓   |    | Type: Steel |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**Internal Main Gate:**

| Yes | No | Comments    |
|-----|----|-------------|
| ✓   |    | Type: Steel |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**Shed:**

| Yes | No | Comments   |
|-----|----|------------|
| ✓   |    | Type: Zinc |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**Rain Water System:**

| Yes | No | Comments |
|-----|----|----------|
| ✓   |    |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**Waste Water Drainage System:**

| Yes | No | Comments |
|-----|----|----------|
| ✓   |    |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**Electrical System:**

| Yes | No | Comments |
|-----|----|----------|
| ✓   |    |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**PV Solar Panel at Roof:**

| Yes | No | Comments |
|-----|----|----------|
|     | ✓  |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**Source of Electricity:**

| EDL | Generator |
|-----|-----------|
| No  | ✓         |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |


**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                                          | CERD No. | Governorate / District |
|------------|----------------------------------------------------------------------|----------|------------------------|
| 5          | Al Masoudieh Mixed Public School<br>مدرسة المسعودية الرسمية المختلطة | 516      | Akkar                  |



| School No. | School Name                                                          | CERD No. | Governorate / District |
|------------|----------------------------------------------------------------------|----------|------------------------|
| 5          | Al Masoudieh Mixed Public School<br>مدرسة المسعودية الرسمية المختلطة | 516      | Akkar                  |



| School No. | School Name                                                      | CERD No. | Governorate / District |
|------------|------------------------------------------------------------------|----------|------------------------|
| 6          | Tel Maayan Mixed Public School<br>مدرسة تلمعيان المختلطة الرسمية | 518      | Akkar                  |

|                  |            |            |
|------------------|------------|------------|
| School Location: | X          | Y          |
|                  | 34.6001997 | 36.0362108 |

|                     |             |                    |                |   |
|---------------------|-------------|--------------------|----------------|---|
| School Information: | Owned       | Rented             | No. of Blocks: | 3 |
|                     | ✓ (Gift)    |                    |                |   |
| No. of Floors:      | A:3,B:3,C:1 | No. of Classrooms: | 25             |   |

|                            |                     |             |           |
|----------------------------|---------------------|-------------|-----------|
| Director Name and Contact: | Kawkab Ali Al Masri | - Landline: | 06-810714 |
|                            |                     | - Mobile:   | 76-546248 |

Building Condition: Category **1**

|                                        |     |    |                |           |           |
|----------------------------------------|-----|----|----------------|-----------|-----------|
| Roof Heat Insulation:                  | Yes | No | Comments       | Condition |           |
|                                        | ✓   |    | Damaged        | Good      | To Repair |
| Roof Waterproofing:                    | Yes | No | Comments       | Condition |           |
|                                        | ✓   |    | Type: SBS      | Good      | To Repair |
| Presence of Parapet at Roof Floor:     | Yes | No | Comments       | Condition |           |
|                                        | ✓   |    |                | Good      | To Repair |
| Presence of Handicap Ramp at GF level: | Yes | No | Comments       | Condition |           |
|                                        | ✓   |    |                | Good      | To Repair |
| Presence of Handicap Toilet:           | Yes | No | Comments       | Condition |           |
|                                        | ✓   |    |                | Good      | To Repair |
| Playground:                            | Yes | No | Comments       | Condition |           |
|                                        | ✓   |    | Type: Concrete | Good      | To Repair |

|                                     |     |    |                                                                                     |           |                |
|-------------------------------------|-----|----|-------------------------------------------------------------------------------------|-----------|----------------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments                                                                            | Condition |                |
|                                     | ✓   |    | Type: Tiles                                                                         | Good<br>✓ | To Repair      |
| <b>External Main Gate:</b>          | Yes | No | Comments                                                                            | Condition |                |
|                                     | ✓   |    | Type: Steel                                                                         | Good      | To Repair<br>✓ |
| <b>Internal Main Gate:</b>          | Yes | No | Comments                                                                            | Condition |                |
|                                     | ✓   |    | Type: Steel                                                                         | Good      | To Repair<br>✓ |
| <b>Shed:</b>                        | Yes | No | Comments                                                                            | Condition |                |
|                                     | ✓   |    | Type:                                                                               | Good<br>✓ | To Repair      |
| <b>Rain Water System:</b>           | Yes | No | Comments                                                                            | Condition |                |
|                                     | ✓   |    | There is water leakage (seepage into the walls from an internal pipe) in B1 and B2. | Good      | To Repair<br>✓ |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments                                                                            | Condition |                |
|                                     | ✓   |    |                                                                                     | Good<br>✓ | To Repair      |
| <b>Electrical System:</b>           | Yes | No | Comments                                                                            | Condition |                |
|                                     | ✓   |    |                                                                                     | Good<br>✓ | To Repair      |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments                                                                            | Condition |                |
|                                     | ✓   |    |                                                                                     | Good<br>✓ | To Repair      |
| <b>Source of Electricity:</b>       | EDL |    | Generator                                                                           | Condition |                |
|                                     | ✓   |    | ✓                                                                                   | Good<br>✓ | To Repair      |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                                      | CERD No. | Governorate / District |
|------------|------------------------------------------------------------------|----------|------------------------|
| 6          | Tel Maayan Mixed Public School<br>مدرسة تلمعيان المختلطة الرسمية | 518      | Akkar                  |



| School No. | School Name                                                      | CERD No. | Governorate / District |
|------------|------------------------------------------------------------------|----------|------------------------|
| 6          | Tel Maayan Mixed Public School<br>مدرسة تلمعيان المختلطة الرسمية | 518      | Akkar                  |



| School No. | School Name                                                      | CERD No. | Governorate / District |
|------------|------------------------------------------------------------------|----------|------------------------|
| 6          | Tel Maayan Mixed Public School<br>مدرسة تلمعيان المختلطة الرسمية | 518      | Akkar                  |



| School No. | School Name                                                     | CERD No. | Governorate / District |
|------------|-----------------------------------------------------------------|----------|------------------------|
| 7          | Kolayaat Mixed Public School<br>مدرسة القليعات الرسمية المختلطة | 519      | Akkar                  |

|                  |            |            |
|------------------|------------|------------|
| School Location: | X          | Y          |
|                  | 34.5871831 | 36.0174717 |

|                     |          |        |                |   |
|---------------------|----------|--------|----------------|---|
| School Information: | Owned    | Rented | No. of Blocks: | 3 |
|                     | ✓ (Gift) |        |                |   |

|                |             |                    |    |
|----------------|-------------|--------------------|----|
| No. of Floors: | A:2,B:1,C:1 | No. of Classrooms: | 19 |
|----------------|-------------|--------------------|----|

|                            |               |             |           |
|----------------------------|---------------|-------------|-----------|
| Director Name and Contact: | Hiba Al Chami | - Landline: | 06-875061 |
|                            |               | - Mobile:   | 03-161450 |

Building Condition: Category **1**

|                       |     |    |          |           |           |
|-----------------------|-----|----|----------|-----------|-----------|
| Roof Heat Insulation: | Yes | No | Comments | Condition |           |
|                       |     | ✓  |          | Good      | To Repair |
|                       |     |    |          |           |           |

|                     |     |    |          |           |           |
|---------------------|-----|----|----------|-----------|-----------|
| Roof Waterproofing: | Yes | No | Comments | Condition |           |
|                     | ✓   |    |          | Good      | To Repair |
|                     |     |    |          | ✓         |           |

|                                    |     |    |          |           |           |
|------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Parapet at Roof Floor: | Yes | No | Comments | Condition |           |
|                                    |     | ✓  |          | Good      | To Repair |
|                                    |     |    |          |           |           |

|                                        |     |    |          |           |           |
|----------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Ramp at GF level: | Yes | No | Comments | Condition |           |
|                                        | ✓   |    |          | Good      | To Repair |
|                                        |     |    |          | ✓         |           |

|                              |     |    |          |           |           |
|------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Toilet: | Yes | No | Comments | Condition |           |
|                              | ✓   |    |          | Good      | To Repair |
|                              |     |    |          | ✓         |           |

|             |     |    |          |           |           |
|-------------|-----|----|----------|-----------|-----------|
| Playground: | Yes | No | Comments | Condition |           |
|             | ✓   |    |          | Good      | To Repair |
|             |     |    |          | ✓         |           |

|                                     |     |    |                                            |           |           |
|-------------------------------------|-----|----|--------------------------------------------|-----------|-----------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments                                   | Condition |           |
|                                     | ✓   |    | Type: Resin + Tiles                        | Good      | To Repair |
|                                     |     |    |                                            | ✓         |           |
| <b>External Main Gate:</b>          | Yes | No | Comments                                   | Condition |           |
|                                     | ✓   |    | Type: Steel                                | Good      | To Repair |
|                                     |     |    |                                            | ✓         |           |
| <b>Internal Main Gate:</b>          | Yes | No | Comments                                   | Condition |           |
|                                     | ✓   |    | Type: Steel                                | Good      | To Repair |
|                                     |     |    |                                            | ✓         |           |
| <b>Shed:</b>                        | Yes | No | Comments                                   | Condition |           |
|                                     | ✓   |    | Polycarbonate<br>Brick                     | Good      | To Repair |
|                                     |     |    |                                            | ✓         |           |
| <b>Rain Water System:</b>           | Yes | No | Comments                                   | Condition |           |
|                                     | ✓   |    |                                            | Good      | To Repair |
|                                     |     |    |                                            | ✓         |           |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments                                   | Condition |           |
|                                     | ✓   |    |                                            | Good      | To Repair |
|                                     |     |    |                                            | ✓         |           |
| <b>Electrical System:</b>           | Yes | No | Comments                                   | Condition |           |
|                                     | ✓   |    | Problems with emptying the<br>septic tank. | Good      | To Repair |
|                                     |     |    |                                            | ✓         |           |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments                                   | Condition |           |
|                                     | ✓   |    | Battery shortage                           | Good      | To Repair |
|                                     |     |    |                                            | ✓         |           |
| <b>Source of Electricity:</b>       | EDL |    | Generator                                  | Condition |           |
|                                     | ✓   |    | Available but<br>Not working               | Good      | To Repair |
|                                     |     |    |                                            | ✓         |           |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                                     | CERD No. | Governorate / District |
|------------|-----------------------------------------------------------------|----------|------------------------|
| 7          | Kolayaat Mixed Public School<br>مدرسة القليعات الرسمية المختلطة | 519      | Akkar                  |



| School No. | School Name                                                     | CERD No. | Governorate / District |
|------------|-----------------------------------------------------------------|----------|------------------------|
| 7          | Kolayaat Mixed Public School<br>مدرسة القليعات الرسمية المختلطة | 519      | Akkar                  |



| School No. | School Name                                                     | CERD No. | Governorate / District |
|------------|-----------------------------------------------------------------|----------|------------------------|
| 7          | Kolayaat Mixed Public School<br>مدرسة القليعات الرسمية المختلطة | 519      | Akkar                  |



| School No. | School Name                                                              | CERD No. | Governorate / District |
|------------|--------------------------------------------------------------------------|----------|------------------------|
| 13         | Hekr El Hawshab Mixed Public School<br>مدرسة حكر الحوشب الرسمية المختلطة | 527      | Akkar                  |

|                  |           |           |
|------------------|-----------|-----------|
| School Location: | X         | Y         |
|                  | 34.589225 | 36.093158 |

|                     |                |         |                    |    |
|---------------------|----------------|---------|--------------------|----|
| School Information: | Owned          | Rented  | No. of Blocks:     | 2  |
|                     |                | ✓       |                    |    |
|                     | No. of Floors: | A:3,B:3 | No. of Classrooms: | 37 |

|                            |                     |             |           |
|----------------------------|---------------------|-------------|-----------|
| Director Name and Contact: | Tammam Majed Bakkar | - Landline: | 06-845469 |
|                            |                     | - Mobile:   | 03-467702 |

Building Condition: Category **1**

|                                        |        |        |          |                |                |
|----------------------------------------|--------|--------|----------|----------------|----------------|
| Roof Heat Insulation:                  | Yes    | No     | Comments | Condition      |                |
|                                        |        | ✓      |          | Good           | To Repair      |
| Roof Waterproofing:                    | Yes    | No     | Comments | Condition      |                |
|                                        | B<br>✓ | A<br>✓ |          | Good           | To Repair<br>✓ |
| Presence of Parapet at Roof Floor:     | Yes    | No     | Comments | Condition      |                |
|                                        | ✓      |        |          | Good<br>✓      | To Repair      |
| Presence of Handicap Ramp at GF level: | Yes    | No     | Comments | Condition      |                |
|                                        |        | ✓      |          | Good           | To Repair      |
| Presence of Handicap Toilet:           | Yes    | No     | Comments | Condition      |                |
|                                        |        | ✓      |          | Good           | To Repair      |
| Playground:                            | Yes    | No     | Comments | Condition      |                |
|                                        | ✓      |        |          | Type: Concrete | Good<br>✓      |

|                                     |     |    |             |           |           |
|-------------------------------------|-----|----|-------------|-----------|-----------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    | Type: Tiles | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>External Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Internal Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Shed:</b>                        | Yes | No | Comments    | Condition |           |
|                                     |     | ✓  |             | Good      | To Repair |
|                                     |     |    |             |           |           |
| <b>Rain Water System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Electrical System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Source of Electricity:</b>       | EDL |    | Generator   | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                                              | CERD No. | Governorate / District |
|------------|--------------------------------------------------------------------------|----------|------------------------|
| 13         | Hekr El Hawshab Mixed Public School<br>مدرسة حكر الحوشب الرسمية المختلطة | 527      | Akkar                  |



| School No. | School Name                                                              | CERD No. | Governorate / District |
|------------|--------------------------------------------------------------------------|----------|------------------------|
| 13         | Hekr El Hawshab Mixed Public School<br>مدرسة حكر الحوشب الرسمية المختلطة | 527      | Akkar                  |



| School No. | School Name                                          | CERD No. | Governorate / District |
|------------|------------------------------------------------------|----------|------------------------|
| 14         | Halba Secondary Public School<br>ثانوية حلبا الرسمية | 530      | Akkar                  |

|                  |            |            |
|------------------|------------|------------|
| School Location: | X          | Y          |
|                  | 34.5421809 | 36.0748192 |

|                     |                |        |                    |    |
|---------------------|----------------|--------|--------------------|----|
| School Information: | Owned          | Rented | No. of Blocks:     | 1  |
|                     |                | ✓      |                    |    |
|                     | No. of Floors: | 3      | No. of Classrooms: | 28 |

|                            |                   |             |           |
|----------------------------|-------------------|-------------|-----------|
| Director Name and Contact: | Mahassen Al Zohbi | - Landline: | 26-691921 |
|                            |                   | - Mobile:   | 70-493215 |

Building Condition: Category **1**

|                                        |     |    |          |           |           |
|----------------------------------------|-----|----|----------|-----------|-----------|
| Roof Heat Insulation:                  | Yes | No | Comments | Condition |           |
|                                        |     | ✓  |          | Good      | To Repair |
| Roof Waterproofing:                    | Yes | No | Comments | Condition |           |
|                                        | ✓   |    |          | Good      | To Repair |
| Presence of Parapet at Roof Floor:     | Yes | No | Comments | Condition |           |
|                                        | ✓   |    |          | Good      | To Repair |
| Presence of Handicap Ramp at GF level: | Yes | No | Comments | Condition |           |
|                                        | ✓   |    |          | Good      | To Repair |
| Presence of Handicap Toilet:           | Yes | No | Comments | Condition |           |
|                                        | ✓   |    |          | Good      | To Repair |
| Playground:                            | Yes | No | Comments | Condition |           |
|                                        | ✓   |    |          | Good      | To Repair |

|                                     |     |    |             |           |           |
|-------------------------------------|-----|----|-------------|-----------|-----------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    | Type: Resin | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>External Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Internal Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Shed:</b>                        | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Rain Water System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Electrical System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Source of Electricity:</b>       | EDL |    | Generator   | Condition |           |
|                                     | ✓   |    | No          | Good      | To Repair |
|                                     |     |    |             | ✓         |           |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                          | CERD No. | Governorate / District |
|------------|------------------------------------------------------|----------|------------------------|
| 14         | Halba Secondary Public School<br>ثانوية حلبا الرسمية | 530      | Akkar                  |



| School No. | School Name                                          | CERD No. | Governorate / District |
|------------|------------------------------------------------------|----------|------------------------|
| 14         | Halba Secondary Public School<br>ثانوية حلبا الرسمية | 530      | Akkar                  |



| School No. | School Name                                                                  | CERD No. | Governorate / District |
|------------|------------------------------------------------------------------------------|----------|------------------------|
| 15         | Khraibit El Jindi Mixed Public School<br>مدرسة خريبة الجندي الرسمية المختلطة | 536      | Akkar                  |

**School Location:**

|            |            |
|------------|------------|
| X          | Y          |
| 34.5595141 | 36.0946067 |

**School Information:**

|       |        |
|-------|--------|
| Owned | Rented |
| ✓     |        |

No. of Blocks:

No. of Floors:

No. of Classrooms:

**Director Name and Contact:**

Khoder Rabah Nafaa

|             |           |
|-------------|-----------|
| - Landline: | 26-693455 |
| - Mobile:   | 70-566578 |

**Building Condition: Category 1**

**Roof Heat Insulation:**

| Yes | No | Comments |
|-----|----|----------|
|     | ✓  |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           |           |

**Roof Waterproofing:**

| Yes | No | Comments |
|-----|----|----------|
| ✓   |    |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           | ✓         |

**Presence of Parapet at Roof Floor:**

| Yes | No | Comments |
|-----|----|----------|
| ✓   |    |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**Presence of Handicap Ramp at GF level:**

| Yes | No | Comments |
|-----|----|----------|
|     | ✓  |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           |           |

**Presence of Handicap Toilet:**

| Yes | No | Comments |
|-----|----|----------|
|     | ✓  |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           |           |

**Playground:**

| Yes | No | Comments       |
|-----|----|----------------|
| ✓   |    | Type: concrete |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           | ✓         |

|                                     |     |    |                      |           |           |
|-------------------------------------|-----|----|----------------------|-----------|-----------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments             | Condition |           |
|                                     | ✓   |    | Type: Tiles          | Good      | To Repair |
|                                     |     |    |                      | ✓         |           |
| <b>External Main Gate:</b>          | Yes | No | Comments             | Condition |           |
|                                     | ✓   |    |                      | Good      | To Repair |
|                                     |     |    |                      |           | ✓         |
| <b>Internal Main Gate:</b>          | Yes | No | Comments             | Condition |           |
|                                     | ✓   |    |                      | Good      | To Repair |
|                                     |     |    |                      |           | ✓         |
| <b>Shed:</b>                        | Yes | No | Comments             | Condition |           |
|                                     | ✓   |    | Type: Steel and Zinc | Good      | To Repair |
|                                     |     |    |                      |           | ✓         |
| <b>Rain Water System:</b>           | Yes | No | Comments             | Condition |           |
|                                     | ✓   |    |                      | Good      | To Repair |
|                                     |     |    |                      |           | ✓         |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments             | Condition |           |
|                                     | ✓   |    |                      | Good      | To Repair |
|                                     |     |    |                      |           | ✓         |
| <b>Electrical System:</b>           | Yes | No | Comments             | Condition |           |
|                                     | ✓   |    |                      | Good      | To Repair |
|                                     |     |    |                      | ✓         |           |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments             | Condition |           |
|                                     | ✓   |    |                      | Good      | To Repair |
|                                     |     |    |                      | ✓         |           |
| <b>Source of Electricity:</b>       | EDL |    | Generator            | Condition |           |
|                                     | ✓   |    | ✓                    | Good      | To Repair |
|                                     |     |    |                      | ✓         |           |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                                                  | CERD No. | Governorate / District |
|------------|------------------------------------------------------------------------------|----------|------------------------|
| 15         | Khraibit El Jindi Mixed Public School<br>مدرسة خريبة الجندي الرسمية المختلطة | 536      | Akkar                  |



| School No. | School Name                                                                  | CERD No. | Governorate / District |
|------------|------------------------------------------------------------------------------|----------|------------------------|
| 15         | Khraibit El Jindi Mixed Public School<br>مدرسة خريبة الجندي الرسمية المختلطة | 536      | Akkar                  |



| School No. | School Name                                                                       | CERD No. | Governorate / District |
|------------|-----------------------------------------------------------------------------------|----------|------------------------|
| 16         | Jdeidat El Jouma Elementary Public School<br>مدرسة جديده الجومة التكميلية الرسمية | 539      | Akkar                  |

|                  |            |            |
|------------------|------------|------------|
| School Location: | X          | Y          |
|                  | 34.5371761 | 36.0654184 |

|                     |                |        |                    |    |
|---------------------|----------------|--------|--------------------|----|
| School Information: | Owned          | Rented | No. of Blocks:     | 1  |
|                     | ✓ (Gift)       |        |                    |    |
|                     | No. of Floors: | 3      | No. of Classrooms: | 12 |

|                            |                            |             |           |
|----------------------------|----------------------------|-------------|-----------|
| Director Name and Contact: | Micheline Ibrahim Abdallah | - Landline: | 26-693108 |
|                            |                            | - Mobile:   | 71-690030 |

Building Condition: Category **1**

|                       |     |    |          |           |           |
|-----------------------|-----|----|----------|-----------|-----------|
| Roof Heat Insulation: | Yes | No | Comments | Condition |           |
|                       |     | ✓  |          | Good      | To Repair |

|                     |     |    |           |           |           |
|---------------------|-----|----|-----------|-----------|-----------|
| Roof Waterproofing: | Yes | No | Comments  | Condition |           |
|                     | ✓   |    | Type: SBS | Good      | To Repair |
|                     |     |    |           | ✓         |           |

|                                    |     |    |          |           |           |
|------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Parapet at Roof Floor: | Yes | No | Comments | Condition |           |
|                                    | ✓   |    |          | Good      | To Repair |
|                                    |     |    |          | ✓         |           |

|                                        |     |    |          |           |           |
|----------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Ramp at GF level: | Yes | No | Comments | Condition |           |
|                                        | ✓   |    |          | Good      | To Repair |
|                                        |     |    |          | ✓         |           |

|                              |     |    |          |           |           |
|------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Toilet: | Yes | No | Comments | Condition |           |
|                              | ✓   |    |          | Good      | To Repair |
|                              |     |    |          | ✓         |           |

|             |     |    |                |           |           |
|-------------|-----|----|----------------|-----------|-----------|
| Playground: | Yes | No | Comments       | Condition |           |
|             | ✓   |    | Type: Concrete | Good      | To Repair |
|             |     |    |                |           | ✓         |

|                                     |     |    |             |           |           |
|-------------------------------------|-----|----|-------------|-----------|-----------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    | Type: Resin | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>External Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Internal Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Shed:</b>                        | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Rain Water System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Electrical System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Source of Electricity:</b>       | EDL |    | Generator   | Condition |           |
|                                     |     |    | No          | Good      | To Repair |
|                                     |     |    |             |           |           |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                                                       | CERD No. | Governorate / District |
|------------|-----------------------------------------------------------------------------------|----------|------------------------|
| 16         | Jdeidat El Jouma Elementary Public School<br>مدرسة جديده الجومة التكميلية الرسمية | 539      | Akkar                  |



| School No. | School Name                                                                       | CERD No. | Governorate / District |
|------------|-----------------------------------------------------------------------------------|----------|------------------------|
| 16         | Jdeidat El Jouma Elementary Public School<br>مدرسة جديده الجومة التكميلية الرسمية | 539      | Akkar                  |



| School No. | School Name                                      | CERD No. | Governorate / District |
|------------|--------------------------------------------------|----------|------------------------|
| 17         | El Hakour Public School<br>مدرسة الحاكور الرسمية | 546      | Akkar                  |

**School Location:**

|           |           |
|-----------|-----------|
| X         | Y         |
| 34.524829 | 36.055261 |

**School Information:**

|          |        |                |   |
|----------|--------|----------------|---|
| Owned    | Rented | No. of Blocks: | 1 |
| ✓ (Gift) |        |                |   |

|                |   |                    |    |
|----------------|---|--------------------|----|
| No. of Floors: | 2 | No. of Classrooms: | 10 |
|----------------|---|--------------------|----|

**Director Name and Contact:**

Samia Youssef Al Khoury

- Landline:

06-825810

- Mobile:

71-797111

**Building Condition: Category 1**

**Roof Heat Insulation:**

| Yes | No | Comments |
|-----|----|----------|
|     | ✓  |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           |           |

**Roof Waterproofing:**

| Yes | No | Comments  |
|-----|----|-----------|
| ✓   |    | Type: SBS |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**Presence of Parapet at Roof Floor:**

| Yes | No | Comments |
|-----|----|----------|
| ✓   |    |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**Presence of Handicap Ramp at GF level:**

| Yes | No | Comments |
|-----|----|----------|
| ✓   |    |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**Presence of Handicap Toilet:**

| Yes | No | Comments |
|-----|----|----------|
| ✓   |    |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**Playground:**

| Yes | No | Comments       |
|-----|----|----------------|
| ✓   |    | Type: concrete |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

|                                     |     |    |             |           |           |
|-------------------------------------|-----|----|-------------|-----------|-----------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    | Type: Resin | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>External Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Internal Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Shed:</b>                        | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Rain Water System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Electrical System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Source of Electricity:</b>       | EDL |    | Generator   | Condition |           |
|                                     | ✓   |    | ✓           | Good      | To Repair |
|                                     |     |    |             |           | ✓         |


**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                      | CERD No. | Governorate / District |
|------------|--------------------------------------------------|----------|------------------------|
| 17         | El Hakour Public School<br>مدرسة الحاكور الرسمية | 546      | Akkar                  |



| School No. | School Name                                      | CERD No. | Governorate / District |
|------------|--------------------------------------------------|----------|------------------------|
| 17         | El Hakour Public School<br>مدرسة الحاكور الرسمية | 546      | Akkar                  |



| School No. | School Name                                                   | CERD No. | Governorate / District |
|------------|---------------------------------------------------------------|----------|------------------------|
| 18         | Bkarzela Mixed Public School<br>مدرسة بقرزلا الرسمية المختلطة | 547      | Akkar                  |

|                  |            |            |
|------------------|------------|------------|
| School Location: | X          | Y          |
|                  | 34.5119493 | 36.0558629 |

|                     |                |        |                    |    |
|---------------------|----------------|--------|--------------------|----|
| School Information: | Owned          | Rented | No. of Blocks:     | 1  |
|                     | ✓ (Gift)       |        |                    |    |
|                     | No. of Floors: | 3      | No. of Classrooms: | 15 |

|                            |              |             |           |
|----------------------------|--------------|-------------|-----------|
| Director Name and Contact: | Rana Chouman | - Landline: | 26-805211 |
|                            |              | - Mobile:   | 76-335331 |

Building Condition: Category **1**

|                                        |     |    |                        |           |           |
|----------------------------------------|-----|----|------------------------|-----------|-----------|
| Roof Heat Insulation:                  | Yes | No | Comments               | Condition |           |
|                                        |     | ✓  |                        | Good      | To Repair |
|                                        |     |    |                        | ✓         |           |
| Roof Waterproofing:                    | Yes | No | Comments               | Condition |           |
|                                        | ✓   |    |                        | Good      | To Repair |
|                                        |     |    | Type: SBS              | ✓         |           |
| Presence of Parapet at Roof Floor:     | Yes | No | Comments               | Condition |           |
|                                        | ✓   |    |                        | Good      | To Repair |
|                                        |     |    |                        | ✓         |           |
| Presence of Handicap Ramp at GF level: | Yes | No | Comments               | Condition |           |
|                                        | ✓   |    |                        | Good      | To Repair |
|                                        |     |    |                        | ✓         |           |
| Presence of Handicap Toilet:           | Yes | No | Comments               | Condition |           |
|                                        | ✓   |    |                        | Good      | To Repair |
|                                        |     |    |                        | ✓         |           |
| Playground:                            | Yes | No | Comments               | Condition |           |
|                                        | ✓   |    |                        | Good      | To Repair |
|                                        |     |    | Type: Stamped concrete | ✓         |           |

|                                     |     |    |                |           |           |
|-------------------------------------|-----|----|----------------|-----------|-----------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments       | Condition |           |
|                                     | ✓   |    | Type: Resin    | Good      | To Repair |
|                                     |     |    |                | ✓         |           |
| <b>External Main Gate:</b>          | Yes | No | Comments       | Condition |           |
|                                     | ✓   |    |                | Good      | To Repair |
|                                     |     |    |                |           | ✓         |
| <b>Internal Main Gate:</b>          | Yes | No | Comments       | Condition |           |
|                                     | ✓   |    |                | Good      | To Repair |
|                                     |     |    |                |           | ✓         |
| <b>Shed:</b>                        | Yes | No | Comments       | Condition |           |
|                                     | ✓   |    |                | Good      | To Repair |
|                                     |     |    |                |           | ✓         |
| <b>Rain Water System:</b>           | Yes | No | Comments       | Condition |           |
|                                     | ✓   |    |                | Good      | To Repair |
|                                     |     |    |                |           | ✓         |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments       | Condition |           |
|                                     | ✓   |    |                | Good      | To Repair |
|                                     |     |    |                | ✓         |           |
| <b>Electrical System:</b>           | Yes | No | Comments       | Condition |           |
|                                     | ✓   |    |                | Good      | To Repair |
|                                     |     |    |                | ✓         |           |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments       | Condition |           |
|                                     |     | ✓  |                | Good      | To Repair |
|                                     |     |    |                |           |           |
| <b>Source of Electricity:</b>       | EDL |    | Generator      | Condition |           |
|                                     | ✓   |    | Out of service | Good      | To Repair |
|                                     |     |    |                |           | ✓         |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                                   | CERD No. | Governorate / District |
|------------|---------------------------------------------------------------|----------|------------------------|
| 18         | Bkarzela Mixed Public School<br>مدرسة بقرزلا الرسمية المختلطة | 547      | Akkar                  |



| School No. | School Name                                                   | CERD No. | Governorate / District |
|------------|---------------------------------------------------------------|----------|------------------------|
| 18         | Bkarzela Mixed Public School<br>مدرسة بقرزلا الرسمية المختلطة | 547      | Akkar                  |



| School No. | School Name                                                           | CERD No. | Governorate / District |
|------------|-----------------------------------------------------------------------|----------|------------------------|
| 19         | Zouk El Habasela Mixed Public School<br>ذوق الحبالسة المختلطة الرسمية | 551      | Akkar                  |

|                  |           |           |
|------------------|-----------|-----------|
| School Location: | X         | Y         |
|                  | 34.517159 | 36.038321 |

|                     |                |        |                    |    |
|---------------------|----------------|--------|--------------------|----|
| School Information: | Owned          | Rented | No. of Blocks:     | 1  |
|                     | ✓ (Gift)       |        |                    |    |
|                     | No. of Floors: | 2      | No. of Classrooms: | 12 |

|                            |                       |             |           |
|----------------------------|-----------------------|-------------|-----------|
| Director Name and Contact: | Najwa Abdallah Hoblos | - Landline: | 06-825224 |
|                            |                       | - Mobile:   | 71-718343 |

Building Condition: Category **1**

|                       |     |    |          |           |           |
|-----------------------|-----|----|----------|-----------|-----------|
| Roof Heat Insulation: | Yes | No | Comments | Condition |           |
|                       |     | ✓  |          | Good      | To Repair |
|                       |     |    |          |           |           |

|                     |     |    |          |           |           |
|---------------------|-----|----|----------|-----------|-----------|
| Roof Waterproofing: | Yes | No | Comments | Condition |           |
|                     |     | ✓  |          | Good      | To Repair |
|                     |     |    |          |           |           |

|                                    |     |    |          |           |           |
|------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Parapet at Roof Floor: | Yes | No | Comments | Condition |           |
|                                    | ✓   |    |          | Good      | To Repair |
|                                    |     |    |          | ✓         |           |

|                                        |     |    |          |           |           |
|----------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Ramp at GF level: | Yes | No | Comments | Condition |           |
|                                        | ✓   |    |          | Good      | To Repair |
|                                        |     |    |          | ✓         |           |

|                              |     |    |          |           |           |
|------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Toilet: | Yes | No | Comments | Condition |           |
|                              |     | ✓  |          | Good      | To Repair |
|                              |     |    |          |           |           |

|             |     |    |                |           |           |
|-------------|-----|----|----------------|-----------|-----------|
| Playground: | Yes | No | Comments       | Condition |           |
|             | ✓   |    | Type: Concrete | Good      | To Repair |
|             |     |    |                | ✓         |           |

|                    |     |    |          |           |           |
|--------------------|-----|----|----------|-----------|-----------|
| Drinking Fountain: | Yes | No | Comments | Condition |           |
|                    |     | ✓  |          | Good      | To Repair |
|                    |     |    |          |           |           |

|                     |     |    |          |           |           |
|---------------------|-----|----|----------|-----------|-----------|
| External Main Gate: | Yes | No | Comments | Condition |           |
|                     | ✓   |    |          | Good      | To Repair |
|                     |     |    |          |           | ✓         |

|                     |     |    |          |           |           |
|---------------------|-----|----|----------|-----------|-----------|
| Internal Main Gate: | Yes | No | Comments | Condition |           |
|                     | ✓   |    |          | Good      | To Repair |
|                     |     |    |          |           | ✓         |

|       |     |    |            |           |           |
|-------|-----|----|------------|-----------|-----------|
| Shed: | Yes | No | Comments   | Condition |           |
|       | ✓   |    | Type: Zinc | Good      | To Repair |
|       |     |    |            |           | ✓         |

|                    |     |    |          |           |           |
|--------------------|-----|----|----------|-----------|-----------|
| Rain Water System: | Yes | No | Comments | Condition |           |
|                    | ✓   |    |          | Good      | To Repair |
|                    |     |    |          | ✓         |           |

|                              |     |    |          |           |           |
|------------------------------|-----|----|----------|-----------|-----------|
| Waste Water Drainage System: | Yes | No | Comments | Condition |           |
|                              | ✓   |    |          | Good      | To Repair |
|                              |     |    |          | ✓         |           |

|                    |     |    |          |           |           |
|--------------------|-----|----|----------|-----------|-----------|
| Electrical System: | Yes | No | Comments | Condition |           |
|                    | ✓   |    |          | Good      | To Repair |
|                    |     |    |          |           | ✓         |

|                         |     |    |          |           |           |
|-------------------------|-----|----|----------|-----------|-----------|
| PV Solar Panel at Roof: | Yes | No | Comments | Condition |           |
|                         | ✓   |    |          | Good      | To Repair |
|                         |     |    |          |           | ✓         |

|                        |     |  |           |           |           |
|------------------------|-----|--|-----------|-----------|-----------|
| Source of Electricity: | EDL |  | Generator | Condition |           |
|                        |     |  | ✓         | Good      | To Repair |
|                        |     |  |           | ✓         |           |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                                           | CERD No. | Governorate / District |
|------------|-----------------------------------------------------------------------|----------|------------------------|
| 19         | Zouk El Habasela Mixed Public School<br>ذوق الحبالسة المختلطة الرسمية | 551      | Akkar                  |



| School No. | School Name                                                           | CERD No. | Governorate / District |
|------------|-----------------------------------------------------------------------|----------|------------------------|
| 19         | Zouk El Habasela Mixed Public School<br>ذوق الحبالسة المختلطة الرسمية | 551      | Akkar                  |



| School No. | School Name                                                 | CERD No. | Governorate / District |
|------------|-------------------------------------------------------------|----------|------------------------|
| 20         | Majdala Mixed Public School<br>مدرسة مجدلا المختلطة الرسمية | 552      | Akkar                  |

|                  |           |           |
|------------------|-----------|-----------|
| School Location: | X         | Y         |
|                  | 34.500364 | 36.035925 |

|                     |                |        |                    |    |
|---------------------|----------------|--------|--------------------|----|
| School Information: | Owned          | Rented | No. of Blocks:     | 1  |
|                     |                | ✓      |                    |    |
|                     | No. of Floors: | 2      | No. of Classrooms: | 11 |

|                            |                       |             |           |
|----------------------------|-----------------------|-------------|-----------|
| Director Name and Contact: | Bouchra Said Al Asmar | - Landline: | 06-805720 |
|                            |                       | - Mobile:   | 70-674442 |

Building Condition: Category **1**

|                                        |     |    |          |           |           |
|----------------------------------------|-----|----|----------|-----------|-----------|
| Roof Heat Insulation:                  | Yes | No | Comments | Condition |           |
|                                        |     | ✓  |          | Good      | To Repair |
| Roof Waterproofing:                    | Yes | No | Comments | Condition |           |
|                                        |     | ✓  |          | Good      | To Repair |
| Presence of Parapet at Roof Floor:     | Yes | No | Comments | Condition |           |
|                                        | ✓   |    |          | Good      | To Repair |
| Presence of Handicap Ramp at GF level: | Yes | No | Comments | Condition |           |
|                                        |     | ✓  |          | Good      | To Repair |
| Presence of Handicap Toilet:           | Yes | No | Comments | Condition |           |
|                                        |     | ✓  |          | Good      | To Repair |
| Playground:                            | Yes | No | Comments | Condition |           |
|                                        | ✓   |    |          | Good      | To Repair |

|                                     |     |    |             |           |           |
|-------------------------------------|-----|----|-------------|-----------|-----------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    | Type: Tiles | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>External Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Internal Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Shed:</b>                        | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    | Eternit     | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Rain Water System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Electrical System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Source of Electricity:</b>       | EDL |    | Generator   | Condition |           |
|                                     | ✓   |    | No          | Good      | To Repair |
|                                     |     |    |             | ✓         |           |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                                 | CERD No. | Governorate / District |
|------------|-------------------------------------------------------------|----------|------------------------|
| 20         | Majdala Mixed Public School<br>مدرسة مجدلا المختلطة الرسمية | 552      | Akkar                  |



| School No. | School Name                                                 | CERD No. | Governorate / District |
|------------|-------------------------------------------------------------|----------|------------------------|
| 20         | Majdala Mixed Public School<br>مدرسة مجدلا المختلطة الرسمية | 552      | Akkar                  |



| School No. | School Name                                                 | CERD No. | Governorate / District |
|------------|-------------------------------------------------------------|----------|------------------------|
| 20         | Majdala Mixed Public School<br>مدرسة مجدلا المختلطة الرسمية | 552      | Akkar                  |



| School No. | School Name                                                          | CERD No. | Governorate / District |
|------------|----------------------------------------------------------------------|----------|------------------------|
| 23         | Burj Al Arab Mixed Public School<br>مدرسة برج العرب الرسمية المختلطة | 559      | Akkar                  |

**School Location:**

|            |           |
|------------|-----------|
| X          | Y         |
| 34.5221652 | 36.003303 |

**School Information:**

|       |        |                |   |
|-------|--------|----------------|---|
| Owned | Rented | No. of Blocks: | 2 |
|       | ✓      |                |   |

|                |   |                    |    |
|----------------|---|--------------------|----|
| No. of Floors: | 1 | No. of Classrooms: | 22 |
|----------------|---|--------------------|----|

**Director Name and Contact:**

Fadia Al Zaylaa

|             |           |
|-------------|-----------|
| - Landline: | 06-825234 |
| - Mobile:   | 70-331394 |

**Building Condition: Category 1**

**Roof Heat Insulation:**

| Yes | No | Comments |
|-----|----|----------|
|     | ✓  |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           |           |

**Roof Waterproofing:**

| Yes | No | Comments |
|-----|----|----------|
|     | ✓  |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           |           |

**Presence of Parapet at Roof Floor:**

| Yes | No | Comments |
|-----|----|----------|
| ✓   |    |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           | ✓         |

**Presence of Handicap Ramp at GF level:**

| Yes | No | Comments |
|-----|----|----------|
|     | ✓  |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           |           |

**Presence of Handicap Toilet:**

| Yes | No | Comments |
|-----|----|----------|
|     | ✓  |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           |           |

**Playground:**

| Yes | No | Comments |
|-----|----|----------|
| ✓   |    |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           | ✓         |

|                    |     |    |          |           |           |
|--------------------|-----|----|----------|-----------|-----------|
| Drinking Fountain: | Yes | No | Comments | Condition |           |
|                    | ✓   |    |          | Good      | To Repair |
|                    |     |    |          |           | ✓         |

|                     |     |    |          |           |           |
|---------------------|-----|----|----------|-----------|-----------|
| External Main Gate: | Yes | No | Comments | Condition |           |
|                     | ✓   |    |          | Good      | To Repair |
|                     |     |    |          |           | ✓         |

|                     |     |    |          |           |           |
|---------------------|-----|----|----------|-----------|-----------|
| Internal Main Gate: | Yes | No | Comments | Condition |           |
|                     | ✓   |    |          | Good      | To Repair |
|                     |     |    |          |           | ✓         |

|       |     |    |                         |           |           |
|-------|-----|----|-------------------------|-----------|-----------|
| Shed: | Yes | No | Comments                | Condition |           |
|       | ✓   |    | Type: Red Brick + Steel | Good      | To Repair |
|       |     |    |                         | ✓         |           |

|                    |     |    |          |           |           |
|--------------------|-----|----|----------|-----------|-----------|
| Rain Water System: | Yes | No | Comments | Condition |           |
|                    | ✓   |    |          | Good      | To Repair |
|                    |     |    |          |           | ✓         |

|                              |     |    |          |           |           |
|------------------------------|-----|----|----------|-----------|-----------|
| Waste Water Drainage System: | Yes | No | Comments | Condition |           |
|                              | ✓   |    |          | Good      | To Repair |
|                              |     |    |          |           | ✓         |

|                    |     |    |          |           |           |
|--------------------|-----|----|----------|-----------|-----------|
| Electrical System: | Yes | No | Comments | Condition |           |
|                    | ✓   |    |          | Good      | To Repair |
|                    |     |    |          | ✓         |           |

|                         |     |    |          |           |           |
|-------------------------|-----|----|----------|-----------|-----------|
| PV Solar Panel at Roof: | Yes | No | Comments | Condition |           |
|                         | ✓   |    |          | Good      | To Repair |
|                         |     |    |          | ✓         |           |

|                        |     |  |           |           |           |
|------------------------|-----|--|-----------|-----------|-----------|
| Source of Electricity: | EDL |  | Generator | Condition |           |
|                        | ✓   |  | No        | Good      | To Repair |
|                        |     |  |           |           | ✓         |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                                          | CERD No. | Governorate / District |
|------------|----------------------------------------------------------------------|----------|------------------------|
| 23         | Burj Al Arab Mixed Public School<br>مدرسة برج العرب الرسمية المختلطة | 559      | Akkar                  |



| School No. | School Name                                                          | CERD No. | Governorate / District |
|------------|----------------------------------------------------------------------|----------|------------------------|
| 23         | Burj Al Arab Mixed Public School<br>مدرسة برج العرب الرسمية المختلطة | 559      | Akkar                  |



| School No. | School Name                                                       | CERD No. | Governorate / District |
|------------|-------------------------------------------------------------------|----------|------------------------|
| 34         | EL Souweisa Mixed Public School<br>مدرسة السويصة الرسمية المختلطة | 593      | Akkar                  |

|                  |            |            |
|------------------|------------|------------|
| School Location: | X          | Y          |
|                  | 34.5535408 | 36.1193857 |

|                     |                |        |                    |    |
|---------------------|----------------|--------|--------------------|----|
| School Information: | Owned          | Rented | No. of Blocks:     | 1  |
|                     | ✓              |        |                    |    |
|                     | No. of Floors: | 2      | No. of Classrooms: | 12 |

|                            |                     |             |           |
|----------------------------|---------------------|-------------|-----------|
| Director Name and Contact: | Emtithal Al Thoabeh | - Landline: | 06-835347 |
|                            |                     | - Mobile:   | 71-930017 |

Building Condition: Category **1**

|                       |     |    |          |           |           |
|-----------------------|-----|----|----------|-----------|-----------|
| Roof Heat Insulation: | Yes | No | Comments | Condition |           |
|                       |     | ✓  |          | Good      | To Repair |

|                     |     |    |           |           |           |
|---------------------|-----|----|-----------|-----------|-----------|
| Roof Waterproofing: | Yes | No | Comments  | Condition |           |
|                     | ✓   |    | Type: SBS | Good      | To Repair |

|                                    |     |    |          |           |           |
|------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Parapet at Roof Floor: | Yes | No | Comments | Condition |           |
|                                    | ✓   |    |          | Good      | To Repair |

|                                        |     |    |          |           |           |
|----------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Ramp at GF level: | Yes | No | Comments | Condition |           |
|                                        |     | ✓  |          | Good      | To Repair |

|                              |     |    |          |           |           |
|------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Toilet: | Yes | No | Comments | Condition |           |
|                              |     | ✓  |          | Good      | To Repair |

|             |     |    |               |           |           |
|-------------|-----|----|---------------|-----------|-----------|
| Playground: | Yes | No | Comments      | Condition |           |
|             | ✓   |    | Slab on grade | Good      | To Repair |

|                                     |     |    |                    |           |           |
|-------------------------------------|-----|----|--------------------|-----------|-----------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments           | Condition |           |
|                                     | ✓   |    | Type: Tiles        | Good      | To Repair |
|                                     |     |    |                    | ✓         |           |
| <b>External Main Gate:</b>          | Yes | No | Comments           | Condition |           |
|                                     | ✓   |    | Type: Steel        | Good      | To Repair |
|                                     |     |    |                    |           | ✓         |
| <b>Internal Main Gate:</b>          | Yes | No | Comments           | Condition |           |
|                                     | ✓   |    | Type: Steel        | Good      | To Repair |
|                                     |     |    |                    |           | ✓         |
| <b>Shed:</b>                        | Yes | No | Comments           | Condition |           |
|                                     | ✓   |    | Type: Steel + Zinc | Good      | To Repair |
|                                     |     |    |                    | ✓         |           |
| <b>Rain Water System:</b>           | Yes | No | Comments           | Condition |           |
|                                     | ✓   |    |                    | Good      | To Repair |
|                                     |     |    |                    |           | ✓         |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments           | Condition |           |
|                                     | ✓   |    |                    | Good      | To Repair |
|                                     |     |    |                    |           | ✓         |
| <b>Electrical System:</b>           | Yes | No | Comments           | Condition |           |
|                                     | ✓   |    |                    | Good      | To Repair |
|                                     |     |    |                    | ✓         |           |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments           | Condition |           |
|                                     | ✓   |    |                    | Good      | To Repair |
|                                     |     |    |                    | ✓         |           |
| <b>Source of Electricity:</b>       | EDL |    | Generator          | Condition |           |
|                                     | ✓   |    | ✓                  | Good      | To Repair |
|                                     |     |    |                    | ✓         |           |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                                       | CERD No. | Governorate / District |
|------------|-------------------------------------------------------------------|----------|------------------------|
| 34         | EL Souweisa Mixed Public School<br>مدرسة السويصة الرسمية المختلطة | 593      | Akkar                  |



| School No. | School Name                                                       | CERD No. | Governorate / District |
|------------|-------------------------------------------------------------------|----------|------------------------|
| 34         | EL Souweisa Mixed Public School<br>مدرسة السويصة الرسمية المختلطة | 593      | Akkar                  |



| School No. | School Name                                               | CERD No. | Governorate / District |
|------------|-----------------------------------------------------------|----------|------------------------|
| 35         | Rahbeh Public School - Girls<br>مدرسة رحبة الرسمية للبنات | 595      | Akkar                  |

|                  |            |            |
|------------------|------------|------------|
| School Location: | X          | Y          |
|                  | 34.5029107 | 36.1480854 |

|                     |                |        |                    |    |
|---------------------|----------------|--------|--------------------|----|
| School Information: | Owned          | Rented | No. of Blocks:     | 1  |
|                     | ✓              |        |                    |    |
|                     | No. of Floors: | 3      | No. of Classrooms: | 12 |

|                            |                      |             |           |
|----------------------------|----------------------|-------------|-----------|
| Director Name and Contact: | Salwa Mtanious Assad | - Landline: | 06-890012 |
|                            |                      | - Mobile:   | 76-787968 |

Building Condition: Category **1**

|                       |     |    |          |           |           |
|-----------------------|-----|----|----------|-----------|-----------|
| Roof Heat Insulation: | Yes | No | Comments | Condition |           |
|                       |     | ✓  |          | Good      | To Repair |
|                       |     |    |          |           |           |

|                     |     |    |           |           |           |
|---------------------|-----|----|-----------|-----------|-----------|
| Roof Waterproofing: | Yes | No | Comments  | Condition |           |
|                     | ✓   |    | Type: SBS | Good      | To Repair |
|                     |     |    |           | ✓         |           |

|                                    |     |    |          |           |           |
|------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Parapet at Roof Floor: | Yes | No | Comments | Condition |           |
|                                    | ✓   |    |          | Good      | To Repair |
|                                    |     |    |          | ✓         |           |

|                                        |     |    |          |           |           |
|----------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Ramp at GF level: | Yes | No | Comments | Condition |           |
|                                        | ✓   |    |          | Good      | To Repair |
|                                        |     |    |          | ✓         |           |

|                              |     |    |          |           |           |
|------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Toilet: | Yes | No | Comments | Condition |           |
|                              | ✓   |    |          | Good      | To Repair |
|                              |     |    |          | ✓         |           |

|             |     |    |          |           |           |
|-------------|-----|----|----------|-----------|-----------|
| Playground: | Yes | No | Comments | Condition |           |
|             | ✓   |    |          | Good      | To Repair |
|             |     |    |          | ✓         |           |

|                    |     |    |          |           |           |
|--------------------|-----|----|----------|-----------|-----------|
| Drinking Fountain: | Yes | No | Comments | Condition |           |
|                    | ✓   |    |          | Good      | To Repair |
|                    |     |    |          |           | ✓         |

|                     |     |    |          |           |           |
|---------------------|-----|----|----------|-----------|-----------|
| External Main Gate: | Yes | No | Comments | Condition |           |
|                     | ✓   |    |          | Good      | To Repair |
|                     |     |    |          | ✓         |           |

|                     |     |    |          |           |           |
|---------------------|-----|----|----------|-----------|-----------|
| Internal Main Gate: | Yes | No | Comments | Condition |           |
|                     | ✓   |    |          | Good      | To Repair |
|                     |     |    |          | ✓         |           |

|       |     |    |          |           |           |
|-------|-----|----|----------|-----------|-----------|
| Shed: | Yes | No | Comments | Condition |           |
|       | ✓   |    |          | Good      | To Repair |
|       |     |    |          | ✓         |           |

|                    |     |    |          |           |           |
|--------------------|-----|----|----------|-----------|-----------|
| Rain Water System: | Yes | No | Comments | Condition |           |
|                    | ✓   |    |          | Good      | To Repair |
|                    |     |    |          |           | ✓         |

|                              |     |    |          |           |           |
|------------------------------|-----|----|----------|-----------|-----------|
| Waste Water Drainage System: | Yes | No | Comments | Condition |           |
|                              | ✓   |    |          | Good      | To Repair |
|                              |     |    |          | ✓         |           |

|                    |     |    |          |           |           |
|--------------------|-----|----|----------|-----------|-----------|
| Electrical System: | Yes | No | Comments | Condition |           |
|                    | ✓   |    |          | Good      | To Repair |
|                    |     |    |          | ✓         |           |

|                         |     |    |          |           |           |
|-------------------------|-----|----|----------|-----------|-----------|
| PV Solar Panel at Roof: | Yes | No | Comments | Condition |           |
|                         | ✓   |    |          | Good      | To Repair |
|                         |     |    |          | ✓         |           |

|                        |     |  |           |           |           |
|------------------------|-----|--|-----------|-----------|-----------|
| Source of Electricity: | EDL |  | Generator | Condition |           |
|                        | No  |  | ✓         | Good      | To Repair |
|                        |     |  |           | ✓         |           |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                               | CERD No. | Governorate / District |
|------------|-----------------------------------------------------------|----------|------------------------|
| 35         | Rahbeh Public School - Girls<br>مدرسة رحبة الرسمية للبنات | 595      | Akkar                  |



| School No. | School Name                                               | CERD No. | Governorate / District |
|------------|-----------------------------------------------------------|----------|------------------------|
| 35         | Rahbeh Public School - Girls<br>مدرسة رحبة الرسمية للبنات | 595      | Akkar                  |



| School No. | School Name                                                                  | CERD No. | Governorate / District |
|------------|------------------------------------------------------------------------------|----------|------------------------|
| 36         | Daher El Laysineh Mixed Public School<br>مدرسة صهر الليسينه المختلطة الرسمية | 597      | Akkar                  |

|                  |            |           |
|------------------|------------|-----------|
| School Location: | X          | Y         |
|                  | 34.5359328 | 36.142857 |

|                     |                |        |                    |   |
|---------------------|----------------|--------|--------------------|---|
| School Information: | Owned          | Rented | No. of Blocks:     | 1 |
|                     | ✓              |        |                    |   |
|                     | No. of Floors: | 1      | No. of Classrooms: | 8 |

|                            |                     |             |           |
|----------------------------|---------------------|-------------|-----------|
| Director Name and Contact: | Alisar Bedr Khayzir | - Landline: | 06-840.41 |
|                            |                     | - Mobile:   | 03-458304 |

Building Condition: Category **1**

|                       |     |    |          |           |           |
|-----------------------|-----|----|----------|-----------|-----------|
| Roof Heat Insulation: | Yes | No | Comments | Condition |           |
|                       |     | ✓  |          | Good      | To Repair |
|                       |     |    |          |           |           |

|                     |     |    |          |           |           |
|---------------------|-----|----|----------|-----------|-----------|
| Roof Waterproofing: | Yes | No | Comments | Condition |           |
|                     | ✓   |    |          | Good      | To Repair |
|                     |     |    |          | ✓         |           |

|                                    |     |    |          |           |           |
|------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Parapet at Roof Floor: | Yes | No | Comments | Condition |           |
|                                    |     | ✓  |          | Good      | To Repair |
|                                    |     |    |          |           |           |

|                                        |     |    |          |           |           |
|----------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Ramp at GF level: | Yes | No | Comments | Condition |           |
|                                        |     | ✓  |          | Good      | To Repair |
|                                        |     |    |          |           |           |

|                              |     |    |          |           |           |
|------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Toilet: | Yes | No | Comments | Condition |           |
|                              |     | ✓  |          | Good      | To Repair |
|                              |     |    |          |           |           |

|             |     |    |          |           |           |
|-------------|-----|----|----------|-----------|-----------|
| Playground: | Yes | No | Comments | Condition |           |
|             | ✓   |    |          | Good      | To Repair |
|             |     |    |          | ✓         |           |

|                                     |     |    |           |           |           |
|-------------------------------------|-----|----|-----------|-----------|-----------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments  | Condition |           |
|                                     |     | ✓  |           | Good      | To Repair |
|                                     |     |    |           |           |           |
| <b>External Main Gate:</b>          | Yes | No | Comments  | Condition |           |
|                                     | ✓   |    |           | Good      | To Repair |
|                                     |     |    |           |           | ✓         |
| <b>Internal Main Gate:</b>          | Yes | No | Comments  | Condition |           |
|                                     | ✓   |    |           | Good      | To Repair |
|                                     |     |    |           |           | ✓         |
| <b>Shed:</b>                        | Yes | No | Comments  | Condition |           |
|                                     | ✓   |    |           | Good      | To Repair |
|                                     |     |    |           |           | ✓         |
| <b>Rain Water System:</b>           | Yes | No | Comments  | Condition |           |
|                                     | ✓   |    |           | Good      | To Repair |
|                                     |     |    |           |           | ✓         |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments  | Condition |           |
|                                     | ✓   |    |           | Good      | To Repair |
|                                     |     |    |           |           | ✓         |
| <b>Electrical System:</b>           | Yes | No | Comments  | Condition |           |
|                                     | ✓   |    |           | Good      | To Repair |
|                                     |     |    |           |           | ✓         |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments  | Condition |           |
|                                     | ✓   |    |           | Good      | To Repair |
|                                     |     |    |           | ✓         |           |
| <b>Source of Electricity:</b>       | EDL |    | Generator | Condition |           |
|                                     | No  |    | No        | Good      | To Repair |
|                                     |     |    |           |           |           |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                                                  | CERD No. | Governorate / District |
|------------|------------------------------------------------------------------------------|----------|------------------------|
| 36         | Daher El Laysineh Mixed Public School<br>مدرسة ضهر الليسينة المختلطة الرسمية | 597      | Akkar                  |



| School No. | School Name                                                                  | CERD No. | Governorate / District |
|------------|------------------------------------------------------------------------------|----------|------------------------|
| 36         | Daher El Laysineh Mixed Public School<br>مدرسة صهر الليسينه المختلطة الرسمية | 597      | Akkar                  |



| School No. | School Name                                                | CERD No. | Governorate / District |
|------------|------------------------------------------------------------|----------|------------------------|
| 37         | Al Ouyoun Secondary Public School<br>ثانوية العيون الرسمية | 603      | Akkar                  |

|                  |            |            |
|------------------|------------|------------|
| School Location: | X          | Y          |
|                  | 34.5267823 | 36.1722029 |

|                     |                |        |                    |    |
|---------------------|----------------|--------|--------------------|----|
| School Information: | Owned          | Rented | No. of Blocks:     | 1  |
|                     |                | ✓      |                    |    |
|                     | No. of Floors: | 5      | No. of Classrooms: | 14 |

|                            |               |             |           |
|----------------------------|---------------|-------------|-----------|
| Director Name and Contact: | Mohamad Taleb | - Landline: | 06-360254 |
|                            |               | - Mobile:   | 70-388875 |

Building Condition: Category **1**

|                                        |     |    |          |           |           |
|----------------------------------------|-----|----|----------|-----------|-----------|
| Roof Heat Insulation:                  | Yes | No | Comments | Condition |           |
|                                        |     | ✓  |          | Good      | To Repair |
| Roof Waterproofing:                    | Yes | No | Comments | Condition |           |
|                                        | ✓   |    |          | Good      | To Repair |
| Presence of Parapet at Roof Floor:     | Yes | No | Comments | Condition |           |
|                                        | ✓   |    |          | Good      | To Repair |
| Presence of Handicap Ramp at GF level: | Yes | No | Comments | Condition |           |
|                                        |     | ✓  |          | Good      | To Repair |
| Presence of Handicap Toilet:           | Yes | No | Comments | Condition |           |
|                                        |     | ✓  |          | Good      | To Repair |
| Playground:                            | Yes | No | Comments | Condition |           |
|                                        | ✓   |    |          | Good      | To Repair |

|                                     |     |    |             |           |           |
|-------------------------------------|-----|----|-------------|-----------|-----------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    | Type: Tiles | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>External Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Internal Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Shed:</b>                        | Yes | No | Comments    | Condition |           |
|                                     |     | ✓  |             | Good      | To Repair |
|                                     |     |    |             |           |           |
| <b>Rain Water System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Electrical System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments    | Condition |           |
|                                     |     | ✓  |             | Good      | To Repair |
|                                     |     |    |             |           |           |
| <b>Source of Electricity:</b>       | EDL |    | Generator   | Condition |           |
|                                     | No  |    | ✓           | Good      | To Repair |
|                                     |     |    |             | ✓         |           |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                                | CERD No. | Governorate / District |
|------------|------------------------------------------------------------|----------|------------------------|
| 37         | Al Ouyoun Secondary Public School<br>ثانوية العيون الرسمية | 603      | Akkar                  |



| School No. | School Name                                                | CERD No. | Governorate / District |
|------------|------------------------------------------------------------|----------|------------------------|
| 37         | Al Ouyoun Secondary Public School<br>ثانوية العيون الرسمية | 603      | Akkar                  |



| School No. | School Name                                                | CERD No. | Governorate / District |
|------------|------------------------------------------------------------|----------|------------------------|
| 37         | Al Ouyoun Secondary Public School<br>ثانوية العيون الرسمية | 603      | Akkar                  |



| School No. | School Name                                              | CERD No. | Governorate / District |
|------------|----------------------------------------------------------|----------|------------------------|
| 38         | Beino Mixed Public School<br>مدرسة بينو الرسمية المختلطة | 606      | Akkar                  |

|                  |           |           |
|------------------|-----------|-----------|
| School Location: | X         | Y         |
|                  | 34.538579 | 36.174617 |

|                     |                |        |                    |   |
|---------------------|----------------|--------|--------------------|---|
| School Information: | Owned          | Rented | No. of Blocks:     | 2 |
|                     |                | ✓      |                    |   |
|                     | No. of Floors: | 1      | No. of Classrooms: | 3 |

|                            |                      |             |           |
|----------------------------|----------------------|-------------|-----------|
| Director Name and Contact: | Razan Aatiye Mansour | - Landline: | 06-361330 |
|                            |                      | - Mobile:   | 71-972193 |

Building Condition: Category **1**

|                       |     |    |          |           |           |
|-----------------------|-----|----|----------|-----------|-----------|
| Roof Heat Insulation: | Yes | No | Comments | Condition |           |
|                       |     | ✓  |          | Good      | To Repair |

|                     |     |    |           |           |           |
|---------------------|-----|----|-----------|-----------|-----------|
| Roof Waterproofing: | Yes | No | Comments  | Condition |           |
|                     | ✓   |    | Type: SBS | Good      | To Repair |
|                     |     |    |           | ✓         |           |

|                                    |     |    |          |           |           |
|------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Parapet at Roof Floor: | Yes | No | Comments | Condition |           |
|                                    |     | ✓  |          | Good      | To Repair |

|                                        |     |    |          |           |           |
|----------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Ramp at GF level: | Yes | No | Comments | Condition |           |
|                                        |     | ✓  |          | Good      | To Repair |

|                              |     |    |          |           |           |
|------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Toilet: | Yes | No | Comments | Condition |           |
|                              |     | ✓  |          | Good      | To Repair |

|             |     |    |          |           |           |
|-------------|-----|----|----------|-----------|-----------|
| Playground: | Yes | No | Comments | Condition |           |
|             | ✓   |    |          | Good      | To Repair |

|                                     |     |    |             |           |           |
|-------------------------------------|-----|----|-------------|-----------|-----------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    | Type: Tiles | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>External Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Internal Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Shed:</b>                        | Yes | No | Comments    | Condition |           |
|                                     |     | ✓  |             | Good      | To Repair |
|                                     |     |    |             |           |           |
| <b>Rain Water System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Electrical System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Source of Electricity:</b>       | EDL |    | Generator   | Condition |           |
|                                     | No  |    | ✓           | Good      | To Repair |
|                                     |     |    |             | ✓         |           |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                              | CERD No. | Governorate / District |
|------------|----------------------------------------------------------|----------|------------------------|
| 38         | Beino Mixed Public School<br>مدرسة بينو الرسمية المختلطة | 606      | Akkar                  |



| School No. | School Name                                              | CERD No. | Governorate / District |
|------------|----------------------------------------------------------|----------|------------------------|
| 38         | Beino Mixed Public School<br>مدرسة بينو الرسمية المختلطة | 606      | Akkar                  |



| School No. | School Name                                                  | CERD No. | Governorate / District |
|------------|--------------------------------------------------------------|----------|------------------------|
| 39         | Bazbina Mixed Public School<br>مدرسة بزيينا الرسمية المختلطة | 608      | Akkar                  |

**School Location:**

|            |            |
|------------|------------|
| X          | Y          |
| 34.5187056 | 36.1854637 |

**School Information:**

|       |        |
|-------|--------|
| Owned | Rented |
| ✓     |        |

No. of Blocks:

No. of Floors:

No. of Classrooms:

**Director Name and Contact:**

Lara Fazaa

|             |           |
|-------------|-----------|
| - Landline: | 06-360809 |
| - Mobile:   | 71-269994 |

**Building Condition: Category 1**

**Roof Heat Insulation:**

| Yes | No | Comments |
|-----|----|----------|
|     | ✓  |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           |           |

**Roof Waterproofing:**

| Yes | No | Comments  |
|-----|----|-----------|
| ✓   |    | Type: SBS |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**Presence of Parapet at Roof Floor:**

| Yes | No | Comments |
|-----|----|----------|
| ✓   |    |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**Presence of Handicap Ramp at GF level:**

| Yes | No | Comments |
|-----|----|----------|
|     | ✓  |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           |           |

**Presence of Handicap Toilet:**

| Yes | No | Comments |
|-----|----|----------|
|     | ✓  |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           |           |

**Playground:**

| Yes | No | Comments |
|-----|----|----------|
| ✓   |    |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

|                                     |     |    |             |           |           |
|-------------------------------------|-----|----|-------------|-----------|-----------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    | Type: Tiles | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>External Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Internal Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Shed:</b>                        | Yes | No | Comments    | Condition |           |
|                                     |     | ✓  |             | Good      | To Repair |
|                                     |     |    |             |           |           |
| <b>Rain Water System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Electrical System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Source of Electricity:</b>       | EDL |    | Generator   | Condition |           |
|                                     | No  |    | ✓           | Good      | To Repair |
|                                     |     |    |             | ✓         |           |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                                  | CERD No. | Governorate / District |
|------------|--------------------------------------------------------------|----------|------------------------|
| 39         | Bazbina Mixed Public School<br>مدرسة بزبينا الرسمية المختلطة | 608      | Akkar                  |



| School No. | School Name                                                  | CERD No. | Governorate / District |
|------------|--------------------------------------------------------------|----------|------------------------|
| 39         | Bazbina Mixed Public School<br>مدرسة بزيينا الرسمية المختلطة | 608      | Akkar                  |



| School No. | School Name                                                 | CERD No. | Governorate / District |
|------------|-------------------------------------------------------------|----------|------------------------|
| 40         | Akkar El Atila Public School<br>ثانوية عكار العتيقة الرسمية | 616      | Akkar                  |

**School Location:**

|            |            |
|------------|------------|
| X          | Y          |
| 34.5262267 | 36.2391495 |

**School Information:**

|          |        |                |   |
|----------|--------|----------------|---|
| Owned    | Rented | No. of Blocks: | 1 |
| ✓ (Gift) |        |                |   |

|                |   |                    |    |
|----------------|---|--------------------|----|
| No. of Floors: | 3 | No. of Classrooms: | 10 |
|----------------|---|--------------------|----|

**Director Name and Contact:**

|                        |             |           |
|------------------------|-------------|-----------|
| Chehadeh Mohamad Hasan | - Landline: | 06-885110 |
|                        | - Mobile:   | 70-507711 |

**Building Condition: Category 1**

**Roof Heat Insulation:**

| Yes | No | Comments |
|-----|----|----------|
|     | ✓  |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           |           |

**Roof Waterproofing:**

| Yes | No | Comments |
|-----|----|----------|
|     | ✓  |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           |           |

**Presence of Parapet at Roof Floor:**

| Yes | No | Comments |
|-----|----|----------|
|     | ✓  |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           |           |

**Presence of Handicap Ramp at GF level:**

| Yes | No | Comments |
|-----|----|----------|
| ✓   |    |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**Presence of Handicap Toilet:**

| Yes | No | Comments |
|-----|----|----------|
| ✓   |    |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**Playground:**

| Yes | No | Comments      |
|-----|----|---------------|
| ✓   |    | Slab on grade |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

|                                     |     |    |             |           |           |
|-------------------------------------|-----|----|-------------|-----------|-----------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    | Type: Tiles | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>External Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Internal Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Shed:</b>                        | Yes | No | Comments    | Condition |           |
|                                     |     | ✓  |             | Good      | To Repair |
|                                     |     |    |             |           |           |
| <b>Rain Water System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Electrical System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    | 23 panels   | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Source of Electricity:</b>       | EDL |    | Generator   | Condition |           |
|                                     | No  |    | ✓           | Good      | To Repair |
|                                     |     |    |             | ✓         |           |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                                 | CERD No. | Governorate / District |
|------------|-------------------------------------------------------------|----------|------------------------|
| 40         | Akkar El Atila Public School<br>ثانوية عكار العتيقة الرسمية | 616      | Akkar                  |



| School No. | School Name                                                 | CERD No. | Governorate / District |
|------------|-------------------------------------------------------------|----------|------------------------|
| 40         | Akkar El Atila Public School<br>ثانوية عكار العتيقة الرسمية | 616      | Akkar                  |



| School No. | School Name                                                            | CERD No. | Governorate / District |
|------------|------------------------------------------------------------------------|----------|------------------------|
| 41         | Mrahat Akkar Mixed Public School<br>مدرسة مراحات عكار الرسمية المختلطة | 617      | Akkar                  |

|                  |            |            |
|------------------|------------|------------|
| School Location: | X          | Y          |
|                  | 34.5473279 | 36.2419859 |

|                     |                |        |                    |   |
|---------------------|----------------|--------|--------------------|---|
| School Information: | Owned          | Rented | No. of Blocks:     | 1 |
|                     | ✓ (Gift)       |        |                    |   |
|                     | No. of Floors: | 1      | No. of Classrooms: | 7 |

|                            |              |             |           |
|----------------------------|--------------|-------------|-----------|
| Director Name and Contact: | Mahmoud Kanj | - Landline: | 06-886494 |
|                            |              | - Mobile:   | 03-224986 |

Building Condition: Category **1**

|                                        |     |    |          |           |           |
|----------------------------------------|-----|----|----------|-----------|-----------|
| Roof Heat Insulation:                  | Yes | No | Comments | Condition |           |
|                                        |     | ✓  |          | Good      | To Repair |
| Roof Waterproofing:                    | Yes | No | Comments | Condition |           |
|                                        |     | ✓  |          | Good      | To Repair |
| Presence of Parapet at Roof Floor:     | Yes | No | Comments | Condition |           |
|                                        |     | ✓  |          | Good      | To Repair |
| Presence of Handicap Ramp at GF level: | Yes | No | Comments | Condition |           |
|                                        | ✓   |    |          | Good      | To Repair |
| Presence of Handicap Toilet:           | Yes | No | Comments | Condition |           |
|                                        | ✓   |    |          | Good      | To Repair |
| Playground:                            | Yes | No | Comments | Condition |           |
|                                        | ✓   |    |          | Good      | To Repair |

|                                     |     |    |             |           |           |
|-------------------------------------|-----|----|-------------|-----------|-----------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    | Type: Resin | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>External Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Internal Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Shed:</b>                        | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    | T.O.T       | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Rain Water System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             |           | ✓         |
| <b>Electrical System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments    | Condition |           |
|                                     |     | ✓  |             | Good      | To Repair |
|                                     |     |    |             |           |           |
| <b>Source of Electricity:</b>       | EDL |    | Generator   | Condition |           |
|                                     | No  |    | ✓           | Good      | To Repair |
|                                     |     |    |             | ✓         |           |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                                            | CERD No. | Governorate / District |
|------------|------------------------------------------------------------------------|----------|------------------------|
| 41         | Mrahat Akkar Mixed Public School<br>مدرسة مراحات عكار الرسمية المختلطة | 617      | Akkar                  |



| School No. | School Name                                                            | CERD No. | Governorate / District |
|------------|------------------------------------------------------------------------|----------|------------------------|
| 41         | Mrahat Akkar Mixed Public School<br>مدرسة مراحات عكار الرسمية المختلطة | 617      | Akkar                  |



| School No. | School Name                               | CERD No. | Governorate / District |
|------------|-------------------------------------------|----------|------------------------|
| 60         | Ayat Public School<br>متوسطة عيات الرسمية | 1489     | Akkar                  |

|                  |            |            |
|------------------|------------|------------|
| School Location: | X          | Y          |
|                  | 34.5356236 | 36.1997867 |

|                     |                |        |                    |   |
|---------------------|----------------|--------|--------------------|---|
| School Information: | Owned          | Rented | No. of Blocks:     | 1 |
|                     |                | ✓      |                    |   |
|                     | No. of Floors: | 3      | No. of Classrooms: | 9 |

|                            |                      |             |           |
|----------------------------|----------------------|-------------|-----------|
| Director Name and Contact: | Abdo Mostafa Al Zein | - Landline: | 06-361217 |
|                            |                      | - Mobile:   | 70-806643 |

Building Condition: Category **1**

|                       |     |    |          |           |           |
|-----------------------|-----|----|----------|-----------|-----------|
| Roof Heat Insulation: | Yes | No | Comments | Condition |           |
|                       |     | ✓  |          | Good      | To Repair |
|                       |     |    |          |           |           |

|                     |     |    |          |           |           |
|---------------------|-----|----|----------|-----------|-----------|
| Roof Waterproofing: | Yes | No | Comments | Condition |           |
|                     |     | ✓  |          | Good      | To Repair |
|                     |     |    |          |           |           |

|                                    |     |    |          |           |           |
|------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Parapet at Roof Floor: | Yes | No | Comments | Condition |           |
|                                    | ✓   |    |          | Good      | To Repair |
|                                    |     |    |          | ✓         |           |

|                                        |     |    |          |           |           |
|----------------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Ramp at GF level: | Yes | No | Comments | Condition |           |
|                                        |     | ✓  |          | Good      | To Repair |
|                                        |     |    |          |           |           |

|                              |     |    |          |           |           |
|------------------------------|-----|----|----------|-----------|-----------|
| Presence of Handicap Toilet: | Yes | No | Comments | Condition |           |
|                              |     | ✓  |          | Good      | To Repair |
|                              |     |    |          |           |           |

|             |     |    |          |           |           |
|-------------|-----|----|----------|-----------|-----------|
| Playground: | Yes | No | Comments | Condition |           |
|             | ✓   |    | asphalt  | Good      | To Repair |
|             |     |    |          | ✓         |           |

|                                     |     |    |             |           |           |
|-------------------------------------|-----|----|-------------|-----------|-----------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    | Type: Tiles | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>External Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Internal Main Gate:</b>          | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Shed:</b>                        | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    | Asbestos    | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Rain Water System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>Electrical System:</b>           | Yes | No | Comments    | Condition |           |
|                                     | ✓   |    |             | Good      | To Repair |
|                                     |     |    |             | ✓         |           |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments    | Condition |           |
|                                     |     | ✓  |             | Good      | To Repair |
|                                     |     |    |             |           |           |
| <b>Source of Electricity:</b>       | EDL |    | Generator   | Condition |           |
|                                     |     |    | ✓           | Good      | To Repair |
|                                     |     |    |             | ✓         |           |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                               | CERD No. | Governorate / District |
|------------|-------------------------------------------|----------|------------------------|
| 60         | Ayat Public School<br>متوسطة عيات الرسمية | 1489     | Akkar                  |



| School No. | School Name                               | CERD No. | Governorate / District |
|------------|-------------------------------------------|----------|------------------------|
| 60         | Ayat Public School<br>متوسطة عيات الرسمية | 1489     | Akkar                  |



| School No. | School Name                                       | CERD No. | Governorates |
|------------|---------------------------------------------------|----------|--------------|
| 69         | EL Hseinah Public School<br>مدرسة الحصنية الرسمية | 1623     | Akkar        |

**School Location:**

|            |            |
|------------|------------|
| X          | Y          |
| 34.5203868 | 36.0399125 |

**School Information:**

|       |        |                |   |
|-------|--------|----------------|---|
| Owned | Rented | No. of Blocks: | 1 |
| ✓     |        |                |   |

|                |   |                    |    |
|----------------|---|--------------------|----|
| No. of Floors: | 4 | No. of Classrooms: | 25 |
|----------------|---|--------------------|----|

**Director Name and Contact:**

Haniya Bachir Al Dika

- Landline:

06-826250

- Mobile:

03-343643

**Building Condition: Category 1**

**Roof Heat Insulation:**

| Yes | No | Comments |
|-----|----|----------|
|     | ✓  |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           |           |

**Roof Waterproofing:**

| Yes | No | Comments |
|-----|----|----------|
| ✓   |    |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**Presence of Parapet at Roof Floor:**

| Yes | No | Comments |
|-----|----|----------|
| ✓   |    |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**Presence of Handicap Ramp at GF level:**

| Yes | No | Comments |
|-----|----|----------|
| ✓   |    |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

**Presence of Handicap Toilet:**

| Yes | No | Comments |
|-----|----|----------|
|     | ✓  |          |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
|           |           |

**Playground:**

| Yes | No | Comments      |
|-----|----|---------------|
| ✓   |    | Slab on grade |

| Condition |           |
|-----------|-----------|
| Good      | To Repair |
| ✓         |           |

|                                     |     |    |                 |           |           |
|-------------------------------------|-----|----|-----------------|-----------|-----------|
| <b>Drinking Fountain:</b>           | Yes | No | Comments        | Condition |           |
|                                     | ✓   |    | Type: tiles     | Good      | To Repair |
|                                     |     |    |                 |           | ✓         |
| <b>External Main Gate:</b>          | Yes | No | Comments        | Condition |           |
|                                     | ✓   |    |                 | Good      | To Repair |
|                                     |     |    |                 |           | ✓         |
| <b>Internal Main Gate:</b>          | Yes | No | Comments        | Condition |           |
|                                     | ✓   |    |                 | Good      | To Repair |
|                                     |     |    |                 |           | ✓         |
| <b>Shed:</b>                        | Yes | No | Comments        | Condition |           |
|                                     | ✓   |    |                 | Good      | To Repair |
|                                     |     |    |                 |           | ✓         |
| <b>Rain Water System:</b>           | Yes | No | Comments        | Condition |           |
|                                     | ✓   |    |                 | Good      | To Repair |
|                                     |     |    |                 |           | ✓         |
| <b>Waste Water Drainage System:</b> | Yes | No | Comments        | Condition |           |
|                                     | ✓   |    |                 | Good      | To Repair |
|                                     |     |    |                 |           | ✓         |
| <b>Electrical System:</b>           | Yes | No | Comments        | Condition |           |
|                                     | ✓   |    |                 | Good      | To Repair |
|                                     |     |    |                 |           | ✓         |
| <b>PV Solar Panel at Roof:</b>      | Yes | No | Comments        | Condition |           |
|                                     | ✓   |    |                 | Good      | To Repair |
|                                     |     |    |                 | ✓         |           |
| <b>Source of Electricity:</b>       | EDL |    | Generator       | Condition |           |
|                                     | No  |    | Out of services | Good      | To Repair |
|                                     |     |    |                 |           | ✓         |

**Remarks:**

Based on the visual site assessment, the school is classified as **Category 1**, as the identified needs are limited to minor rehabilitation works that can be addressed without structural intervention and fall within the intended scope of the current assignment.

| School No. | School Name                                       | CERD No. | Governorate / District |
|------------|---------------------------------------------------|----------|------------------------|
| 69         | EL Hseinah Public School<br>مدرسة الحصنية الرسمية | 1623     | Akkar                  |



| School No. | School Name                                       | CERD No. | Governorate / District |
|------------|---------------------------------------------------|----------|------------------------|
| 69         | EL Hseinah Public School<br>مدرسة الحصنية الرسمية | 1623     | Akkar                  |

